

AMENDMENT TABLE FOR PART 28—Continued

Amend:	By removing the reference to:	And adding in its place:
§ 28.320(a) (two times)	ATF	TTB.
§ 28.320(b) (two times)	ATF	TTB.
§ 28.321	ATF	TTB.
§ 28.331	§ 252.40	§ 28.40.
§ 28.331	§ 252.41	§ 28.41.
§ 28.331	§ 252.42	§ 28.42.
§ 28.331 (two times)	ATF	TTB.
§ 28.331	§ 252.65	§ 28.65.
§ 28.332	§ 252.331	§ 28.331.
§ 28.332 (four times)	ATF	TTB.
§ 28.333 (two times)	ATF	TTB.
§ 28.333	§ 252.40	§ 28.40.
§ 28.333	§ 252.41	§ 28.41.
§ 28.333	§ 252.42	§ 28.42.
§ 28.334	ATF	TTB.
§ 28.335	ATF	TTB.

Signed: October 2, 2003.

Arthur J. Libertucci,
Administrator.

Approved: December 24, 2003.

Timothy E. Skud,
Deputy Assistant Secretary, Tax, Trade, and
Tariff Policy.

[FR Doc. 04-1508 Filed 1-26-04; 8:45 am]

BILLING CODE 4810-31-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 117

[CGD05-04-010]

RIN 1625-AA09

Drawbridge Operation Regulations; Southern Branch of the Elizabeth River, Chesapeake, VA

AGENCY: Coast Guard, DHS.

ACTION: Temporary deviation from
regulations.

SUMMARY: The Coast Guard has approved a temporary deviation from the regulations governing the operation of the Jordan Bridge across the Southern Branch of the Elizabeth River, at mile 2.8, in Chesapeake, Virginia. From midnight on January 14, 2004, through midnight on February 14, 2004, this deviation allows the bridge to be untended and maintained in the full open position to vessels while a full assessment of the structural integrity of the bridge is completed. This deviation is necessary to facilitate the needs of navigation caused by an allision with a tug and barge that occurred on January 3, 2004.

DATES: This deviation is effective from midnight on January 14, 2004, through midnight on February 14, 2004.

FOR FURTHER INFORMATION CONTACT: Bill Brazier, Bridge Management Specialist, Fifth Coast Guard District, at (757) 398-6422.

SUPPLEMENTARY INFORMATION: On January 3, 2004, the Jordan Bridge experienced severe damage as a result of an allision with a tug and barge. This 75-year old vertical-lift drawbridge, which spans the Southern Branch of the Elizabeth River, was struck nearly dead center causing significant damage to the bridge. The Jordan Bridge, which connects the cities of Chesapeake and Portsmouth, is owned and operated by the City of Chesapeake.

The structural impact of the mishap essentially knocked the bridge, which rises vertically between two towers, off its track locking the span approximately 80 feet in the air. Subsequently, waterway passage maintained a 75-foot vertical height restriction and efforts to realign the bridge span were completed on January 12, 2004. On January 13, 2004, the damaged bridge was raised to the full open position to 145 feet, at mean high water, and the Captain of the Port of Hampton Roads lifted all waterway restrictions on the Jordan Bridge allowing all vessel traffic to transit. Until a full assessment of the damages to Jordan Bridge is completed, the bridge will be maintained in the full open position to vessels and untended, except for two days, from midnight on January 14, 2004, through midnight on February 14, 2004. On January 22 and 23, 2004, the bridge will be lowered for repair inspections. During these two days the bridge will be tended and will operate as required by the regulations in 33 CFR 117.997(b).

The District Commander has granted temporary deviation from the operating

requirements listed in 33 CFR 117.997(b) to allow all vessel traffic to transit until a full assessment of Jordan Bridge is completed. The temporary deviation allows the Jordan Bridge across the Southern Branch of the Elizabeth River, mile 4.0, to remain in the full open position to vessels from midnight on January 14, 2004, through midnight on February 14, 2004, except for January 22 and 23, 2004.

Dated: January 15, 2004.

Waverly W. Gregory, Jr.,
Chief, Bridge Administration Section, Fifth
Coast Guard District.

[FR Doc. 04-1611 Filed 1-26-04; 8:45 am]

BILLING CODE 4910-15-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 117

[CGD08-03-050]

RIN 1625-AA09

Drawbridge Operating Regulation; Upper Mississippi River, Louisiana, Missouri

AGENCY: Coast Guard, DHS.

ACTION: Notice of temporary deviation
from regulations.

SUMMARY: The Commander, Eighth Coast Guard District has issued a temporary deviation from the regulation governing the operation of the Louisiana Railroad Drawbridge, across the Upper Mississippi River, mile 282.1, at Louisiana, Missouri. This deviation allows the drawbridge to remain closed to navigation for 46 days from 8 a.m., January 15, 2004, until 8 a.m., February 29, 2004, Central Standard Time. The

deviation will facilitate maintenance work on the bridge that is essential to the continued safe operation of the drawbridge.

DATES: This temporary deviation is effective from 8 a.m., January 15, 2004, until 8 a.m., February 29, 2004.

ADDRESSES: Materials referred to in this notice are available for inspection or copying at the office of the Eighth Coast Guard District, Bridge Administration Branch, Commander (obr), Eighth Coast Guard District, 1222 Spruce Street, St. Louis, MO 63103-2832, between 8 a.m. and 4 p.m., Monday through Friday, except Federal holidays. The Bridge Administration Branch maintains the public docket for this temporary deviation.

FOR FURTHER INFORMATION CONTACT:

Roger K. Wiebusch, Bridge Administrator, Commander (obr), Eighth Coast Guard District, 1222 Spruce Street, St. Louis, MO 63103-2832, (314) 539-3900, extension 2378.

SUPPLEMENTARY INFORMATION: The Kansas City Southern Railway Company requested a temporary deviation on December 15, 2003 for the operation of the drawbridge to allow the bridge owner time for preventative maintenance. Presently, the draw opens on signal for passage of river traffic. This deviation allows the bridge to remain closed to navigation for 46 days from 8 a.m., January 15, 2004, until 8 a.m., February 29, 2004, Central Standard Time. Vessels not exceeding the vertical clearance of the drawbridge may pass under the drawbridge during repairs. There are no alternate routes for vessels transiting through mile 282.1, Upper Mississippi River.

The Louisiana Railroad Drawbridge provides a vertical clearance of 15.8 feet above normal pool in the closed to navigation position. Navigation on the waterway consists primarily of commercial tows and recreational watercraft. In order to repair the four large wedge cylinders, the bridge must be kept inoperative and in the closed to navigation position. This deviation has been coordinated with waterway users. No objections were received.

In accordance with 33 CFR 117.35(c), this work will be performed with all due speed in order to return the bridge to normal operation as soon as possible. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: January 20, 2004.

Roger K. Wiebusch,
Bridge Administrator.

[FR Doc. 04-1643 Filed 1-26-04; 8:45 am]

BILLING CODE 4910-15-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 117

[CGD13-04-001]

Drawbridge Operation Regulations; Hoquiam River, Aberdeen, WA

AGENCY: Coast Guard, DHS.

ACTION: Notice of temporary deviation from regulations.

SUMMARY: The Commander, Thirteenth Coast Guard District, has issued a temporary deviation from the regulation governing the operation of the Simpson Avenue Drawbridge at mile 0.5 and the Riverside Avenue Drawbridge at mile 0.9 across the Hoquiam River at Aberdeen, Washington. This deviation allows the bridges to temporarily operate on two-hour notice for all openings for vessels. The deviation is necessary to facilitate seismic retrofit of the structures.

DATES: This deviation is effective from 6 a.m., February 16 through 6 p.m., April 15, 2004.

ADDRESSES: Materials referred to in this document are available for inspection or copying at Commander (oan), Thirteenth Coast Guard District, 915 Second Avenue, Seattle, Washington 98174-1067 between 7:45 a.m. and 4:15 p.m., Monday through Friday, except Federal holidays. The telephone number is (206) 220-7270. The Bridge Section of the Aids to Navigation and Waterways Management Branch maintains the public docket for this temporary deviation.

FOR FURTHER INFORMATION CONTACT: Austin Pratt, Chief, Bridge Section, Aids to Navigation and Waterways Management Branch, (206) 220-7282.

SUPPLEMENTARY INFORMATION: Washington State Department of Transportation (WSDOT) requested this deviation from normal operations to facilitate seismic retrofit. The containment system for contaminants and other equipment must be modified or removed in order to operate the movable spans. Currently, the draws need not open for the passage of vessels unless one hour notice is provided at all times. Vessels on the related reach of the waterway should be able to provide at least two hours notice for openings without unreasonable inconvenience.

In accordance with 33 CFR 117.35(c), this work will be performed with all due speed in order to return the bridge to normal operation as soon as possible. This deviation from the operating

regulations is authorized under 33 CFR 117.35.

Dated: January 20, 2004.

Jeffrey M. Garrett,

Rear Admiral, U.S. Coast Guard, Commander, Thirteenth Coast Guard District.

[FR Doc. 04-1644 Filed 1-26-04; 8:45 am]

BILLING CODE 4910-15-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Parts 148, 149, and 150

[USCG-1998-3884]

RIN 1625-AA20 (formerly RIN 2115-AF63)

Deepwater Ports; Correction

AGENCY: Coast Guard, DHS.

ACTION: Temporary interim rule; correction.

SUMMARY: On January 6, 2004, the Coast Guard published a temporary interim rule with request for comments in the **Federal Register**, which inadvertently contained errors in the table of contents for 33 CFR part 149 and in paragraph designations for 33 CFR 149.415. This document corrects those errors.

DATES: Effective on January 27, 2004.

FOR FURTHER INFORMATION CONTACT: Lieutenant Commander Kevin Tone, Vessel and Facility Operating Standards Division (G-MSO-2), Coast Guard, telephone 202-267-0226.

SUPPLEMENTARY INFORMATION: The Coast Guard published a temporary interim rule with request for comments in the **Federal Register** of January 6, 2004 (69 FR 724; FR Doc. 03-32204). The rule contained inadvertent errors in the table of contents to 33 CFR part 149 and in paragraph designations for 33 CFR 149.415. These errors are nonsubstantive, but we are correcting them to prevent unnecessary confusion.

PART 149—[CORRECTED]

■ In temporary interim rule FR Doc. 03-32204 published on January 6, 2004 (69 FR 724), make the following corrections. On page 761, in the third column, remove the words “149.150 What are the requirements for the receipt of oil residues from vessels?” On page 769, in the second column under § 149.415, redesignate paragraphs (d) and (e) as paragraphs (c) and (d) respectively.