

3. There must be means to allow the crew to check the functioning of each fire detector circuit while in flight.

4. The detection system effectiveness must be shown for all approved operating configurations and conditions.

(c) The flight crew must have means to shut off the ventilating airflow to or within the compartment, from the pilot's station, on an all-cargo configuration.

(d) Passenger and COMBI configurations where the cargo or baggage compartment are not accessible to the flightcrew, must have an approved, built-in fire extinguishing system. The built-in fire extinguishing system shall be controllable from the pilot's station. There must be means to control ventilation and drafts within an inaccessible cargo or baggage compartment so the extinguishing agent can control any fire that may start in the compartment. The built-in fire extinguishing system must be installed so that no extinguishing agent likely to enter the personnel compartments will be hazardous to the occupants. The discharge of the fire extinguishing system must not cause structural damage. The capacity of the extinguishing system must be adequate for any fire likely to occur in the compartment where used. Consideration must be given to the volume of the compartment and the ventilation rate.

(e) In addition to the fire extinguishers required by § 23.851, a hand fire extinguisher must be readily accessible for use in each cargo and baggage compartment that is accessible to crewmembers in flight. Hazardous quantities of smoke, flames or extinguishing agent must not enter any compartment occupied by crew or passengers, when the access to that compartment is used.

(f) Protective breathing equipment must be installed for crewmembers in each crewmember compartment. Protective breathing equipment must:

1. Be designed to protect the flightcrew from smoke, carbon dioxide and other harmful gases at the pilot's station and while combating fires in cargo or baggage compartments.

2. Have masks that cover the eyes, nose and mouth; or masks that cover the nose and mouth plus accessory equipment to cover the eyes.

3. Allow the flightcrew to use the radio equipment and to communicate with each other while at their assigned stations.

4. Not cause any appreciable adverse effect on vision and must allow corrective glasses to be worn.

5. Supply protective oxygen of 15 minutes duration per crewmember at a

pressure altitude of 8,000 feet with a respiratory minute volume of 30 liters per minute BTPD (BTPD refers to body temperature conditions (that is 37 °C at ambient pressure, dry)). If a demand oxygen system is used, a supply of 300 liters of free oxygen at 70 °F. and 760 mm. Hg. pressure is considered to be adequate to meet the 15-minute-duration requirement at the prescribed altitude and minute volume. If a continuous flow protective breathing system is used (including a mask with a standard rebreather bag), a flow rate of 60 liters per minute at 8,000 feet (45 liters per minute at sea level) and a supply of 600 liters of free oxygen at 70 °F and 760 mm. Hg. pressure is considered to be adequate to meet the 15-minute-duration requirement at the prescribed altitude and minute volume.

6. Be free from hazards in itself, in its method of operation, and in its effect upon other components.

7. Have a means to allow the crew to readily determine, during flight, the quantity of oxygen available in each source of supply.

Issued in Kansas City, Missouri on March 28, 2001.

**Michael Gallagher,**

*Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 01-8513 Filed 4-5-01; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Airspace Docket No. 2000-ASW-21]

#### Revocation of Class E Airspace, Gage, OK

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Direct final rule; confirmation of effective date.

**SUMMARY:** This document confirms the effective date of a direct final rule which revokes the Class E Airspace at Gage, OK.

**EFFECTIVE DATE:** The direct final rule published at 66 FR 8364 is effective 0901 UTC, May 17, 2001.

**FOR FURTHER INFORMATION CONTACT:** Donald J. Day, Airspace Branch, Air Traffic Division, Southwest Region, Federal Aviation Administration, Fort Worth, TX 76193-0520, telephone: 817-222-5593.

**SUPPLEMENTARY INFORMATION:** The FAA published this direct final rule with a request for comments in the **Federal**

**Register** on January 31, 2001, (66 FR 8364). The FAA uses the direct final rulemaking procedure for a noncontroversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, were received within the comment period, the regulation would become effective on May 17, 2001. No adverse comments were received, and, thus, this action confirms that this direct final rule will be effective on that date.

Issued in Fort Worth, TX, on March 28, 2001.

**Robert N. Stevens,**

*Acting Manager, Air Traffic Division, Southwest Region.*

[FR Doc. 01-8440 Filed 4-5-01; 8:45 am]

**BILLING CODE 4910-13-M**

## DEPARTMENT OF THE TREASURY

### Internal Revenue Service

#### 26 CFR Part 1

[TD 8881]

RIN 1545-AX53; 1545-AV27; 1545-AV41

#### Revisions to Regulations Relating to Withholding of Tax on Certain U.S. Source Income Paid to Foreign Persons and Revisions of Information Reporting Regulations; Correction

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Correction to final regulations.

**SUMMARY:** This document contains corrections to final regulations (TD 8881) which were published in the **Federal Register** on Monday, May 22, 2000 (65 FR 32152). The final regulations relate to withholding of tax on certain U.S. source income paid to foreign persons and related requirements governing the collection, deposit, refunds, and credits of withheld amounts under sections 1461 through 1463.

**DATES:** This correction is effective January 1, 2001.

**FOR FURTHER INFORMATION CONTACT:** Carl Cooper, Laurie Hatten-Boyd, or Kate Hwa (202) 622-3840 (not a toll-free number).

#### SUPPLEMENTARY INFORMATION:

##### Background

The final regulations that are subject to these corrections are under section 1441 of the Internal Revenue Code.