

final rule has no federalism implications warranting the preparation of a Federalism Assessment.

For purposes of the Paperwork Reduction Act, 44 U.S.C. Ch. 35, SBA has determined that this rule does not impose new reporting or recordkeeping requirements.

SBA has determined that this final rule may have a significant beneficial economic impact on a substantial number of small entities within the meaning of the Regulatory Flexibility Act (RFA), 5 U.S.C. § 601, *et seq.* This rule involves revising the definition of "principal office" and eliminating certain requirements governing the allowable affiliations of qualified HUBZone SBCs and SBCs that operate as non-manufacturers. The rule will affect a large percentage of the over 30,000 SBCs that SBA believes are now eligible or will become eligible for certification as qualified HUBZone SBCs over the life of the program.

Pursuant to the requirements of the RFA, SBA prepared an Initial Regulatory Flexibility Analysis (IRFA), fully discussing the economic impact of the amendments on small entities. SBA submitted a copy of the IRFA to the Chief Counsel for Advocacy of the Small Business Administration. No comments were submitted in response to the IRFA. Since this final rule implements the amendments without significant substantive change, this final rule does not change the nature of the economic impact of the amendments on small entities, nor alter the basis of SBA's IRFA. Accordingly, this Final Regulatory Flexibility Analysis incorporates by reference the entire IRFA. A copy of the Final Regulatory Flexibility Analysis and IRFA may be obtained by contacting the Chief Counsel for Advocacy of the Small Business Administration, (202) 205-6533.

The amendments that are the subject of this rule will affect primarily those SBCs that participate in Federal procurements, that have affiliates, or that are non-manufacturers. The amendments will make it easier for qualified SBCs to participate in the program because it provides a definition of "principal office" that accommodates the fluid nature of the construction and service industries and it allows qualified HUBZone SBCs to have any affiliates provided that they, together with their affiliates, do not exceed their applicable size standard under part 121 of title 13 of the Code of Federal Regulations. This final rule also will facilitate the certification of qualified HUBZone SBCs and open the door to more HUBZone contracts by eliminating

the eligibility requirement that non-manufacturers must demonstrate that they can supply the goods of a qualified SBC as a prerequisite for program certification, and by exempting non-manufacturers from making that showing when submitting offers to supply goods for HUBZone contracts with a total value of \$25,000 or less.

In addition, this final rule does not duplicate, overlap or conflict with relevant Federal regulations. SBA reviewed several alternatives to the amendments implemented by this rule and believes that the amendments are in the best interest of SBCs and the HUBZone Program.

(Catalog of Federal Domestic Assistance Programs, No. 59.009)

List of Subjects in 13 CFR Part 126

Administrative practice and procedure, Government procurement, Reporting and recordkeeping requirements, Small businesses.

Accordingly, for the reasons set forth above, SBA amends 13 CFR part 126, as follows:

PART 126—HUBZONE PROGRAM [AMENDED]

1. Revise the authority citation for 13 CFR part 126 to read as follows:

Authority: 15 U.S.C. 632(a); Pub. L. 105-135 sec. 601 *et seq.*, 111 Stat. 2592.

2. Amend § 126.101 by adding a new paragraph (c) to read as follows:

§ 126.101 Which government departments or agencies are affected directly by the HUBZone program?

* * * * *

(c) The HUBZone program does not apply to contracts awarded by state and local governments. However, state and local governments may use the List of qualified HUBZone SBCs to identify qualified HUBZone SBCs for similar programs authorized under state or local law.

3. Amend § 126.103 to revise the definition of "principal office" to read as follows:

§ 126.103 What definitions are important in the HUBZone program?

* * * * *

Principal office means the location where the greatest number of the concern's employees at any one location perform their work. However, for those concerns whose "primary industry" (see 13 CFR 121.107) is service or construction (see 13 CFR 121.201), the determination of principal office excludes the concern's employees who perform the majority of their work at

job-site locations to fulfill specific contract obligations.

* * * * *

4. Revise § 126.204 to read as follows:

§ 126.204 May a qualified HUBZone SBC have affiliates?

A concern may have affiliates provided that the aggregate size of the concern and all its affiliates is small as defined in part 121 of this title.

5. Revise § 126.206 to read as follows:

§ 126.206 May non-manufacturers be certified as qualified HUBZone SBCs?

Non-manufacturers (referred to in the HUBZone Act of 1997 as "regular dealers") may be certified as qualified HUBZone SBCs if they meet all of the requirements set forth in § 126.200. For purposes of this part, a "non-manufacturer" is defined in § 121.406(b)(1)(i) and (ii) of this title.

6. Amend § 126.601 by revising paragraph (d) to read as follows:

§ 126.601 What additional requirements must a qualified HUBZone SBC meet to bid on a contract?

* * * * *

(d) A qualified HUBZone SBC which is a non-manufacturer may submit an offer on a HUBZone contract for supplies if it meets the requirements of the non-manufacturer rule set forth at § 121.406(b)(1)(i) and (ii) of this title, and if the small manufacturer providing the end item for the contract is also a qualified HUBZone SBC. However, for HUBZone contracts at or below \$25,000 in total value, a qualified HUBZone SBC may supply the end item of any manufacturer, including a large business.

Dated: January 10, 2001.

Aida Alvarez,
Administrator.

[FR Doc. 01-1543 Filed 1-17-01; 8:45 am]

BILLING CODE 8025-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-CE-57-AD; Amendment 39-12073; AD 2001-01-03]

RIN 2120-AA64

Airworthiness Directives; British Aerospace HP137 Mk1, Jetstream Series 200, and Jetstream Models 3101 and 3201 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to all British Aerospace HP137 Mk1, Jetstream series 200, and Jetstream Models 3101 and 3201 airplanes. This AD requires you to remove the nose landing gear steering actuator and install one that incorporates a modified piston rod. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the United Kingdom. The actions specified by this AD are intended to prevent failure of the nose landing gear steering actuator because of problems with the current design piston rod. Continued operation with the current design piston rod could result in loss of nose wheel steering and possible loss of control of the airplane during takeoff, landing, and taxi operations.

DATES: This AD becomes effective on February 24, 2001.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of February 24, 2001.

ADDRESSES: You may get the service information referenced in this AD from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone: (01292) 479888; facsimile: (01292) 479703. You may examine this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-CE-57-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

What events have caused this AD? The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, recently notified FAA that an unsafe condition may exist on all British Aerospace HP137 Mk1, Jetstream series 200, and Jetstream Models 3101 and 3201 airplanes. The CAA reports three occurrences of nose landing gear failure in the area of the undercut on the base of the eye and thread on the steering actuator. The CAA reports cracks in this area on 10 additional nose landing gear units.

Investigation of these occurrences reveals incorrect installation or insufficient lubrication at the steering actuator trunnions. This then causes bending loads in the steering actuator piston rod during operation.

What are the consequences if the condition is not corrected? Cracks in or failure of the steering actuator piston rod could result in loss of nose wheel steering and possible loss of control of the airplane during takeoff, landing, and taxi operations.

Has FAA taken any action to this point? We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all British Aerospace HP137 Mk1, Jetstream series 200, and Jetstream Models 3101 and 3201 airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on October 24, 2000 (65 FR 63551). The NPRM proposed to require you to remove the nose landing gear steering actuator and install one that incorporates a modified piston rod.

Was the public invited to comment? Interested persons were afforded an opportunity to participate in the making of this amendment. We have given due consideration to the comments received.

Comment Disposition

What is the Commenters' Concern? Several commenters express concern over the compliance time that FAA

established. In particular, the comments are:

- 200 hours time-in-service (TIS) is unrealistic for the installation because parts would not be available and many of the affected aircraft would be unjustly grounded; and
- since CAA and British Aerospace recommend 3,000 landings since May 5, 2000, FAA should adopt a similar compliance time.

What is FAA's Response to the Concern? After consulting with British Aerospace and CAA, we concur that 200 hours TIS would unjustly ground many of the affected aircraft. We are changing the compliance time of the installation in this final rule as follows:

“Within the next 3,000 landings after May 5, 2000 (the issue date of the applicable service information) or within the next 90 days after the effective date of this AD, whichever occurs later.”

The FAA's Determination

What is FAA's Final Determination on this Issue? After careful review of all available information related to the subject presented above, we have determined that air safety and the public interest require the adoption of the rule as proposed except for the compliance time change and minor editorial corrections. We determined that this compliance time change and the minor corrections:

- Will not change the meaning of the AD; and
- Will not add any additional burden upon the public than was already proposed.

Cost Impact

How many airplanes does this AD impact? We estimate that this AD affects 264 airplanes in the U.S. registry.

What is the cost impact of this AD on owners/operators of the affected airplanes? We estimate the following costs to accomplish the modification:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. airplane operators
2 workhours × \$60 per hour=\$120	\$1,520 per airplane	\$1,640 per airplane	\$432,960

Regulatory Impact

Does this AD impact various entities? The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

Does this AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this

action (1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by Reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration

amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends § 39.13 by adding a new AD to read as follows:

2001-01-03 British Aerospace:

Amendment 39-12073; Docket No. 2000-CE-57-AD.

(a) *What airplanes are affected by this AD?* This AD affects Models HP137 Mk1,

Jetstream Series 200, and Jetstream Models 3101 and 3201 airplanes, all serial numbers, certificated in any category.

(b) *Who must comply with this AD?*

Anyone who wishes to operate any of the above airplanes must comply with this AD.

(c) *What problem does this AD address?*

The actions specified by this AD are intended to prevent failure of the nose landing gear steering actuator because of problems with the current design piston rod. Continued operation with the current design piston rod could result in loss of nose wheel steering and possible loss of control of the airplane during takeoff, landing, and taxi operations.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Action	Compliance time	Procedures
(1) Remove the nose landing gear steering actuator and install one that incorporates a modified piston rod.	Within the next 3,000 landings after May 5, 2000 (the issue date of the applicable service bulletin) or within the next 90 days after February 17, 2001 (the effective date of this AD), whichever occurs later, unless already accomplished. If the number of landings is unknown, you may use hours time-in-service (TIS) by multiplying the number of hours TIS by 0.75. In this case, 3,000 landings would be equal to 4,000 hours TIS (4,000 hours TIS \times 0.75 = 3,000 landings).	In accordance with the procedures in APPH Ltd. Service Bulletin 32-73, dated April 2000, as referenced in British Aerospace Jetstream Mandatory Service Bulletin 32-JA000342, Issued: May 5, 2000.
(2) You may not install, on any affected airplane, a nose landing gear unit that does not incorporate a modified steering actuator piston rod, as required by paragraph (d)(1) of this AD.	As of February 17, 2001 (the effective date of this AD).	Not Applicable.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

- (1) Your alternative method of compliance provides an equivalent level of safety; and
- (2) The Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 1: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Mr. Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with APPH Ltd. Service Bulletin 32-73, dated April 2000, as referenced in British Aerospace Jetstream Mandatory Service Bulletin 32-JA000342, Issued: May 5, 2000. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland. You can look at copies at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(i) *When does this amendment become effective?* This amendment becomes effective on February 24, 2001.

Note 2: The subject of this AD is addressed in British AD 004-05-2000.

Issued in Kansas City, Missouri, on January 4, 2001.

Michael Gallagher,
Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-901 Filed 1-17-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-141-AD; Amendment 39-12078; AD 2001-01-08]

RIN 2120-AA64

Airworthiness Directives; BAE Systems (Operations) Limited (Jetstream) Model 4101 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to all BAE Systems (Operations) Limited (Jetstream) Model 4101 airplanes, that requires inspection