

Rules and Regulations

Federal Register

Vol. 88, No. 212

Friday, November 3, 2023

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–2142; Project Identifier MCAI–2023–01056–T; Amendment 39–22592; AD 2023–22–08]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2023–04–12, which applied to all Airbus SAS Model A350–941 and –1041 airplanes. AD 2023–04–12 required repetitive detailed inspections of affected cargo sealing tapes and applicable corrective actions. Since the FAA issued AD 2023–04–12, additional locations have been identified that are subject to the unsafe condition. This AD retains the requirements of AD 2023–04–12 and expands the inspection area, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 20, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 20, 2023.

The FAA must receive comments on this AD by December 18, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- **Fax:** 202–493–2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–2142; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA material incorporated by reference in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–2142.

FOR FURTHER INFORMATION CONTACT: Dat Le, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7317; email Dat.V.Le@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2023–2142; Project Identifier MCAI–2023–01056–T” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Dat Le, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7317; email Dat.V.Le@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2023–04–12, Amendment 39–22359 (88 FR 12143, February 27, 2023) (AD 2023–04–12), for all Airbus SAS Model A350–941 and –1041 airplanes. AD 2023–04–12 was prompted by an MCAI originated by EASA, which is the Technical Agent for the Member States of the European Union. EASA issued AD 2023–0011, dated January 17, 2023 (EASA AD 2023–0011), to correct an unsafe condition.

EASA AD 2023–0011 stated that longitudinal sealing tape in the forward and aft cargo compartments had migrated from its original position, possibly due to relative movement between the cargo floor panels and the cargo loading system, combined with compression of the tape.

AD 2023–04–12 required repetitive detailed inspection of the affected parts (*i.e.*, cargo sealing tapes installed between the cargo floor panels and the cargo loading system in longitudinal direction, in the forward and aft cargo compartment area), and, depending on findings, accomplishment of applicable corrective action. The FAA issued AD 2023–04–12 to address migration of the tape, which can affect the tightness of the cargo compartment floor panels that provide an enclosed area to maintain halon concentration in the event of a fire. This condition, if not addressed, could affect the fire extinguishing system efficiency in the cargo compartments, possibly resulting in failure of the system to contain a cargo compartment fire or permanently extinguish a fire.

Actions Since AD 2023–04–12 Was Issued

Since the FAA issued AD 2023–04–12, EASA issued AD 2023–0011R1, dated February 23, 2023 (EASA AD 2023–0011R1) to provide dispatch instructions under the Master Minimum Equipment List. EASA subsequently superseded EASA AD 2023–0011R1 and issued EASA AD 2023–0176, dated October 6, 2023 (EASA AD 2023–0176) (also referred to as the MCAI), to correct an unsafe condition for all Airbus SAS Model A350–941 and –1041 airplanes. The MCAI states that additional parts (cargo sealing tapes installed between the cargo floor panels and the floor structure in transversal direction in the bulk cargo compartment area at frame 82) have been identified as affected by the same potential unsafe condition.

The FAA is issuing this AD to address the unsafe condition on these products. You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–2142.

Explanation of Retained Requirements

Although this AD does not explicitly restate the requirements of AD 2023–04–12, this AD retains all of the requirements of AD 2023–04–12. Those requirements are referenced in EASA AD 2023–0176, which, in turn, is referenced in paragraph (g) of this AD.

Related Service Information Under 1 CFR Part 51

EASA AD 2023–0176 specifies procedures for the following actions:

- Repetitive detailed inspections to detect complete or partial migration of the cargo sealing tapes (including high speed tape and glass cloth tape) and existing repairs of affected parts (*i.e.*, cargo sealing tapes installed between the cargo floor panels and the cargo

loading system in longitudinal direction, in the forward and aft cargo compartment area; and cargo sealing tapes installed between the cargo floor panels and the floor structure in transversal direction, in the bulk cargo compartment area at frame 82).

- Measurement of the maximum migration of partially migrated tape.
- Inspection for incorrect seating or sealant of repaired tape.
- Repair of discrepancies, including cargo sealing tape that has migrated more than 11 millimeters, complete migration of the tape, incorrect seating/condition of the tape in repaired areas, and incorrect sealant condition in repaired areas.

EASA AD 2023–0176 allows deferral of corrective actions through dispatch of the airplane under specified Airbus A350 Master Minimum Equipment List items.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this AD after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Requirements of This AD

This AD requires accomplishing the actions specified in EASA AD 2023–0176 described previously, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, EASA AD 2023–0176 is incorporated by reference in this AD. This AD requires compliance with EASA AD 2023–0176 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using

common terms that are the same as the heading of a particular section in EASA AD 2023–0176 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2023–0176. Service information required by EASA AD 2023–0176 for compliance will be available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–2142 after this AD is published.

Interim Action

The FAA considers that this AD is an interim action. If final action is later identified, the FAA might consider further rulemaking then.

FAA’s Justification and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies forgoing notice and comment prior to adoption of this rule because migration of the sealing tape can affect the tightness of the cargo compartment floor panels, which provide an enclosed area to maintain halon concentration in the event of a fire. Migration of the sealing tape in the forward and aft cargo compartments could affect the fire extinguishing system efficiency in the cargo compartments and possibly result in failure of the system to contain a cargo compartment fire or permanently extinguish the fire. The additional affected locations in the bulk cargo compartment further increase the effect on the fire extinguishing system efficiency by widening the area in which a halon concentration could perpetuate due to migration of the sealing tape and increasing the likelihood of a failure to contain a cargo

compartment fire or permanently extinguish the fire. Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b)(3)(B).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in

less than 30 days, for the same reasons the FAA found good cause to forgo notice and comment.

Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it

has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 32 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Retained actions from AD 2023-04-12	Up to 1 work-hour × \$85 per hour = \$85	\$0	Up to \$85	Up to \$2,720.
New actions	2 work-hours × \$85 per hour = \$170	0	\$170	\$5,440.

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on

the results of any required actions. The FAA has no way of determining the

number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
Up to 3 work-hours × \$85 per hour = \$255	Up to \$10	Up to \$265.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
 - a. Removing Airworthiness Directive (AD) 2023–04–12, Amendment 39–22359 (88 FR 12143, February 27, 2023); and
 - b. Adding the following new AD:

2023–22–08 Airbus SAS: Amendment 39–22592; Docket No. FAA–2023–2142; Project Identifier MCAI–2023–01056–T.

(a) Effective Date

This airworthiness directive (AD) is effective November 20, 2023.

(b) Affected ADs

This AD replaces AD 2023–04–12, Amendment 39–22359 (88 FR 12143, February 27, 2023) (AD 2023–04–12).

(c) Applicability

This AD applies to all Airbus SAS Model A350–941 and –1041 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by the migration of cargo sealing tape from its original position between the cargo floor panels and the cargo loading system in the longitudinal direction in the forward and aft cargo compartment area, and between the cargo floor panels and the floor structure in the transversal direction in the bulk cargo compartment area at frame 82. The FAA is issuing this AD to address this tape migration, which can affect the tightness of the cargo compartment floor panels that provide an enclosed area to maintain halon concentration in the event of a fire. This condition, if not addressed, could affect the fire extinguishing system efficiency in the cargo compartments, possibly resulting in failure of the system to contain a cargo compartment fire or permanently extinguish a fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2023–0176, dated October 6, 2023 (EASA AD 2023–0176).

(h) Exceptions to EASA AD 2023–0176

(1) Where EASA AD 2023–0176 refers to “31 January 2023 [the effective date of EASA AD 2023–0011],” this AD requires replacing those words with “March 14, 2023 (the effective date of AD 2023–04–12).”

(2) Where EASA AD 2023–0176 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where paragraph (2) of EASA AD 2023–0176 specifies accomplishing corrective actions if “discrepancies, as identified in the AOT” are found, for this AD, discrepancies are defined as cargo sealing tape that has migrated more than 11 millimeters, complete migration of the tape as shown in Condition B of the service information reference in EASA AD 2023–0176, incorrect seating/condition of the tape in repaired areas, and incorrect sealant condition in repaired areas.

(4) Where paragraph (2) of EASA AD 2023–0176 specifies accomplishing corrective actions “in accordance with the instructions of the AOT,” for this AD, replace those words with “in accordance with the instructions of the AOT for the FWD and AFT cargo compartment areas and in accordance with the instructions of Airbus AOT A53P016–22, Revision 03, dated September 13, 2023, or later approved revisions for the BULK cargo compartment areas.”

(5) Where the service information referenced in EASA AD 2023–0176 specifies use of cargo sealing tape 398FR, this AD also allows use of cargo sealing tape 398FRP.

(6) This AD does not adopt the “Remarks” section of EASA AD 2023–0176.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(ii) AMOCs approved previously for AD 2023–04–12 are approved as AMOCs for the corresponding provisions of EASA AD 2023–0176 that are required by paragraph (g) of this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation

Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (i)(2) of this AD, if any service information referenced in EASA AD 2023–0176 that contains paragraphs that are labeled as RC, the instructions in RC paragraphs, including subparagraphs under an RC paragraph, must be done to comply with this AD; any paragraphs, including subparagraphs under those paragraphs, that are not identified as RC are recommended. The instructions in paragraphs, including subparagraphs under those paragraphs, not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the instructions identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to instructions identified as RC require approval of an AMOC.

(j) Additional Information

For more information about this AD, contact Dat Le, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7317; email Dat.V.Le@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2023–0176, dated October 6, 2023.

(ii) [Reserved]

(3) For EASA AD 2023–0176, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket at regulations.gov under Docket No. FAA–2023–2142.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–24405 Filed 11–1–23; 11:15 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA–2023–1339; Airspace Docket No. 22–ANM–84]

RIN 2120–AA66

Establishment of Class E Airspace; Grand Coulee Dam Airport, Electric City, WA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class E airspace extending upward from 700 feet above the surface at Grand Coulee Dam Airport, Electric City, WA, in support of the airport’s transition from visual flight rules (VFR) to instrument flight rules (IFR) operations.

DATES: Effective date 0901 UTC, May 16, 2024. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: A copy of the Notice of Proposed Rulemaking (NPRM), all comments received, this final rule, and all background material may be viewed online at www.regulations.gov using the FAA Docket number. Electronic retrieval help and guidelines are available on the website. It is available 24 hours each day, 365 days each year.

FAA Order JO 7400.11H, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at www.faa.gov/air_traffic/publications/. You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington DC 20591; telephone: (202) 267–8783.

FOR FURTHER INFORMATION CONTACT:

Jeffrey Drasin, Federal Aviation Administration, Western Service Center, Operations Support Group, 2200 S. 216th Street, Des Moines, WA 98198; telephone (206) 231–2248.

SUPPLEMENTARY INFORMATION:**Authority for This Rulemaking**

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority. This rulemaking is promulgated under the authority