

address in the **FOR FURTHER INFORMATION CONTACT** section.

The Office of the U.S. Trade Representative has reviewed this rule and concurs with its issuance.

After consideration of all relevant material presented, including the Committee's recommendation, and other information, it is found that finalizing the interim final rule, without change, as published in the **Federal Register** (68 FR 43614, July 24, 2003) will tend to effectuate the declared policy of the Act.

List of Subjects

7 CFR Part 993

Marketing agreements, Plums, Prunes, Reporting and recordkeeping requirements.

7 CFR Part 999

Dates, Filberts, Food grades and standards, Imports, Nuts, Prunes, Raisins, Reporting and recordkeeping requirements, Walnuts.

PART 993—DRIED PRUNES PRODUCED IN CALIFORNIA

PART 999—SPECIALTY CROPS: IMPORT REGULATIONS

Accordingly, the interim final rule amending 7 CFR parts 993 and 999 which was published at 68 FR 43614 on July 24, 2003, is adopted as a final rule without change.

Dated: October 17, 2003.

A.J. Yates,

Administrator, Agricultural Marketing Service.

[FR Doc. 03-26712 Filed 10-22-03; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-164-AD; Amendment 39-13308; AD 2003-19-05]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-10-10, -10F, -15, -30, -30F (KC-10A and KDC-10), -40, and -40F Airplanes; and Model MD-10-10F and -30F Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document corrects an error that appeared in airworthiness directive (AD) 2003-19-05 that was

published in the **Federal Register** on September 22, 2003 (68 FR 54992). The error resulted in an incorrect Type Certificate holder name. This AD is applicable to certain McDonnell Douglas Model DC-10-10, -10F, -15, -30, -30F (KC-10A and KDC-10), -40, and -40F airplanes; and certain Model MD-10-10F and -30F airplanes. This AD requires inspections for cracking and corrosion of the bolt assemblies and bushings on the hinge fittings of the inboard and outboard flaps of the left and right wings, and follow-on and corrective actions.

DATES: Effective October 27, 2003.

FOR FURTHER INFORMATION CONTACT: Ron Atmur, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5224; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Airworthiness Directive (AD) 2003-19-05, amendment 39-13308, applicable to certain McDonnell Douglas Model DC-10-10, -10F, -15, -30, -30F (KC-10A and KDC-10), -40, and -40F airplanes; and certain Model MD-10-10F and -30F airplanes; was published in the **Federal Register** on September 22, 2003 (68 FR 54992). That AD requires inspections for cracking and corrosion of the bolt assemblies and bushings on the hinge fittings of the inboard and outboard flaps of the left and right wings, and follow-on and corrective actions.

As published, the Type Certificate (TC) holder name appears as "BOEING" in the regulatory text of the AD. The correct TC holder name is McDonnell Douglas, which is correctly referenced throughout the preamble of the the AD.

Since no other part of the regulatory information has been changed, the final rule is not being republished in the **Federal Register**.

The effective date of this AD remains October 27, 2003.

§ 39.13 [Corrected]

On page 54993, in the second column, paragraph 2. of Part 39—Airworthiness Directives of AD 2003-19-05 is corrected to read as follows:

* * * * *

2. Section 39.13 is amended by adding the following new airworthiness directive:

2003-19-05 McDonnell Douglas:
Amendment 39-13308. Docket 2002-NM-164-AD.

* * * * *

Issued in Renton, Washington, on October 17, 2003.

Neil D. Schalekamp,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-26721 Filed 10-22-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-229-AD; Amendment 39-13347; AD 98-16-17 R1]

RIN 2120-AA64

Airworthiness Directives; Cessna Model 750 Citation X Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; rescission.

SUMMARY: This amendment rescinds Airworthiness Directive (AD) 98-16-17 R1, which is applicable to all Cessna Model 750 Citation X series airplanes. That AD requires repetitive in-flight functional tests to verify proper operation of the secondary horizontal stabilizer pitch trim system, and repair if necessary. The requirements of that AD were intended to detect and correct contamination and damage in the system actuator, which could result in simultaneous failure of both primary and secondary pitch trim systems, and consequent reduced controllability of the airplane. Since the issuance of that AD, an improved part has been developed, which, if installed, would terminate the repetitive tests; that improved part has been installed on all affected airplanes or is being installed in production. Therefore, the identified unsafe condition no longer exists.

EFFECTIVE DATE: October 23, 2003.

FOR FURTHER INFORMATION CONTACT: Joel M. Ligon, Aerospace Engineer, Systems and Propulsion Branch, ACE-116W, FAA, Small Airplane Directorate, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4138; fax (316) 946-4407.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all Cessna Model 750 Citation X series airplanes was published in the **Federal Register** on January 7, 2000 (65 FR 1075). That action proposed to rescind AD 98-16-17, amendment 39-10693 (63 FR 42206,

August 13, 1999), which currently requires repetitive in-flight functional tests of the secondary horizontal stabilizer pitch trim system, and repair if necessary.

Comments

We provided the public the opportunity to participate in the development of this AD. We received no comments on the proposed rescission.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require rescinding the AD as proposed.

FAA's Determination

Since AD 98–16–17 was issued, an improved part has been developed. Installation of that part terminates the repetitive tests required by the existing AD. The FAA has been advised that the improved part has been installed on all affected airplanes or will be installed in production. The FAA has determined that the previous part number is no longer available or allowed to be installed. Therefore, the identified unsafe condition no longer exists, and we have determined that it is necessary to rescind AD 98–16–17 to prevent operators from performing unnecessary actions.

The Rescission

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. Section 39.13 is amended by adding an AD which removes amendment 39–10693, to read as follows:

98–16–17 R1 Cessna Aircraft Company:
Amendment 39–13347. Docket No. 99–NM–229–AD. Rescinds AD 98–16–17, Amendment 39–10693.

Applicability: All Model 750 Citation X series airplanes, certificated in any category.
This rescission is effective October 23, 2003.

Issued in Renton, Washington, on October 17, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03–26723 Filed 10–22–03; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[TD 9078]

RIN 1545–AY76

Qualified Subchapter S Trust Election for Testamentary Trust; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Correction to final regulations.

SUMMARY: This document contains a correction to final regulations that were published in the **Federal Register** on July 17, 2003 (68 FR 42251) relating to a qualified subchapter S trust election for testamentary trust.

EFFECTIVE DATE: This correction is effective July 17, 2003.

FOR FURTHER INFORMATION CONTACT: Deane M. Burke (202) 622–3070 (not a toll free number).

SUPPLEMENTARY INFORMATION:

Background

The final regulations that are the subject of this correction are under section 1361 of the Internal Revenue Code.

Need for Correction

As published, the final regulations (TD 9078), contain an error that may prove to be misleading and is in need of clarification.

Correction of Publication

■ Accordingly, the publication of the final regulations (TD 9078), which were the subject of FR Doc. 03–18040, is corrected as follows:

■ On page 42251, column 3, in the preamble under the paragraph heading “**Summary of Comments and Explanation of Provisions**”, third paragraph, line 6, the language “revocable trust (QRT) for which an” is

corrected to read “revocable trust for which an”.

Cynthia E. Grigsby,

Acting Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel (Procedure and Administration).

[FR Doc. 03–26802 Filed 10–22–03; 8:45 am]

BILLING CODE 4830–01–P

DEPARTMENT OF THE TREASURY

Office of Foreign Assets Control

31 CFR Part 575

Exclusion of Certain Transactions With Respect to Certain Iraqi Property From the Scope of a General License

AGENCY: Office of Foreign Assets Control, Treasury.

ACTION: Policy statement.

SUMMARY: The Treasury Department's Office of Foreign Assets Control (“OFAC”) has excluded certain transactions from the scope of the general license found in 31 CFR 575.533(a). This exclusion prohibits any attachment, judgment, decree, lien, execution, garnishment, or other judicial process with respect to certain property consisting of historic and modern books, documents, parchment scrolls, and other items pertaining to the Iraqi Jewish community that have been brought to the United States for restoration and temporary exhibition.

DATES: Effective August 28, 2003.

FOR FURTHER INFORMATION CONTACT: Office of Foreign Assets Control, Department of the Treasury, Washington, DC 20220, tel.: 202/622–2500.

SUPPLEMENTARY INFORMATION: On August 2, 1990, the President issued Executive Order 12722, declaring a national emergency with respect to Iraq. This order was issued under the authority of, inter alia, the International Emergency Economic Powers Act (50 U.S.C. 1701 *et seq.*) (“IEEPA”), the National Emergencies Act (50 U.S.C. 1601 *et seq.*), and section 301 of title 3 of the U.S. Code and imposed economic sanctions, including a complete trade embargo, with respect to Iraq. In keeping with United Nations Security Council Resolution 661 of August 6, 1990, and under the United Nations Participation Act (22 U.S.C. 287c), the President also issued Executive Order 12724 of August 9, 1990, which imposed additional restrictions. The Iraqi Sanctions Regulations, 31 CFR part 575 (the “Regulations”), implement