

# Rules and Regulations

Federal Register

Vol. 70, No. 67

Friday, April 8, 2005

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2005-20514; Directorate Identifier 2005-CE-08-AD; Amendment 39-14025; AD 2005-07-01]

RIN 2120-AA64

#### Airworthiness Directives; the Cessna Aircraft Company Models 208 and 208B Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This document makes a correction to Airworthiness Directive (AD) 2005-07-01, which was published in the **Federal Register** on March 25, 2005 (70 FR 15223), and applies to all the Cessna Aircraft Company (Cessna) Models 208 and 208B airplanes. We incorrectly referenced the affected airplane models as C208 and C208B throughout the document. The correct airplane models are 208 and 208B. This action corrects the regulatory text.

**DATES:** The effective date of this AD remains March 29, 2005.

**FOR FURTHER INFORMATION CONTACT:** Paul Pellicano, Aerospace Engineer (Icing), FAA, Small Airplane Directorate, c/o Atlanta Aircraft Certification Office (ACO), One Crown Center, 1985 Phoenix Boulevard, Suite 450, Atlanta, GA 30349; telephone: (770) 703-6064; facsimile: (770) 703-6097.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

On March 21, 2005, FAA issued AD 2005-07-01, Amendment 39-14025 (70 FR 15223, March 25, 2005), which applies to all the Cessna Models 208 and 208B airplanes.

We incorrectly referenced the affected airplane models as C208 and C208B

throughout the document. The correct airplane models are 208 and 208B. This action corrects the regulatory text.

This AD requires you to incorporate information into the applicable section of the Airplane Flight Manual (AFM) to assure that the pilot has enough information to prevent loss of control of the airplane while in-flight during icing conditions.

#### Need for the Correction

This correction is needed to ensure that the affected airplane models numbers are correct and to eliminate misunderstanding in the field.

#### Correction of Publication

■ Accordingly, the publication of March 25, 2005 (70 FR 15223), of Amendment 39-14025; AD 2005-07-01, which was the subject of FR Doc. 05-5915, is corrected as follows:

■ Starting on page 15223 through page 15227, replace all references to Models C208 and C208B airplanes with Models 208 and 208B airplanes.

#### § 39.13 [Corrected]

■ On page 15225, in § 39.13 [Amended], in paragraph (c), replace Models C208 and C208B with Models 208 and 208B.

■ On page 15226, in § 39.13 [Amended], in paragraph (e)(1), replace Model C208 airplanes and Model C208B airplanes with Model 208 airplanes and Model 208B airplanes.

■ On page 15226, in § 39.13 [Amended], in paragraphs (e)(2) and (e)(3), replace Model C208 airplanes with Model 208 airplanes.

■ On page 15226, in § 39.13 [Amended], in paragraphs (e)(4) and (e)(5), replace Model C208B airplanes with Model 208B airplanes.

■ Action is taken herein to correct this reference in AD 2005-07-01 and to add this AD correction to § 39.13 of the Federal Aviation Regulations (14 CFR 39.13).

The effective date remains March 29, 2005.

Issued in Kansas City, Missouri, on April 1, 2005.

**David R. Showers,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05-7052 Filed 4-7-05; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF LABOR

### Occupational Safety and Health Administration

#### 29 CFR Part 1981

RIN 1218-AC12

#### Procedures for the Handling of Discrimination Complaints Under Section 6 of the Pipeline Safety Improvement Act of 2002

**AGENCY:** Occupational Safety and Health Administration, Labor.

**ACTION:** Final rule.

**SUMMARY:** This document provides the final text of regulations governing the employee protection ("whistleblower") provisions of Section 6 of the Pipeline Safety Improvement Act of 2002 ("Pipeline Safety Act"), enacted into law December 17, 2002. This rule establishes procedures and time frames for the handling of discrimination complaints under the Pipeline Safety Act, including procedures and time frames for employee complaints to the Occupational Safety and Health Administration ("OSHA"), investigations by OSHA, appeals of OSHA determinations to an administrative law judge ("ALJ") for a hearing *de novo*, hearings by ALJs, review of ALJ decisions by the Administrative Review Board (acting on behalf of the Secretary) and judicial review of the Secretary's final decision.

**DATES:** This final rule is effective on April 8, 2005.

**FOR FURTHER INFORMATION CONTACT:** Richard E. Fairfax, Director, Directorate of Enforcement Programs, Occupational Safety and Health Administration, U.S. Department of Labor, Room N-3112, 200 Constitution Avenue, NW., Washington, DC 20210; telephone (202) 693-2100.

#### SUPPLEMENTARY INFORMATION:

##### I. Background

The Pipeline Safety Improvement Act of 2002 ("Pipeline Safety Act"), Public Law 107-355, was enacted on December 17, 2002. Section 6 of the Act, codified at 49 U.S.C. 60129, provides protection to employees against retaliation by an employer, defined as a person owning or operating a pipeline facility or a contractor or subcontractor of such a person, because they provided