

Rules and Regulations

Federal Register

Vol. 85, No. 216

Friday, November 6, 2020

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

FARM CREDIT ADMINISTRATION

12 CFR Part 615

RIN 3052-AD35

Organization; Funding and Fiscal Affairs, Loan Policies and Operations, and Funding Operations; Investment Eligibility; Correction

AGENCY: Farm Credit Administration.

ACTION: Final rule; correction.

SUMMARY: The Farm Credit Administration is correcting a final rule published in the **Federal Register**. On October 6, 2020, the Farm Credit Administration (FCA, we, or our) adopted a final rule that amended our investment regulations to allow Farm Credit System (FCS or System) associations to purchase and hold the portion of certain loans that non-FCS lenders originate and sell in the secondary market, and that the United States Department of Agriculture (USDA) unconditionally guarantees or insures as to the timely payment of principal and interest. In that publication, the amendatory instruction to revise paragraph (b)(3) of 12 CFR 615.5140 is incorrect. This document corrects that error.

DATES: November 6, 2020.

FOR FURTHER INFORMATION CONTACT: Richard A. Katz, Senior Counsel, Office of General Counsel, (703) 883-4020, TTY (703) 883-4056, Farm Credit Administration, 1501 Farm Credit Drive, McLean, VA 22102-5090.

SUPPLEMENTARY INFORMATION: In FR Doc. 2020-19711 "Organization; Funding and Fiscal Affairs, Loan Policies and Operations, and Funding Operations; Investment Eligibility" that was published in the **Federal Register** on Tuesday, October 6, 2020 at 85 FR 62945, in the third column on page 62949, correct amendatory instruction 2 to read as follows:

■ 2. Amend § 615.5140 by revising paragraph (b)(2) and paragraph (b)(3) introductory text to read as follows:

Dated: October 16, 2020.

Dale Aultman,

Secretary, Farm Credit Administration Board.

[FR Doc. 2020-23315 Filed 11-5-20; 8:45 am]

BILLING CODE 6705-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-1019; Product Identifier 2018-SW-011-AD; Amendment 39-21264; AD 2020-20-08]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Airbus Helicopters Model AS332C, AS332C1, AS332L, AS332L1, AS332L2, and EC225LP helicopters. This AD requires, depending on helicopter configuration, installing skived polytetrafluoroethylene tape (PTFE tape) or removing PTFE tape and replacing window seals. This AD also prohibits the installation of a jettisonable cabin window unless the applicable requirements are accomplished. This AD was prompted by a report of excessive friction between the window seal and the helicopter airframe. The actions of this AD are intended to address an unsafe condition on these products.

DATES: This AD is effective December 11, 2020.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of December 11, 2020.

ADDRESSES: For service information identified in this final rule, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view this referenced service information at

the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-1019.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-1019; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Union Aviation Safety Agency (EASA) AD, any service information that is incorporated by reference, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Matt Fuller, AD Program Manager, Operational Safety Branch, Airworthiness Products Section, General Aviation and Rotorcraft Unit, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email matthew.fuller@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to Airbus Helicopters Model AS332C, AS332C1, AS332L, AS332L1, AS332L2, and EC225LP helicopters. The NPRM published in the **Federal Register** on January 6, 2020 (85 FR 469). For all of the specified helicopter models without Modification (MOD) 332P087140.00 installed, the NPRM proposed to require installing PTFE tape to each jettisonable cabin window frame. For some of the specified helicopter models with MOD 332P087140.00 installed, the NPRM proposed to require removing the PTFE tape, if installed, from each jettisonable cabin window and replacing each VIP jettisonable cabin window polychloroprene seal with a silicone seal. The NPRM also proposed to prohibit the installation of a jettisonable