your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (n) Additional Information

For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–231–3226; email tom.rodriguez@faa.gov.

### (o) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.
- (3) The following service information was approved for IBR on May 18, 2023.
- (i) European Union Aviation Safety Agency (EASA) AD 2022–0166, dated August 11, 2022.
  - (ii) [Reserved]
- (4) The following service information was approved for IBR on November 7, 2018 (83 FR 49789, October 3, 2018).
- (i) Chapter 5–40, Airworthiness Limitations, DGT 113872, Revision 24, dated July 2017, of the Dassault Falcon 50/50EX Maintenance Manual.
  - (ii) [Reserved]
- (5) For EASA AD 2022–0166, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.
- (6) For Dassault Falcon 50/50EX service information, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201–440–6700; website dassaultfalcon.com.
- (7) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.
- (8) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibrlocations.html.

Issued on March 9, 2023.

#### Christina Underwood.

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–07751 Filed 4–12–23; 8:45 am]

BILLING CODE 4910-13-P

#### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

### 14 CFR Part 97

[Docket No. 31478; Amdt. No. 4053]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This rule establishes, amends, suspends, or removes Standard **Instrument Approach Procedures** (SIAPS) and associated Takeoff Minimums and Obstacle Departure procedures (ODPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective April 13, 2023. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 13, 2023.

**ADDRESSES:** Availability of matters incorporated by reference in the amendment is as follows:

#### For Examination

- 1. U.S. Department of Transportation, Docket Ops–M30. 1200 New Jersey Avenue SE, West Bldg., Ground Floor, Washington, DC 20590–0001.
- 2. The FAA Air Traffic Organization Service Area in which the affected airport is located;
- 3. The office of Aeronautical Information Services, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov or go to: https://www.archives.gov/federal-register/cfr/ibr-locations.html.

#### Availability

All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit the National Flight Data Center at *nfdc.faa.gov* to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from the FAA Air Traffic Organization Service Area in which the affected airport is located.

#### FOR FURTHER INFORMATION CONTACT:

Thomas J. Nichols, Flight Procedures and Airspace Group, Flight
Technologies and Procedures Division, Flight Standards Service, Federal
Aviation Administration. Mailing
Address: FAA Mike Monroney
Aeronautical Center, Flight Procedures and Airspace Group, 6500 South
MacArthur Blvd., STB Annex, Bldg 26, Room 217, Oklahoma City, OK 73099.
Telephone (405) 954–1139.

**SUPPLEMENTARY INFORMATION:** This rule amends 14 CFR part 97 by establishing, amending, suspending, or removes SIAPS, Takeoff Minimums and/or ODPS. The complete regulatory description of each SIAP and its associated Takeoff Minimums or ODP for an identified airport is listed on FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR part 97.20. The applicable FAA Forms 8260–3, 8260–4, 8260–5, 8260–15A, 8260–15B, when required by an entry on 8260–15A, and 8260–15C.

The large number of SIAPs, Takeoff Minimums and ODPs, their complex nature, and the need for a special format make publication in the Federal Register expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, Takeoff Minimums or ODPs, but instead refer to their graphic depiction on charts printed by publishers or aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP, Takeoff Minimums and ODP listed on FAA form documents is unnecessary. This amendment provides the affected CFR sections and specifies the typed of SIAPS, Takeoff Minimums and ODPs with their applicable effective dates. This amendment also identifies the airport and its location, the procedure, and the amendment number.

# Availability and Summary of Material Incorporated by Reference

The material incorporated by reference is publicly available as listed in the ADDRESSES section.

The material incorporated by reference describes SIAPS, Takeoff Minimums and/or ODPs as identified in the amendatory language for Part 97 of this final rule.

#### The Rule

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP, Takeoff Minimums and ODP as amended in the transmittal. Some SIAP and Takeoff Minimums and textual ODP amendments may have been issued previously by the FAA in a Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flights safety relating directly to published aeronautical charts.

The circumstances that created the need for some SIAP and Takeoff Minimums and ODP amendments may require making them effective in less than 30 days. For the remaining SIAPs and Takeoff Minimums and ODPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs and Takeoff Minimums and ODPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these SIAPs and Takeoff Minimums and ODPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs, Takeoff Minimums and ODPs, and safety in air commerce, I find that notice and public procedure under 5 U.S.C. 553(b) are impracticable and contrary to the public interest and. where applicable, under 5 U.S.C. 553(d), good cause exists for making some SIAPs effective in less than 30 days.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore-(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial

number of small entities under the criteria of the Regulatory Flexibility Act.

## Lists of Subjects in 14 CFR Part 97

Air Traffic Control, Airports, Incorporation by reference, Navigation (Air).

Issued in Washington, DC, on March 17, 2023.

#### Thomas J. Nichols,

Aviation Safety, Flight Standards Service Manager, Standards Section, Flight Procedures & Airspace Group, Flight Technologies & Procedures Division.

## Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me, 14 CFR part 97 is amended by establishing, amending, suspending, or removing Standard Instrument Approach Procedures and/or Takeoff Minimums and Obstacle Departure Procedures effective at 0901 UTC on the dates specified, as follows:

# PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

■ 1. The authority citation for part 97 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44701, 44719, 44721–44722.

■ 2. Part 97 is amended to read as follows:

#### Effective 20 April 2023

Danbury, CT, KDXR, RNAV (GPS) RWY 26,

Washington, DC, KDCA, RNAV (GPS) RWY 33, Amdt 1B, CANCELED

Washington, DC, KDCA, RNAV (GPS) RWY 33, Orig

St Petersburg, FL, KSPG, RNAV (GPS) RWY 7, Amdt 4

St Petersburg, FL, KSPG, RNAV (GPS) RWY 18, Amdt 1

St Petersburg, FL, KSPG, RNAV (GPS) RWY 36, Amdt 2

St Petersburg, FL, KSPG, Takeoff Minimums and Obstacle DP, Amdt 4

St Petersburg, FL, KSPG, VOR RWY 18, Amdt 10

Lihue, HI, PHLI, VOR OR TACAN RWY 21, Amdt 5

Ames, IA, KAMW, ILS OR LOC RWY 1, Amdt 4

Keokuk, IA, KEOK, ILS OR LOC RWY 26, Amdt 1

Keokuk, IA, KEOK, NDB RWY 14, Amdt 12B, CANCELED

Keokuk, IA, KEOK, RNAV (GPS) RWY 26, Amdt 1

South Bend, IN, KSBN, ILS OR LOC RWY 9R, Amdt 10C

South Bend, IN, KSBN, RNAV (GPS) RWY 9L, Amdt 1C

New Bedford, MA, KEWB, Takeoff Minimums and Obstacle DP, Amdt 8A Festus, MO, KFES, RNAV (GPS)-A, Orig-A, CANCELED Festus, MO, KFES, Takeoff Minimums and Obstacle DP, Amdt 4, CANCELED Ardmore, OK, KADM, RNAV (GPS) RWY 31, Amdt 1F

[FR Doc. 2023–07634 Filed 4–12–23; 8:45 am] **BILLING CODE 4910–13–P** 

## **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 97

[Docket No. 31479; Amdt. No. 4054]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This rule amends, suspends, or removes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide for the safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective April 13, 2023. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 13, 2023.

**ADDRESSES:** Availability of matter incorporated by reference in the amendment is as follows:

#### For Examination

- 1. U.S. Department of Transportation, Docket Ops–M30, 1200 New Jersey Avenue SE, West Bldg., Ground Floor, Washington, DC, 20590–0001;
- 2. The FAA Air Traffic Organization Service Area in which the affected airport is located;
- 3. The office of Aeronautical Information Services, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,