

(d) A computer site or service or Web address containing a digitally- or computer-manipulated image, digital image, or picture, shall contain the required statement on its homepage, any known major entry points, or principal URL (including the principal URL of a subdomain), or in a separate window that opens upon the viewer's clicking a hypertext link that states, "18 U.S.C. 2257 Record-Keeping Requirements Compliance Statement."

(e) For all other categories not otherwise mentioned in this section, the statement is to be prominently displayed consistent with the manner of display required for the aforementioned categories.

Dated: May 17, 2005.

**Alberto R. Gonzales,**  
*Attorney General.*

[FR Doc. 05-10107 Filed 5-23-05; 8:45 am]

**BILLING CODE 4410-14-P**

## DEPARTMENT OF HOMELAND SECURITY

### Coast Guard

#### 33 CFR Part 117

[CGD08-05-029]

#### **Drawbridge Operating Regulations; Berwick Bay, (Atchafalaya River) Morgan City, LA**

**AGENCY:** Coast Guard, DHS.

**ACTION:** Notice of temporary deviation from regulations.

**SUMMARY:** The Commander, Eighth Coast Guard District, has issued a temporary deviation from the regulation governing the operation of the BNSF Railway Company Vertical Lift Span Bridge across Berwick Bay, mile 0.4, (Atchafalaya River, mile 17.5) at Morgan City, St. Mary Parish, Louisiana.

**DATES:** This deviation is effective from 8 a.m. until 4 p.m. on Wednesday, June 8, 2005.

**ADDRESSES:** Materials referred to in this document are available for inspection or copying at the office of the Eighth Coast Guard District, Bridge Administration Branch, Hale Boggs Federal Building, Room 1313, 500 Poydras Street, New Orleans, Louisiana, 70130-3310 between 7 a.m. and 3 p.m., Monday through Friday, except Federal holidays. The telephone number is (504) 589-2965. The Bridge Administration Branch maintains the public docket for this temporary deviation.

**FOR FURTHER INFORMATION CONTACT:** Phil Johnson, Bridge Administration Branch, telephone (504) 589-2965.

**SUPPLEMENTARY INFORMATION:** The BNSF Railway Company has requested a temporary deviation in order to replace the railroad signal circuits of the BNSF Railway Railroad Vertical Lift Span Bridge across Berwick Bay, mile 0.4 (Atchafalaya River, mile 17.5) at Morgan City, St. Mary Parish, Louisiana. Replacement of the signal circuits is necessary to turn the lining of signals across the bridge into a fully automatic operation so that the bridge will be in full compliance with requirements of the Federal Railroad Administration. This temporary deviation will allow the bridge to remain in the closed-to-navigation position from 8 a.m. until 4 p.m. on Wednesday, June 8, 2005. There may be times, during the closure period, when the draw will not be able to open for emergencies.

The bridge provides 4 feet of vertical clearance in the closed-to-navigation position. Thus, most vessels will not be able to transit through the bridge site when the bridge is closed. Navigation on the waterway consists of tugs with tows, fishing vessels and recreational craft including sailboats and powerboats. Due to prior experience, as well as coordination with waterway users, it has been determined that this closure will not have a significant effect on these vessels.

In accordance with 33 CFR 117.35(c), this work will be performed with all due speed in order to return the bridge to normal operation as soon as possible. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: May 13, 2005.

**Marcus Redford,**

*Bridge Administrator.*

[FR Doc. 05-10277 Filed 5-23-05; 8:45 am]

**BILLING CODE 4910-15-P**

## DEPARTMENT OF HOMELAND SECURITY

### Coast Guard

#### 33 CFR Part 117

[CGD08-05-033]

#### **Drawbridge Operation Regulations; Pascagoula River, Pascagoula, MS**

**AGENCY:** Coast Guard, DHS.

**ACTION:** Notice of temporary deviation from regulations.

**SUMMARY:** The Commander, Eighth Coast Guard District, has issued a temporary deviation from the regulation governing the operation of the CSX Transportation Railroad Bridge across

the Pascagoula River, mile 1.5, at Pascagoula, Jackson County, Mississippi. This deviation allows the bridge to remain closed to navigation during the morning and afternoon time periods for four consecutive days. During the second day of the deviation, the bridge will remain closed to navigation continuously for ten hours. The deviation is necessary to repair the drive motor and associated hydraulic components of the draw span operating mechanism.

**DATES:** This deviation is effective from 8 a.m. on Monday June 13, 2005 until 6 p.m. on Thursday, June 16, 2005.

**ADDRESSES:** Materials referred to in this document are available for inspection or copying at the office of the Eighth Coast Guard District, Bridge Administration Branch, Hale Boggs Federal Building, room 1313, 500 Poydras Street, New Orleans, Louisiana 70130-3310 between 7 a.m. and 3 p.m., Monday through Friday, except Federal holidays. The telephone number is (504) 589-2965. The Bridge Administration Branch of the Eighth Coast Guard District maintains the public docket for this temporary deviation.

**FOR FURTHER INFORMATION CONTACT:**

David Frank, Bridge Administration Branch, telephone (504) 589-2965.

**SUPPLEMENTARY INFORMATION:** The CSX Transportation Company has requested a temporary deviation in order to repair the main drive motor and associated hydraulic components of the operating mechanism of the CSX Transportation Railroad Bascule Span Bridge across the Pascagoula River, mile 1.5, at Pascagoula, Jackson County, Mississippi. This temporary deviation will allow the bridge to remain in the closed-to-navigation position from 8 a.m. to noon and from 1 p.m. to 6 p.m. on Monday, June 13, 2005, Wednesday, June 15, 2005, and Thursday, June 16, 2005. On Tuesday, June 14, 2005, the bridge will remain closed to navigation continuously from 8 a.m. until 6 p.m. to facilitate installation of a shaft. A temporary deviation was previously approved to complete these repairs in March 2005; however, the required replacement parts were unavailable. The bridge owner has obtained all of the required parts and is now ready to complete the repairs. The repairs are necessary for continued safe operation of the draw span.

As the bridge has no vertical clearance in the closed-to-navigation position, vessels will not be able to transit through the bridge site when the bridge is closed. Navigation on the waterway consists of small cargo ships, tugs with tows, fishing vessels and