

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2007-28253; Directorate Identifier 2007-NM-031-AD; Amendment 39-15064; AD 2007-11-07]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-100, -200, -200C, -300, -400, and -500 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting a typographical error in an existing airworthiness directive (AD) that was published in the **Federal Register** on May 22, 2007 (72 FR 28597). The error resulted in a confusing compliance time. This AD applies to all Boeing Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. This AD requires repetitive detailed inspections for damage of the electrical wire and sleeve that run to the fuel boost pump through a conduit in the fuel tank, and arcing damage of the conduit and signs of fuel leakage into the conduit; replacement of the sleeve with a new, smaller-diameter sleeve; and related investigative and corrective actions, as applicable.

DATES: Effective June 6, 2007.

ADDRESSES: The AD docket contains the proposed AD, comments, and any final disposition. You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located on the ground level of the West Building at the DOT street address stated in the **ADDRESSES** section. This docket number is FAA-2007-28253; the directorate identifier for this docket is 2007-NM-031-AD.

FOR FURTHER INFORMATION CONTACT: Suzanne Lucier, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6438; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION: On May 2, 2007, the FAA issued AD 2007-11-07, amendment 39-15064 (72 FR 28597, May 22, 2007), for all Boeing Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. The AD requires repetitive detailed inspections for

damage of the electrical wire and sleeve that run to the fuel boost pump through a conduit in the fuel tank, and arcing damage of the conduit and signs of fuel leakage into the conduit; replacement of the sleeve with a new, smaller-diameter sleeve; and related investigative and corrective actions, as applicable.

As published, paragraph (k) of AD 2007-11-07 reads “* * * * Thereafter, repeat the detailed inspection at intervals not to exceed 15,000 flight cycles. * * *” The correct term, “flight hours” (not flight cycles), appears in all other compliance times cited in the AD, as intended.

No other part of the regulatory information has been changed; therefore, the final rule is not republished in the **Federal Register**.

The effective date of this AD remains June 6, 2007.

§ 39.13 [Corrected]

■ In the **Federal Register** of May 22, 2007, on page 28600, in the third column, paragraph (k) of AD 2007-11-07 is corrected to read as follows:

* * * * *

(k) At the applicable time specified by paragraph (k)(1) or (k)(2) of this AD: Do a detailed inspection for damage of the sleeve and electrical wire of the fuel boost pump; and, before further flight, install a new, smaller-diameter sleeve, and do related investigative and corrective actions, as applicable; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-28A1263, Revision 1, dated March 19, 2007. Thereafter, repeat the detailed inspection at intervals not to exceed 15,000 flight hours. Accomplishment of the initial inspection, applicable corrective actions, and sleeve installation required by this paragraph terminates the requirements of paragraphs (f), (g), (h), and (i) of this AD.

* * * * *

Issued in Renton, Washington, on August 14, 2007.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-16304 Filed 8-20-07; 8:45 am]

BILLING CODE 4910-13-P

SECURITIES AND EXCHANGE COMMISSION

17 CFR Part 232

[Release Nos. 33-8834; 34-56256; 39-2448; IC-27928]

RIN 3235-AG96

Adoption of Updated EDGAR Filer Manual

AGENCY: Securities and Exchange Commission.

ACTION: Final rule.

SUMMARY: The Securities and Exchange Commission (the Commission) is adopting revisions to the Electronic Data Gathering, Analysis, and Retrieval System (EDGAR) Filer Manual to reflect updates to the EDGAR system.

Revisions are being made primarily to support the expansion of the current interactive data voluntary reporting program to enable mutual funds voluntarily to submit supplemental tagged information contained in the risk/return summary section of their prospectuses on Form N-1A. The EDGAR system is being upgraded to support this functionality on August 20, 2007.

The filer manual is also being revised to incorporate changes in support of several final rules previously adopted by the Commission and implemented in EDGAR. Those rules include the termination of a foreign private issuer's registration of a class of securities under Section 12(g) and duty to file reports under Section 13(a) or 15(d) of the Securities Exchange Act of 1934 (“Exchange Act”); the electronic filing of Transfer Agent (“TA”) forms TA-1, TA-2 and TA-W; and revisions to the accelerated filer definition under the Exchange Act. Other revisions were made to allow an issuer to indicate whether it is subject to reporting obligations after terminating registration of a class of equity securities under the Exchange Act and to remove references to submission types N-14AE and N-14AE/A for the filing of Form N-14 from “Table 3-5: Investment Company Submission Types Accepted by EDGAR” of the Filer Manual.

Revisions to the Filer Manual reflect changes within Volumes I and II, entitled EDGAR Filer Manual, Volume I: “General Information,” Version 4 (August 2007) and EDGAR Filer Manual, Volume II: “EDGAR Filing,” Version 5 (August 2007) respectively. The updated manual will be incorporated by reference into the Code of Federal Regulations.

DATES: *Effective Date:* August 20, 2007. The incorporation by reference of the EDGAR Filer Manual is approved by the Director of the Federal Register as of August 20, 2007.

FOR FURTHER INFORMATION CONTACT: In the Office of Information Technology, Rick Heroux, at (202) 551-8800; in the Division of Investment Management, for questions concerning the expansion of the current interactive data voluntary reporting program, Alberto H. Zapata, Senior Counsel, or Brent J. Fields, Assistant Director, Office of Disclosure Regulation, at (202) 551-6784, and for