

Conclusion

This action affects only certain design features on Learjet Model 24/25 series airplanes modified by LJSC Ltd. It is not a rule of general applicability and affects only the applicant who applied to the FAA for approval of these features on the airplane.

The substance of the special conditions for this airplane has been subjected to notice and comment procedure in several prior instances and has been derived without substantive change from those previously issued. Because a delay would significantly affect the certification of the airplane, which is imminent, the FAA has determined that prior public notice and comment are unnecessary and impracticable, and good cause exists for adopting these special conditions upon issuance. The FAA is requesting comments to allow interested persons to submit views that may not have been submitted in response to the prior opportunities for comment described above.

List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and record keeping requirements.

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

The Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the supplemental type certification basis for Learjet Model 24/25 series airplanes modified by LJSC Ltd.

1. *Protection from Unwanted Effects of High-Intensity Radiated Fields (HIRF).* Each electrical and electronic system that performs critical functions must be designed and installed to ensure that the operation and operational capability of these systems to perform critical functions are not adversely affected when the airplane is exposed to high-intensity radiated fields external to the airplane.

2. For the purpose of these special conditions, the following definition applies:

Critical Functions. Functions whose failure would contribute to or cause a failure condition that would prevent the continued safe flight and landing of the airplane.

Issued in Renton, Washington, on April 14, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-10450 Filed 4-28-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 25

[Docket No. NM250; Special Conditions No. 25-233-SC]

Special Conditions: Israel Aircraft Industries Ltd. Model 1124 Airplanes; High-Intensity Radiated Fields (HIRF)

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final special conditions; request for comments.

SUMMARY: These special conditions are issued for Israel Aircraft Industries Ltd. Model 1124 airplanes modified by Alternative Aviation Services. These modified airplanes will have a novel or unusual design feature when compared to the state of technology envisioned in the airworthiness standards for transport category airplanes. The modification incorporates the installation of dual Innovative Solutions & Support Air Data Display Units. The applicable airworthiness regulations do not contain adequate or appropriate safety standards for the protection of these systems from the effects of high-intensity radiated fields (HIRF). These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

DATES: The effective date of these special conditions is April 18, 2003.

Comments must be received on or before May 29, 2003.

ADDRESSES: Comments on these special conditions may be mailed in duplicate to: Federal Aviation Administration, Transport Airplane Directorate, Attn: Rules Docket (ANM-113), Docket No. NM250, 1601 Lind Avenue SW., Renton Washington, 98055-4056; or delivered in duplicate to the Transport Airplane Directorate at the above address. All comments must be marked: Docket No. NM250.

FOR FURTHER INFORMATION CONTACT: Greg Dunn, FAA, Airplane and Flight Crew Interface Branch, ANM-111, Transport Airplane Directorate, Aircraft Certification Service, 1601 Lind Avenue

SW., Renton, Washington 98055-4056; telephone (425) 227-2799; facsimile (425) 227-1320.

SUPPLEMENTARY INFORMATION:

FAA Determination as to Need for Public Process

The FAA has determined that notice and opportunity for prior public comment is impracticable because these procedures would significantly delay certification of the airplane and thus delivery of the affected airplane. The FAA therefore finds that good cause exists for making these special conditions effective upon issuance; however the FAA invites interested persons to participate in this rulemaking by submitting written comments, data, or views. The most helpful comments reference a specific portion of the special conditions, explain the reason for any recommended change, and include supporting data. We ask that you send us two copies of written comments.

We will file in the docket all comments we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning these special conditions. The docket is available for public inspection before and after the comment closing date. If you wish to review the docket in person, go to the address in the **ADDRESSES** section of this document between 7:30 a.m. and 4 p.m., Monday through Friday, except Federal holidays.

We will consider all comments we receive on or before the closing date for comments. We will consider comments filed late if it is possible to do so without incurring expense or delay. We may change these special conditions based on comments we receive.

If you want the FAA to acknowledge receipt of your comments on these special conditions, include with your comments a pre-addressed, stamped postcard on which the docket number appears. We will stamp the date on the postcard and mail it back to you.

Background

On September 25, 2002, Alternative Aviation Services, 1661 Airport Road, Waterford, MI 48327, applied for a supplemental type certificate (STC) to modify Israel Aircraft Industries Ltd. Model 1124 airplanes approved under Type Certificate No. A2SW. The Model 1124 is a small transport category airplane powered by two Airesearch Manufacturing Company TFE-731-3-1G turbofan engines and has a maximum takeoff weight of 23,500 pounds. This airplane operates with a 2-pilot crew and can hold up to 10

passengers. The modification incorporates the installation of Innovative Solutions & Support Air Data Display Units (ADDU). The ADDU replaces the existing analog flight instrumentation and provides additional functional capability and redundancy in the system. The avionics/electronics and electrical systems installed in this airplane have the potential to be vulnerable to high-intensity radiated fields (HIRF) external to the airplane.

Type Certification Basis

Under the provisions of 14 CFR 21.101, Amendment 21–69, effective September 16, 1991, Alternative Aviation Services must show that the Israel Aircraft Industries Ltd. Model 1124 airplane, as changed, continues to meet the applicable provisions of the regulations incorporated by reference in Type Certificate No. A2SW, or the applicable regulations in effect on the date of application for the change. [Subsequent changes have been made to § 21.101 as part of Amendment 21–77, but those changes do not become effective until June 10, 2003.] The regulations incorporated by reference in the type certificate are commonly referred to as the “original type certification basis.” The original type certification basis for the modified Israel Aircraft Industries Ltd. Model 1124 airplanes includes 14 CFR part 25 as amended by Amendments 25–1 through 25–20, dated February 1, 1964, except for special conditions and exceptions noted in Type Certificate Data Sheet A2SW.

If the Administrator finds that the applicable airworthiness regulations (that is, part 25, as amended) do not contain adequate or appropriate safety standards for the Israel Aircraft Industries Ltd. Model 1124 airplanes because of a novel or unusual design feature, special conditions are prescribed under the provisions of § 21.16.

In addition to the applicable airworthiness regulations and special conditions, the Israel Aircraft Industries Ltd. Model 1124 airplanes must comply with the fuel vent and exhaust emission requirements of 14 CFR part 34 and the noise certification requirement of 14 CFR part 36.

Special conditions, as defined in 14 CFR 11.19, are issued in accordance with § 11.38 and become part of the type certification basis in accordance with § 21.101(b)(2), Amendment 21–69, effective September 16, 1991.

Special conditions are initially applicable to the model for which they are issued. Should Alternative Aviation Services apply at a later date for a

supplemental type certificate to modify any other model included on Type Certificate No. A2SW to incorporate the same or similar novel or unusual design feature, these special conditions would also apply to the other model under the provisions of § 21.101(a)(1), Amendment 21–69, effective September 16, 1991.

Novel or Unusual Design Features

As noted earlier, Israel Aircraft Industries Ltd. Model 1124 airplanes modified by Alternative Aviation Services will incorporate systems comprised of dual Innovative Solutions & Support Air Data Display Units that will perform critical functions. These systems may be vulnerable to high-intensity radiated fields external to the airplane. The current airworthiness standards of part 25 do not contain adequate or appropriate safety standards for the protection of this equipment from the adverse effects of HIRF.

Accordingly, this system is considered to be a novel or unusual design feature.

Discussion

There is no specific regulation that addresses protection requirements for electrical and electronic systems from HIRF. Increased power levels from ground-based radio transmitters and the growing use of sensitive avionics/electronics and electrical systems to command and control airplanes have made it necessary to provide adequate protection.

To ensure that a level of safety is achieved equivalent to that intended by the regulations incorporated by reference, special conditions are needed for Israel Aircraft Industries Ltd. Model 1124 airplanes modified by Alternative Aviation Services. These special conditions require that new avionics/electronics and electrical systems that perform critical functions be designed and installed to preclude component damage and interruption of function due to both the direct and indirect effects of HIRF.

High-Intensity Radiated Fields (HIRF)

With the trend toward increased power levels from ground-based transmitters and the advent of space and satellite communications, coupled with electronic command and control of the airplane, the immunity of critical avionics/electronics and electrical systems to HIRF must be established.

It is not possible to precisely define the HIRF to which the airplane will be exposed in service. There is also uncertainty concerning the effectiveness of airframe shielding for HIRF. Furthermore, coupling of

electromagnetic energy to cockpit-installed equipment through the cockpit window apertures is undefined. Based on surveys and analysis of existing HIRF emitters, an adequate level of protection exists when compliance with the HIRF protection special condition is shown with either paragraph 1, or 2 below:

1. A minimum threat of 100 volts rms (root-mean-square) per meter electric field strength from 10 KHz to 18 GHz.

a. The threat must be applied to the system elements and their associated wiring harnesses without the benefit of airframe shielding.

b. Demonstration of this level of protection is established through system tests and analysis.

2. A threat external to the airframe of the field strengths identified in the table below for the frequency ranges indicated. Both peak and average field strength components from the table are to be demonstrated.

Frequency	Field Strength (volts per meter)	
	Peak	Average
10 kHz—100 kHz	50	50
100 kHz—500 kHz	50	50
500 kHz—2 MHz	50	50
2 MHz—30 MHz	100	100
30 MHz—70 MHz	50	50
70 MHz—100 MHz	50	50
100 MHz—200 MHz	100	100
200 MHz—400 MHz	100	100
400 MHz—700 MHz	700	50
700 MHz—1 GHz	700	100
1 GHz—2 GHz	2000	200
2 GHz—4 GHz	3000	200
4 GHz—6 GHz	3000	200
6 GHz—8 GHz	1000	200
8 GHz—12 GHz	3000	300
12 GHz—18 GHz	2000	200
18 GHz—40 GHz	600	200

The field strengths are expressed in terms of peak of the root-mean-square (rms) over the complete modulation period.

The threat levels identified above are the result of an FAA review of existing studies on the subject of HIRF, in light of the ongoing work of the Electromagnetic Effects Harmonization Working Group of the Aviation Rulemaking Advisory Committee.

Applicability

As discussed above, these special conditions are applicable to Israel Aircraft Industries Ltd. Model 1124 airplanes modified by Alternative Aviation Services. Should Alternative Aviation Services apply at a later date for a supplemental type certificate to modify any other model included on Type Certificate A2SW to incorporate the same or similar novel or unusual design feature, these special conditions would apply to that model as well.

under the provisions of § 21.101(a)(1), Amendment 21–69, effective September 16, 1991.

Conclusion

This action affects only certain novel or unusual design features on Israel Aircraft Industries Ltd. Model 1124 airplanes modified by Alternative Aviation Services. It is not a rule of general applicability and affects only the applicant who applied to the FAA for approval of these features on the airplane.

The substance of these special conditions has been subjected to the notice and comment period in several prior instances and has been derived without substantive change from those previously issued. Because a delay would significantly affect the certification of the airplane, which is imminent, the FAA has determined that prior public notice and comment are unnecessary and impracticable, and good cause exists for adopting these special conditions upon issuance. The FAA is requesting comments to allow interested persons to submit views that may not have been submitted in response to the prior opportunities for comment described above.

List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

■ The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

The Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the supplemental type certification basis for Israel Aircraft Industries Ltd. Model 1124 airplanes modified by Alternative Aviation Services.

1. *Protection from Unwanted Effects of High-Intensity Radiated Fields (HIRF).* Each electrical and electronic system that performs critical functions must be designed and installed to ensure that the operation and operational capability of these systems to perform critical functions are not adversely affected when the airplane is exposed to high-intensity radiated fields.

2. For the purpose of these special conditions, the following definition applies:

Critical Functions: Functions whose failure would contribute to or cause a failure condition that would prevent the continued safe flight and landing of the airplane.

Issued in Renton, Washington, on April 18, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03–10446 Filed 4–28–03; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003–CE–01–AD; Amendment 39–13130; AD 2003–09–01]

RIN 2120–AA64

Airworthiness Directives; Pilatus Aircraft Ltd. Model PC–6 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to all Pilatus Aircraft Ltd. (Pilatus) Model PC–6 airplanes. This AD requires you to inspect and correct, as necessary, the aileron control bellcrank assemblies at the wing and fuselage locations. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Switzerland. The actions specified by this AD are intended to detect and correct increased friction in the aileron control bellcrank assemblies, which could result in failure of the aileron flight-control system. Such failure could lead to problems in controlling flight.

DATES: This AD becomes effective on June 17, 2003.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of June 17, 2003.

ADDRESSES: You may get the service information referenced in this AD from Pilatus Aircraft Ltd., Customer Liaison Manager, CH–6371 Stans, Switzerland; telephone: +41 41 619 63 19; facsimile: +41 41 619 6224; or from Pilatus Business Aircraft Ltd., Product Support Department, 11755 Airport Way, Broomfield, Colorado 80021; telephone: (303) 465–9099; facsimile: (303) 465–6040. You may view this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003–CE–01–AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4059; facsimile: (816) 329–4090.

SUPPLEMENTARY INFORMATION:

Discussion

What events have caused this AD? The Federal Office for Civil Aviation (FOCA), which is the airworthiness authority for Switzerland, recently notified FAA that an unsafe condition may exist on all Pilatus Model PC–6 airplanes. The FOCA reports one occurrence where the pilot reported increased friction on the ailerons. Inspection revealed unwanted axial movement of the aileron bellcrank assemblies, part numbers 6132.0071.51, 6132.0071.52, and 6232.0118.00. The axial movement is caused by deterioration of the adhesive bond around the bellcrank bearings which could cause the heads of the control cable attachment bolts to catch on the adjacent structure.

Has FAA taken any action to this point? We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain Pilatus Model PC–6 airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on February 12, 2003 (68 FR 7081). The NPRM proposed to you to inspect and correct, as necessary, the aileron control bellcrank assemblies at the wing and fuselage locations.

What is the potential impact if FAA took no action? Increased friction in the aileron control bellcrank assemblies could result in failure of the aileron flight-control system. Such failure could lead to problems in controlling flight.

Was the public invited to comment? The FAA encouraged interested persons to participate in the making of this amendment. We did not receive any comments on the proposed rule or on our determination of the cost to the public.

FAA's Determination

What is FAA's final determination on this issue? We carefully reviewed all available information related to the subject presented above and determined that air safety and the public interest require the adoption of the rule as proposed except for the changes discussed above and minor editorial questions. We have determined that these changes and minor corrections: