

Rules and Regulations

Federal Register

Vol. 69, No. 123

Monday, June 28, 2004

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 89-ANE-10-AD; Amendment 39-13644; AD 2004-10-14]

RIN 2120-AA64

Airworthiness Directives; Lycoming Engines (Formerly Textron Lycoming), Direct-Drive Reciprocating Engines; Correction

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document makes corrections to Airworthiness Directive (AD) 2004-10-14, applicable to Lycoming Engines (formerly Textron Lycoming), direct-drive reciprocating engines that was published in the **Federal Register** on May 21, 2004 (69 FR 29210). Some corrections to engine models have been made by adding missing dashes, clarification to changes in requirements from the proposed rule are made, and some corrections are made for clarification in the compliance section. In all other respects, the original document remains the same.

DATES: *Effective Date:* Effective June 28, 2004.

FOR FURTHER INFORMATION CONTACT: Norm Perenson, Aerospace Engineer, New York Aircraft Certification Office, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (516) 228-7337; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION: A final rule AD, FR Doc. 04-11406, applicable to Lycoming Engines direct-drive reciprocating engines (except O-145, O-320-H, O-360-E, IO-360-E, LTO-360-E, O-435, and TIO 541 series engines), was published in the **Federal Register** on May 21, 2004 (69 FR 29210). The following corrections are needed:

On page 29210, in the second column, in the **SUMMARY** section, in the sixth and seventh lines, "O-320H, O-360E, LO-360E, LTO-360E" are corrected to read "O-320-H, O-360-E, LO-360-E, LTO-360-E, TO-360-E".

In the third column, in the **SUMMARY** section, in the 14th line, after the words "propeller strike.", a sentence is added to read "This AD removes the requirement to perform inspections at overhaul and during repair of the gear train, because Lycoming has incorporated those procedures from their Service Bulletin into their Overhaul Manual."

Also in the third column, in the **SUPPLEMENTARY INFORMATION** section, in the seventh and eighth lines, "O-320H, O-360E, LO-360E, LTO-360E" is corrected to read "O-320-H, O-360-E, LO-360-E, LTO-360-E, TO-360-E".

On page 29211, in the second column, after the second paragraph, add the following paragraph:

Other Corrections

The TO-360-E engine model was inadvertently omitted from the list of exceptions of engines. That engine model has been added to the list of exceptions of engines not affected by this AD. Also, some of the engine model numbers were missing dashes and are corrected in this AD. Also, the phrase of after the effective date of this AD, was inadvertently omitted from paragraph (e). This phrase is added to paragraph (e) to cover engines that experience a propeller strike after the effective date of the AD.

§ 39.13 [Corrected]

■ Also, on page 29211, in the third column, eighth paragraph, fourth and fifth lines, "O-320H, O-360E, LO-360E, LTO-360E" is corrected to read "O-320-H, O-360-E, LO-360-E, LTO-360-E, TO-360-E".

■ Also, on page 29211, in the third column, paragraph (e), which reads "Compliance with this AD is required as indicated before further flight if the engine has experienced a propeller strike as defined in paragraphs (i) and (j) of this AD, unless already done." is corrected to read "Compliance with this AD is required as indicated before further flight if the engine experiences a propeller strike after the effective date of this AD, as defined in paragraphs (i) and (j) of this AD."

Issued in Burlington, MA, on June 18, 2004.

Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.
[FR Doc. 04-14477 Filed 6-25-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2004-17433; Airspace Docket No. 04-ACE-31]

Modification of Class E Airspace; Kimball, NE

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; confirmation of effective date.

SUMMARY: This document confirms the effective date of the direct final rule which revises Class E airspace at Kimball, NE.

DATES: *Effective Date:* 0901 UTC, August 5, 2004.

FOR FURTHER INFORMATION CONTACT: Brenda Mumper, Air Traffic Division, Airspace Branch, ACE-520A, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas City, MO 64104; telephone: (816) 329-2524.

SUPPLEMENTARY INFORMATION: The FAA published this direct final rule with a request for comments in the **Federal Register** on May 11, 2004 (69 FR 26031). The FAA uses the direct final rulemaking procedure for a non-controversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, were received within the comment period, the regulation would become effective on August 5, 2004. No adverse comments were received, and thus this notice confirms that this direct final rule will become effective on that date.