

# Rules and Regulations

Federal Register

Vol. 88, No. 234

Thursday, December 7, 2023

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2023–1717; Project Identifier MCAI–2023–00728–A; Amendment 39–22578; AD 2023–21–06]

RIN 2120–AA64

#### Airworthiness Directives; Embraer S.A. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** The FAA is correcting an airworthiness directive (AD) that published in the **Federal Register**. That AD applies to certain Embraer S.A. (Embraer) Model EMB–505 airplanes. As published, two references to an Agência Nacional de Aviação Civil (ANAC) AD in the preamble Background section are incorrect. This document corrects those errors. In all other respects, the original document remains the same.

**DATES:** This correction is effective December 11, 2023. The effective date of AD 2023–21–06 remains December 11, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 11, 2023 (88 FR 76114, November 6, 2023).

#### ADDRESSES:

**AD Docket:** You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1717; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule; correction, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building

Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### Material Incorporated by Reference:

- For the service information identified in this final rule, contact ANAC, Continuing Airworthiness Technical Branch (GTAC), Rua Doutor Orlando Feirabend Filho, 230—Centro Empresarial Aquarius—Torre B—Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246–190—São José dos Campos—SP, Brazil; phone: 55 (12) 3203–6600; email: [pac@anac.gov.br](mailto:pac@anac.gov.br); website: [anac.gov.br/en/](https://anac.gov.br/en/). You may find this material on the ANAC website at [sistemas.anac.gov.br/certificacao/DA/DAE.asp](https://sistemas.anac.gov.br/certificacao/DA/DAE.asp).

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110. It is also available in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1717.

**FOR FURTHER INFORMATION CONTACT:** Jim Rutherford, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (816) 329–4165; email: [jim.rutherford@faa.gov](mailto:jim.rutherford@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Background

AD 2023–21–06, Amendment 39–22578 (88 FR 76114, November 6, 2023) (AD 2023–21–06), requires installing structural reinforcements on certain monuments and replacing certain floor support rivets, as specified in ANAC AD 2023–05–03, effective June 2, 2023 (ANAC AD 2023–05–03), for certain Embraer Model EMB–505 airplanes.

##### Need for Correction

As published, two references to the ANAC AD in the preamble Background section of AD 2023–21–06 are incorrect. The Background section refers to the ANAC AD as “ANAC AD 2023–04–01” in two places. The correct reference is “ANAC AD 2023–05–03.”

##### Related Service Information Under 1 CFR Part 51

ANAC AD 2023–05–03 specifies procedures for installing structural reinforcements on certain monuments and replacing applicable fasteners on the floor support.

This material is reasonably available because the interested parties have

access to it through their normal course of business or by the means identified in **ADDRESSES**.

#### Correction of Publication

This document corrects two errors and correctly adds the AD as an amendment to 14 CFR 39.13. Although no other part of the preamble or regulatory information has been corrected, the FAA is publishing the entire rule in the **Federal Register**.

The effective date of this AD remains December 11, 2023.

Since this action only corrects two incorrect references to an ANAC AD in the preamble Background section, it has no adverse economic impact and imposes no additional burden on any person. Therefore, the FAA has determined that notice and public comment procedures are unnecessary.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Corrected]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2023–21–06 Embraer S.A.:** Amendment 39–22578; Docket No. FAA–2023–1717; Project Identifier MCAI–2023–00728–A.

##### (a) Effective Date

This airworthiness directive (AD) is effective December 11, 2023.

##### (b) Affected ADs

None.

##### (c) Applicability

This AD applies to Embraer S.A. Model EMB–505 airplanes, as identified in Agência Nacional de Aviação Civil (ANAC) AD 2023–05–03, effective June 2, 2023 (ANAC AD 2023–05–03), certificated in any category.

**(d) Subject**

Joint Aircraft System Component (JASC)  
Code 2500, Cabin Equipment/Furnishings.

**(e) Unsafe Condition**

This AD was prompted by analysis of certain monuments (the right-hand refreshment center and left-hand forward cabinet) that identified the need for installing structural reinforcements and replacing applicable floor support rivets. The FAA is issuing this AD to address the unsafe condition. The unsafe condition, if not addressed, could result in a monument not withstanding the loads expected for specific emergency landing conditions, which may cause the detachment of mass items and result in injuries to the airplane occupants.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, ANAC AD 2023–05–03.

**(h) Exceptions to ANAC AD 2023–05–03**

(1) Where ANAC AD 2023–05–03 refers to its effective date, this AD requires using the effective date of this AD.

(2) The service information referenced in ANAC AD 2023–05–03 allows the use of alternative or similar parts in place of the ones specified in the kits, provided that these alternative or similar parts are approved by Embraer. This AD requires approval from either the Manager, International Validation Branch, FAA; ANAC; or ANAC's authorized Designee. If approved by the ANAC Designee, the approval must include the Designee's authorized signature.

(3) Where the service information referenced in ANAC AD 2023–05–03 specifies discarding parts, this AD requires removing those parts from service.

(4) This AD does not adopt paragraph (d) of ANAC AD 2023–05–03.

**(i) No Reporting Requirement**

Although the service information referenced in ANAC AD 2023–05–03 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

**(j) Alternative Methods of Compliance (AMOCs)**

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (k) of this AD or email to: 9-AVS-AIR-730-AMOC@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector,

or lacking a principal inspector, the manager of the local Flight Standards District Office/certificate holding district office.

**(k) Additional Information**

For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (816) 329–4165; email: jim.rutherford@faa.gov.

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Agência Nacional de Aviação Civil (ANAC) AD 2023–05–03, effective June 2, 2023.

(ii) [Reserved]

(3) For ANAC AD 2023–05–03, contact ANAC, Continuing Airworthiness Technical Branch (GTAC), Rua Doutor Orlando Feirabend Filho, 230—Centro Empresarial Aquarius—Torre B—Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246–190—São José dos Campos—SP, Brazil; phone: 55 (12) 3203–6600; email: pac@anac.gov.br; website: anac.gov.br/en/. You may find this material on the ANAC website at [sistemas.anac.gov.br/certificacao/DA/DAE.asp](https://sistemas.anac.gov.br/certificacao/DA/DAE.asp).

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](https://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on November 29, 2023.

**Victor Wicklund,**

*Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2023–26637 Filed 12–6–23; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA–2023–2192; Airspace  
Docket No. 23–AEA–19]

**RIN 2120–AA66**

**Amendment of Class D and Class E Airspace; Wilmington, DE**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action amends Class D airspace and Class E surface airspace for

New Castle Airport, Wilmington, DE, by making editorial changes to the airspace legal descriptions. This action does not change the airspace boundaries or operating requirements.

**DATES:** Effective 0901 UTC, March 21, 2024. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order JO 7400.11H, Airspace Designations, Reporting Points, and subsequent amendments online at [www.faa.gov/air\\_traffic/publications/](https://www.faa.gov/air_traffic/publications/). For further information, contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

**FOR FURTHER INFORMATION CONTACT:** John Goodson, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Avenue, College Park, GA 30337; telephone: (404) 305–5966.

**SUPPLEMENTARY INFORMATION:****Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority, as it updates airspace descriptions. This update is an administrative change and does not change the airspace boundaries or operating requirements.

**Incorporation by Reference**

Class D and Class E airspace are published in paragraphs 5000 and 6002 of FAA Order JO 7400.11, Airspace Designations and Reporting Points, which is incorporated by reference in 14 CFR 71.1 annually. This document amends the current version of that order, FAA Order JO 7400.11H, dated August 11, 2023, and effective September 15, 2023. FAA Order JO 7400.11H is publicly available as listed in the **ADDRESSES** section of this document. These amendments will be published in the next FAA Order JO 7400.11 update. FAA Order JO