

the compliance times specified, unless the actions have already been done.

Restatement of Requirements of AD 2009-02-06 With Clarifications of Compliance Requirements

Service Bulletin Reference Paragraph

(g) The term "service bulletin," as used in this AD, means Boeing Alert Service Bulletin 737-53A1279, dated December 18, 2007.

(1) Where the service bulletin specifies a compliance time after the date on the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) The "Condition" column of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, dated December 18, 2007, refers to total flight cycles "at the date given on this service bulletin." However, this AD applies to the airplanes with the specified total flight cycles as of April 15, 2009 (the effective date of AD 2009-02-06).

(3) Where the service bulletin specifies to contact Boeing for instructions for removing damage and repairing cracking: Before further flight, remove the damage or repair the cracking using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(4) Although the service bulletin referenced in this AD specifies to submit information to the manufacturer, this AD does not include that requirement.

Inspections, Related Investigative Actions, and Corrective Actions

(h) At the applicable time specified in paragraph 1.E., "Compliance," of the service bulletin, except as specified by paragraph (g)(1) of this AD: Do a high frequency eddy current (HFEC) surface inspection or an HFEC hole/edge inspection for cracking of the 1.04-inch nominal diameter wire penetration hole in the frame and frame reinforcement, between stringer S-20 and S-21; and do all applicable related investigative and corrective actions by accomplishing all the actions specified in the Accomplishment Instructions of the service bulletin, except as specified by paragraphs (g)(3) and (g)(4) of this AD. Do all applicable related investigative and corrective actions before further flight. Thereafter, repeat the inspections at the applicable intervals specified in paragraph 1.E., "Compliance," of the service bulletin.

Terminating Action

(i) Doing the repair in Part 3 or the preventative modification in Part 5 of the Accomplishment Instructions of the service bulletin terminates the repetitive inspection requirements of this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *Attn:* Wayne Lockett, Aerospace Engineer, Airframe Branch, ANM-120S, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6447; fax (425) 917-6590. Or,

e-mail information to *9-ANM-Seattle-ACO-AMOC-Requests@faa.gov*.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and the approval must specifically refer to this AD.

Material Incorporated by Reference

(k) You must use Boeing Alert Service Bulletin 737-53A1279, dated December 18, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register previously approved the incorporation by reference of Boeing Alert Service Bulletin 737-53A1279, dated December 18, 2007, on April 15, 2009 (74 FR 10469, March 11, 2009).

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1, fax 206-766-5680; e-mail *me.boecom@boeing.com*; Internet *https://www.myboeingfleet.com*.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: *http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html*.

Issued in Renton, Washington, on August 26, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-21311 Filed 9-4-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2009-0362; Airspace Docket No. 09-ASW-10]

Establishment of Class D Airspace; Arlington, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends Class E airspace at Arlington, TX. Establishment of an air traffic control tower at Arlington Municipal Airport has made this action necessary for the safety and management of Instrument Flight Rule (IFR) operations at Arlington Municipal Airport.

DATES: 0901 UTC, December 17, 2009. The Director of the Federal Register approves this incorporation by reference action under 1 CFR Part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT:

Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone (817) 321-7716.

SUPPLEMENTARY INFORMATION:

History

On June 24, 2009, the FAA published in the **Federal Register** a notice of proposed rulemaking to establish Class D airspace at Arlington Municipal Airport, Arlington, TX. (74 FR 30022, Docket No. FAA-2009-0362). Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received. Class D airspace designations are published in paragraph 5000 of FAA Order 7400.9S, signed October 3, 2008, and effective October 31, 2008, which is incorporated by reference in 14 CFR Part 71.1. The Class D airspace designations listed in this document will be published subsequently in the Order.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) Part 71 by establishing Class D airspace extending upward from the surface up to but not including 2,000 feet MSL for the safety and management of IFR operations at Arlington Municipal Airport, Arlington, TX.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes controlled airspace at Arlington Municipal Airport, Arlington, TX.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR Part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR Part 71.1 of the Federal Aviation Administration Order 7400.9S, Airspace Designations and Reporting Points, signed October 3, 2008, and effective October 31, 2008, is amended as follows:

Paragraph 5000 Class D airspace.

* * * * *

ASW TX D Arlington, TX [New]

Arlington Municipal Airport, TX (Lat. 32°39’50” N., long. 97°05’39” W.)

That airspace extending upward from the surface, to but not including 2,000 feet MSL within a 4-mile radius of Arlington Municipal Airport, excluding the portion east of a line between lat. 32°43’48” N.; long. 97°05’06” W.; and lat. 32°38’10” N.; long. 97°3’26” W., and lat. 32°36’16” N.; long. 97°03’31” W., and excluding that airspace within the Dallas/Fort Worth, TX, Class B airspace area. This Class D airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective dates and times will thereafter be continuously published in the Airport/Facility Directory.

* * * * *

Issued in Fort Worth, Texas, on August 25, 2009.

Ronnie L. Uhlenhaker,

Acting Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. E9–21224 Filed 9–4–09; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2009–0363; Airspace Docket No. 09–ASW–11]

Establishment of Class D Airspace; Grand Prairie, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class D airspace at Grand Prairie, TX. Establishment of an air traffic control tower at Grand Prairie Municipal Airport has made this action necessary for the safety and management of Instrument Flight Rule (IFR) operations at Grand Prairie Municipal Airport.

DATES: 0901 UTC, December 17, 2009. The Director of the Federal Register approves this incorporation by reference action under 1 CFR Part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT:

Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone (817) 321–7716.

SUPPLEMENTARY INFORMATION:

History

On June 24, 2009, the FAA published in the **Federal Register** a notice of proposed rulemaking to establish Class D airspace at Grand Prairie Municipal Airport, Grand Prairie, TX. (74 FR 30023, Docket No. FAA–2009–0363). Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received. Class D airspace designations are published in paragraph 5000 of FAA Order 7400.9S signed October 3, 2008, and effective October 31, 2008, which is incorporated by reference in 14 CFR Part 71.1. The Class D airspace designations listed in this document will be published subsequently in the Order.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) part 71 by establishing Class D airspace extending upward from the surface up to but not including 2,000 feet MSL for IFR operations at Grand Prairie Municipal Airport, Grand Prairie, TX, for the safety and management of IFR operations.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes