

DEPARTMENT OF TRANSPORTATION**Pipeline and Hazardous Materials Safety Administration**

[Docket No. PHMSA-2005-21159, Notice No. 04]

Safety Advisory: Unauthorized Marking of Compressed Gas Cylinders

AGENCY: Pipeline and Hazardous Materials Safety Administration (PHMSA), DOT.

ACTION: Safety advisory notice.

SUMMARY: This is to notify the public that PHMSA is investigating the unauthorized marking of high- and low-pressure compressed gas cylinders, including fire extinguishers, oxygen cylinders, and self-contained breathing apparatus, by All-Out Fire Equipment Co., Inc. The company is located at 385 High Street, Holbrook, NY. On June 15, 2004, two inspectors from the Office of Hazardous Materials Enforcement (OHME—Eastern Region) conducted a compliance inspection of All-Out Fire Equipment Co., Inc. During the inspection, PHMSA obtained evidence that All-Out Fire Equipment Co., Inc. had marked, certified, and returned to service an undetermined number of cylinders as being properly tested in accordance with the Hazardous Materials Regulations (HMR), without conducting the required hydrostatic testing of those cylinders.

All-Out Fire Equipment Co., Inc.'s retest records revealed that, from November 2003 through June 2004, All-Out Fire Equipment Co., Inc. had returned to service hundreds of cylinders without hydrostatically testing them. In addition, PHMSA found no records of hydrostatic testing for cylinders All-Out Fire Equipment Co., Inc. had requalified prior to November 2003. This and other evidence obtained by PHMSA indicates that All-Out Fire Equipment Co., Inc. also failed to perform required hydrostatic testing on cylinders it requalified prior to November 2003.

Hydrostatic retesting and visual inspection, conducted as prescribed in the HMR, are used to verify the structural integrity of a cylinder. If the hydrostatic retesting and visual inspection are not performed in accordance with the HMR, a cylinder with compromised structural integrity may be returned to service when it should have been condemned in the first place. Extensive property damage, serious personal injury, or death could result from rupture of a cylinder. Cylinders that have not been retested in accordance with the HMR may not be

charged or filled with compressed gas or other hazardous material.

FOR FURTHER INFORMATION CONTACT:

Chris Michalski, Senior Inspector, Office of Hazardous Materials Enforcement, Pipeline and Hazardous Materials Safety Administration, U.S. Department of Transportation, 820 Bear Tavern Road, Suite 306, West Trenton, NJ 08626. Telephone: (609) 989-2256, Fax: (609) 989-2277.

SUPPLEMENTARY INFORMATION: Through its inspection, PHMSA has determined that All-Out Fire Equipment Co., Inc. marked and certified an undetermined number of cylinders as having been properly tested in accordance with the HMR, without actually retesting the cylinders. During the inspection, All-Out Fire Equipment Co., Inc. was unable to calibrate its test equipment. In addition, All-Out Fire Equipment Co., Inc. failed to keep complete records of its retest and re-inspections; thus, it is impossible to determine the number of cylinders that All-Out Fire Equipment Co., Inc. has improperly re-certified. These cylinders pose a potential safety risk to the public.

The cylinders in question are stamped with the following RIN: A261. The markings appear in the following pattern:

A 2
M Y
1 6

M is the month of retest (e.g. 10), and Y is the year of the retest (e.g. 01).

Anyone who has a cylinder that has been serviced by All-Out Fire Equipment Co., Inc. and that is marked with RIN number A261 should consider the cylinder unsafe and not fill it with a hazardous material unless the cylinder is first properly retested by a DOT-authorized retest facility. Filled cylinders (if filled with an atmospheric gas) described in this safety advisory should be vented or otherwise safely discharged and then taken to a DOT-authorized cylinder retest facility for proper retest to determine compliance with the HMR and their suitability for continuing service. Under no circumstance should a cylinder described in this safety advisory be filled, refilled, or used for its intended purpose until it is re-inspected and retested by a DOT-authorized retest facility.

It is further recommended that persons finding or possessing a cylinder or cylinders described in this safety advisory contact Inspector Michalski for additional information. The inspector can also provide a list of authorized retest facilities in your area or you may

obtain such a list at the following Web site: <http://hazmat.dot.gov>.

Issued in Washington, DC on September 9, 2005.

Robert A. McGuire,

Associate Administrator for Hazardous Materials Safety.

[FR Doc. 05-18275 Filed 9-13-05; 8:45 am]

BILLING CODE 4910-06-P

DEPARTMENT OF THE TREASURY**Submission for OMB Review; Comment Request**

September 7, 2005.

The Department of the Treasury has submitted the following public information collection requirement(s) to OMB for review and clearance under the Paperwork Reduction Act of 1995, Public Law 104-13. Copies of the submission(s) may be obtained by calling the Treasury Bureau Clearance Officer listed. Comments regarding this information collection should be addressed to the OMB reviewer listed and to the Treasury Department Clearance Officer, Department of the Treasury, Room 11000, 1750 Pennsylvania Avenue, NW., Washington, DC 20220.

Dates: Written comments should be received on or before October 14, 2005 to be assured of consideration.

Internal Revenue Service (IRS)

OMB Number: 1545-1008.

Type of Review: Revision.

Title: Passive Activity Loss Limitations.

Form: IRS form 8582.

Description: Under Internal Revenue Code section 469, losses from passive activities, to the extent that they exceed income from passive activities, cannot be deducted against nonpassive income. Form 8582 is used to figure the passive activity loss allowed and the loss to be reported on the tax return.

Respondents: Individuals or Households, Business or other-for-profit and Farms.

Estimated Total Burden Hours: 17,435,949 hours.

OMB Number: 1545-0126.

Type of Review: Revision.

Title: U.S. Income Tax Return of a Foreign Corporation.

Form: IRS form 1120-F.

Description: Form 1120-F is used by foreign corporations that have

investments, or a business or a branch in the U.S. The IRS uses Form 1120-F to determine if the foreign corporation has correctly reported its income, deductions and tax, and to determine if it has paid the correct amount of tax.

Respondents: Business or other for-profit.

Estimated Total Burden Hours: 4,793,792 hours.

OMB Number: 1545-1518.

Type of Review: Extension.

Title: HSA, Archer MSA or Medicare Advantage MSA Information.

Form: IRS form 5498-SA.

Description: Section 220(h) requires trustees to report to the IRS and medical savings accountholders contributions to and the year-end fair market value of any contributions made to a medical savings account (MSA). Congress requires Treasury to report to them the total contributions made to an MSA for the current tax year. Section 1201 of the Medicare prescription Drug, Improvement and Modernization Act of 2003 (Pub. L. 108-173) created new Code section 223 and section 223(h) requires the reporting of contributions to and the year-end fair market value of health savings accounts for tax years beginning after December 21, 2003.

Respondents: Business or other for-profit.

Estimated Total Burden Hours: 6,988 hours.

OMB Number: 1545-1793.

Type of Review: Extension.

Title: Rev. Proc. 2002-43

Determination of Substitute Agent for a Consolidated Group.

Description: The information is needed in order for (i) a terminating common parent of a consolidated group to notify the IRS that it will terminate and to designate another corporation to be the group's substitute agent, pursuant to Treas. Reg. Section 1.1502-77(d)(1) or Section 1.1502-77A(d); (ii) the remaining members of a consolidated group to designate a substitute agent pursuant to section 1.1502-77(d); (iii) the default substitute agent to notify the IRS that it is the default substitute agent pursuant to section 1.1502-77(d)(2); or (iv) requests by a member of the group for the IRS to designate a substitute agent or replace a previously designated substitute agent. The IRS will use the information to determine whether to approve the designation (if approval is required), to designate a substitute agent, or to replace a substitute agent, and to change the IRS records to reflect the name and other information about the substitute agent.

Respondents: Business or other for-profit.

Estimated Total Burden Hours: 400 hours.

OMB Number: 1545-1941.

Type of Review: Extension.

Title: Consumer Cooperative Exemption Application.

Form: IRS form 3491.

Description: A cooperative uses Form 3491 to apply for exemption from filing information returns (Form 1099-PATR) on patronage distributions of \$10 or more to any person during the calendar year.

Respondents: Business or other for-profit, Individuals or households and Farms.

Estimated Total Burden Hours: 148 hours.

Clearance Officer: Glenn P. Kirkland (202) 622-3428; Internal Revenue Service, Room 6516, 1111 Constitution Avenue, NW., Washington, DC 20224.

OMB Reviewer: Alexander T. Hunt (202) 395-7316; Office of Management and Budget, Room 10235, New Executive Office Building, Washington, DC 20503.

Michael A. Robinson,

Treasury PRA Clearance Officer.

[FR Doc. 05-18183 Filed 9-13-05; 8:45 am]

BILLING CODE 4830-01-P

DEPARTMENT OF THE TREASURY

Submission for OMB Review; Comment Request

September 7, 2005.

The Department of Treasury has submitted the following public information collection requirement(s) to OMB for review and clearance under the Paperwork Reduction Act of 1995, Public Law 104-13. Copies of the submission(s) may be obtained by calling the Treasury Bureau Clearance Officer listed. Comments regarding this information collection should be addressed to the OMB reviewer listed and to the Treasury Department Clearance Officer, Department of the Treasury, Room 11000, 1750 Pennsylvania Avenue, NW., Washington, DC 20220.

Dates: Written comments should be received on or before October 14, 2005 to be assured of consideration. Financial Crimes Enforcement Network (FinCEN)

OMB Number: 1506-0022.

Type of Review: Extension.

Title: Customer Identification Programs for Future Commission Merchants and Introducing Brokers.

Description: Section 326 of the USA PATRIOT Act added a subsection (1) to 31 U.S.C. 5318 of the Bank Secrecy Act that requires the Secretary of Treasury

to require financial institutions to establish and maintain programs to verify the identity of customers opening an account. FinCEN has adopted such rules for Futures Commission Merchants and Introducing Brokers.

Respondents: Business or other for-profit.

Estimated Total Reporting Burden: 20,471 hours.

Clearance Officer: Russell Stephenson, (202) 354-6012, Financial Crimes Enforcement Network, Suite 200, 2070 Chain Bridge Road, Vienna, VA 22182.

OMB Reviewer: Alexander T. Hunt, (202) 395-7316, Office of Management and Budget, Room 10235, New Executive Office Building, Washington, DC 20503.

Michael A. Robinson,

Treasury PRA Clearance Officer.

[FR Doc. 05-18184 Filed 9-13-05; 8:45 am]

BILLING CODE 4810-02-P

DEPARTMENT OF THE TREASURY

Public Meeting of the President's Advisory Panel on Federal Tax Reform

AGENCY: Department of the Treasury.

ACTION: Change in meeting date.

SUMMARY: This notice advises all interested persons of change in the date of a public meeting of the President's Advisory Panel on Federal Tax Reform.

DATES: This meeting scheduled to be held on Friday, September 23, 2005, has been postponed. This meeting will be rescheduled and announced at a later date.

FOR FURTHER INFORMATION CONTACT: The Panel staff at (202) 927-2TAX (927-2829) (not a toll-free call) or e-mail info@taxreformpanel.gov (please do not send comments to this box). Additional information is available at <http://www.taxreformpanel.gov>.

Dated: September 12, 2005.

Mark S. Kaizen,

Designated Federal Officer.

[FR Doc. 05-18356 Filed 9-13-05; 8:45 am]

BILLING CODE 4811-33-M