1319, 1338, 1354, 1374, 1378, 1445, 1470, 1498, 1513, 1546, 1632, 1736, 1766, 1846, 1849, 2002 through 2009 inclusive, 2011, 2013 through 2016 inclusive, 2019, 2020, or 2022, on any Model CL-600-2B19 airplane.

(3) As of the effective date of this AD: It is acceptable to replace an HSTA P/N 601R92305–1 (vendor P/N 8396–2), P/N 601R92305–3 (vendor P/N 8396–3), or P/N 601R92305–5 (vendor P/N 8396–4) with an HSTA having P/N 601R92305–5 (vendor P/N 8396–4) that is not identified in paragraph (1)(2) of this AD, provided the actions required by paragraph (j)(2) of this AD are accomplished within the compliance time specified in that paragraph.

(m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE–170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(n) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF–2013–14, dated June 4, 2013, for related information. This MCAI may be found in the AD docket on the Internet at http://www.regulations.gov/ #!documentDetail;D=FAA-2014-1049-0002.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (o)(3) and (o)(4) of this AD.

(o) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.
- (i) Bombardier Service Bulletin 601R–27– 161, Revision A, dated January 30, 2014.

- (ii) Supplement 23, "Horizontal Stabilizer Trim Check," of Chapter 7 "Supplements," of Bombardier CL–600–2B19 Airplane Flight Manual CSP A–012, Volume 3, Revision 61, dated April 2, 2013.
- (iii) Task C27–40–103–04, "Operational Check (ground maintenance test) of the horizontal stabilizer trim control unit," in Bombardier CL–600–2B19 Temporary Revision 2A–56, dated June 4, 2012, to Appendix A, Certification Maintenance Requirements, of Part 2, Airworthiness Requirements, of the Bombardier CL–600–2B19 Maintenance Requirements Manual.
- (3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–5000; fax 514–855–7401; email thd.crj@aero.bombardier.com; Internet http://www.bombardier.com
- (4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.
- (5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http://www.archives.gov/federal-register/cfr/ibrlocations.html.

Issued in Renton, Washington, on December 23, 2015.

John P. Piccola, Jr.,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 2015–33288 Filed 1–12–16; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2015-4514; Airspace Docket No. 15-AEA-9]

Amendment of Class E Airspace for the Following New York Towns: Elmira, NY; Ithaca, NY; Poughkeepsie, NY

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule; technical amendment, withdrawal.

SUMMARY: This action withdraws a Final rule; technical amendment published in the Federal Register on November 30, 2015, amending Class E airspace at Elmira/Corning Regional Airport, Elmira, NY; Ithaca Tompkins Regional Airport, Ithaca, NY; and Duchess County Airport, Poughkeepsie, NY is being withdrawn. The FAA has determined that withdrawal of the final rule is warranted as additional analysis is needed.

DATES: Effective 0901 UTC. As of January 13, 2016 the final rule; technical amendment published November 30, 2015, at 80 FR 74676, is withdrawn.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305–6364.

SUPPLEMENTARY INFORMATION:

History

On November 30, 2015, the FAA published in the **Federal Register** a final rule, technical amendment to amend Class E airspace at Elmira/Corning Regional Airport, Elmira, NY; Ithaca Tompkins Regional Airport, Ithaca, NY; and Duchess County Airport, Poughkeepsie, NY. (80 FR 74676). Docket No. FAA–2015–4514. Subsequent to publication the FAA found errors in the airspace descriptions that now need further analysis. Therefore, the final rule is being withdrawn.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Withdrawal

In consideration of the foregoing, the final rule technical amendment for FR Doc. FAA–2015–4514, Airspace Docket No. 15–AEA–9 as published in the **Federal Register** of November 30, 2015 (80 FR 74676) (FR Doc. 2015–30187), is hereby withdrawn.

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

Issued in College Park, Georgia, on December 18, 2015.

Ryan W. Almasy

Acting Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.

[FR Doc. 2016–00172 Filed 1–12–16; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

RIN 2120-AA65

[Docket No. FAA-2015-8761]

Amendment of Authority Citation for Standard Instrument Procedures

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.