2018 (the effective date of this AD), then only paragraph (h)(2) of this AD applies.

(g) Determine Number of Affected Pitot Probes Installed

Within 30 days after March 16, 2018 (the effective date of this AD), inspect the airplane to determine the number of pitot probes identified in paragraph (c)(1) of this AD that are installed on the airplane. This inspection can be performed through a review of maintenance records in lieu of a physical inspection of the product if the serial number and repair date can be positively identified from the review. If the serial number cannot be positively identified from a review of the aircraft's maintenance records or from the outside of the airplane, this may require the pitot probe to be removed from the fuselage to view the serial number at the inner base of the probe. If it is determined that no more than one pitot probe identified in paragraph (c)(1) of this AD is installed on the airplane, no further action is required except for the ongoing requirement in paragraph (h)(2) of this AD.

(h) Replace Affected Pitot Probes

- (1) If it is determined that more than one pitot probe identified in paragraph (c)(1) of this AD is installed on the airplane during the inspection required in paragraph (g) of this AD, within the next 2 months after March 16, 2018 (the effective date of this AD), do one of the following so that no more than one pitot probe identified in paragraph (c)(1) of this AD is installed on any aircraft simultaneously.
- (i) Replace the pitot probes that are listed with pitot probes that do not have a serial number listed in paragraph (c)(1) of this AD; or
- (ii) Replace the pitot probes that are listed with one that has been properly repaired, and if repaired by CSI, has a repair date of August 1, 2014, or later. This can be done by having the existing pitot probe repaired by CSI Aerospace, Inc.
- (2) Ås of March 16, 2018 (the effective date of this AD), do not install on any airplane a pitot probe having a serial number listed in paragraph (c)(1) of this AD, unless it has been properly repaired, and if repaired by CSI Aerospace, Inc., has a repair date of August 1, 2014, or later.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Fort Worth ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO Branch, send it to the attention of the person identified in paragraph (j) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact Jonathan Kim, Aerospace Engineer,

Fort Worth ACO Branch, FAA, 10101 Hillwood Parkway, Fort Worth, Texas 76177– 1524; telephone: (817) 222–5131; fax: (817) 222–5245; email: jonathan.kim@faa.gov.

Issued in Kansas City, Missouri, on February 2, 2018.

Melvin J. Johnson,

 $\label{eq:policy} \textit{Deputy Director, Policy & Innovation Division,} \\ \textit{Aircraft Certification Service.}$

[FR Doc. 2018-02550 Filed 2-8-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2017-0279; Airspace Docket No. 17-ASO-10]

Establishment of Class E Airspace; Johnson City, TN

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class E airspace extending upward from 700 feet above the surface at Johnson City, TN, to accommodate new area navigation (RNAV) global positioning system (GPS) standard instrument approach procedures (SIAPs) serving Johnson City Medical Center Heliport. Controlled airspace is necessary for the safety and management of instrument flight rules (IFR) operations at the heliport.

DATES: Effective 0901 UTC, March 29, 2018. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11B, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/ air traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11B at NARA, call (202) 741–6030, or go to *https://* www.archives.gov/federal-register/cfr/ ibr-locations.html.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305–6364.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes Class E airspace at Johnson City Medical Center Heliport, Johnson City, TN, to support IFR operations under standard instrument approach procedures at the heliport.

History

The FAA published a notice of proposed rulemaking in the Federal Register (82 FR 24268, May 26, 2017) for Docket No. FAA—2017—0279 to establish Class E airspace extending upward from 700 feet above the surface at Johnson City Medical Center Heliport, Johnson City, TN, due to the new RNAV (GPS) standard instrument approach procedures for IFR operations at the heliport. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.11B dated August 3, 2017, and effective September 15, 2017, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

Availability and Summary of Documents for Incorporation by Reference

This document proposes to amend FAA Order 7400.11B, Airspace Designations and Reporting Points, dated August 3, 2017, and effective September 15, 2017. FAA Order 7400.11B is publicly available as listed in the ADDRESSES section of this

document. FAA Order 7400.11B lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) part 71 by establishing Class E airspace extending upward from 700 feet above the surface within a 6.5-mile radius of Johnson City Medical Center Heliport, Johnson City, TN. This action provides the controlled airspace required to support the new RNAV (GPS) standard instrument approach procedures for IFR operations at Johnson City Medical Center Heliport.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5–6.5a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the FAA amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.11B, Airspace Designations and Reporting Points, dated August 3, 2017, effective September 15, 2017, is amended as follows:

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.

ASO KY E5 Johnson City, TN [New]

Johnson City Medical Center Heliport, TN (Lat. 36°18′26″ N, long. 82°23′10″ W)

That airspace extending upward from 700 feet above the surface within a 6.5-mile radius of Johnson City Medical Center Heliport.

Issued in College Park, Georgia, on January 30, 2018.

Ryan W. Almasy,

Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization. [FR Doc. 2018–02324 Filed 2–8–18; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2017-0897; Airspace Docket No. 17-ANM-22]

Establishment of Class E Airspace, Spanish Fork, UT

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class E airspace extending upward from 700 feet above the surface, at Spanish Fork Airport Springville-Woodhouse Field, Spanish Fork, UT, to accommodate new area navigation (RNAV) procedures at the airport. This action ensures the safety and management of Instrument Flight Rules (IFR) operations within the National Airspace System.

DATES: Effective 0901 UTC, March 29, 2018. The Director of the Federal Register approves this incorporation by reference action under Title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11B, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to https://www.archives.gov/federal-register/cfr/ibr-locations.html.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: Tom Clark, Federal Aviation Administration, Operations Support Group, Western Service Center, 2200 S 216th Street, Des Moines, WA 98198–6547; telephone (206) 223–2253.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes Class E airspace extending upward from 700 feet above the surface at Spanish Fork Airport Springville-Woodhouse Field, Spanish Fork, UT, to support standard instrument approach procedures for IFR operations at the airport.

History

The FAA published a notice of proposed rulemaking in the **Federal Register** (82 FR 55965; November 27, 2017) for Docket No. FAA–2017–0897 to establish Class E airspace extending upward from 700 feet above the surface at Spanish Fork Airport Springville-Woodhouse Field, Spanish Fork, UT. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005 of FAA