

B. Regulatory Impact Analysis: E.O. 12866

The MSPB has determined that this is not a significant regulatory action under E.O. 12866. Therefore, no regulatory impact analysis is required.

C. Regulatory Flexibility Act

The Regulatory Flexibility Act (RFA) requires an agency to prepare a regulatory flexibility analysis for rules unless the agency certifies that the rule will not have a significant economic impact on a substantial number of small entities. The RFA applies only to rules for which an agency is required to first publish a proposed rule. See 5 U.S.C. 603(a) and 604(a). As discussed above, the 2015 Act does not require agencies to first publish a proposed rule when adjusting CMPs within their jurisdiction. Thus, the RFA does not apply to this final rule.

D. Paperwork Reduction Act

This document does not contain information collection requirements subject to the Paperwork Reduction Act of 1995, Public Law 104–13 (44 U.S.C. Chapter 35).

List of Subjects in 5 CFR Part 1201

Administrative practice and procedure, Civil rights, Government employees.

For the reasons set forth above, 5 CFR part 1201 is amended as follows:

PART 1201—PRACTICES AND PROCEDURES

- 1. The authority citation for part 1201 continues to read as follows:

Authority: 5 U.S.C. 1204, 1305, and 7701, and 38 U.S.C. 4331, unless otherwise noted.

§ 1201.126 [Amended]

- 2. Section 1201.126 is amended in paragraph (a) by removing “\$1,066” and adding in its place “\$1,093.”

Jennifer Everling,
Acting Clerk of the Board.

[FR Doc. 2019–03018 Filed 2–21–19; 8:45 am]

BILLING CODE 7400–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2018–0508; Product Identifier 2018–NM–012–AD; Amendment 39–19563; AD 2019–03–11]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Airbus SAS Model A350–941 and –1041 airplanes. This AD was prompted by a determination that more restrictive maintenance requirements and airworthiness limitations are necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive maintenance requirements and airworthiness limitations. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 29, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 29, 2019.

ADDRESSES: For service information identified in this final rule, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email *continued-airworthiness.a350@airbus.com*; internet *http://www.airbus.com*. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available on the internet at *http://www.regulations.gov* by searching for and locating Docket No. FAA–2018–0508.

Examining the AD Docket

You may examine the AD docket on the internet at *http://www.regulations.gov* by searching for and locating Docket No. FAA–2018–0508; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other

information. The address for Docket Operations (phone: 800–647–5527) is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3218.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus SAS Model A350–941 airplanes. The NPRM published in the **Federal Register** on June 11, 2018 (83 FR 26884). The NPRM was prompted by a determination that more restrictive maintenance requirements and airworthiness limitations are necessary. The NPRM proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive maintenance requirements and airworthiness limitations.

We issued a supplemental NPRM (SNPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus SAS Model A350–941 and –1041 airplanes. The SNPRM published in the **Federal Register** on November 6, 2018 (83 FR 55496). We issued the SNPRM because the service information referenced in the NPRM had been further revised to include new or more restrictive maintenance requirements and airworthiness limitations. We also revised the applicability of the proposed AD by adding Airbus SAS Model A350–1041 airplanes.

We are issuing this AD to address safety-significant latent failures that would, in combination with one or more other specific failures or events, result in a hazardous or catastrophic failure condition.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018–0179, dated August 23, 2018, to correct an unsafe condition on all Airbus SAS Model A350–941 and –1041 airplanes. EASA AD 2018–0179 states:

Certification Maintenance Requirements (CMR) for the Airbus A350, which are approved by EASA, are currently defined and published in the Airbus A350 ALS [Airworthiness Limitations Section] Part 3 document. These instructions have been

identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

EASA previously issued AD 2018–0004 to require the actions as specified in Airbus A350 ALS Part 3 Revision 04.

Since this [EASA] AD was issued, Airbus published variation 4.2 of Airbus A350 ALS Part 3, to introduce new and more restrictive CMRs.

For the reason described above, this [EASA] AD requires accomplishment of the actions specified in the ALS.

EASA previously issued AD 2018–0004, dated January 9, 2018, to correct an unsafe condition on all Airbus SAS Model A350–941 airplanes. EASA AD 2018–0004 states:

Certification Maintenance Requirements (CMR) for the Airbus A350, which are approved by EASA, are currently defined and published in the Airbus A350 ALS Part 3 document. These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

EASA previously issued AD 2017–0029 to require the actions as specified in Airbus A350 ALS Part 3 Revision 03.

Since this [EASA] AD was issued, Airbus published Revision 04 of Airbus A350 ALS Part 3, to introduce new and more restrictive CMRs.

For the reason described above, this [EASA] AD retains the requirements of EASA AD 2017–0029, which is superseded, and requires accomplishment of the actions specified in the ALS.

EASA ADs 2018–0004 and 2018–0179 are collectively referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0508.

Comments

We gave the public the opportunity to participate in developing this final rule. The following presents the comment received on the SNPRM and the FAA’s response to that comment.

Support for the SNPRM

An anonymous commenter stated support for the SNPRM.

Request To Clarify the Cost of Compliance

The anonymous commenter wondered how the total cost of \$7,650 per worker was reached and expressed concern that the cost would create inefficient use of workers’ time if they are checking the airplane more than they should be.

From these statements, we infer that the commenter was requesting that we clarify the proposed Costs of Compliance. We agree to clarify the Costs of Compliance in this final rule. As we explained in the Costs of Compliance section, the cost estimate comes from the \$85 per work-hour labor rate multiplied by the 90 work-hours for incorporating the new, more restrictive maintenance requirements and airworthiness limitations into the operator’s maintenance or inspection program, although this figure may vary from operator to operator. In the past, we have estimated that this action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), we have determined that a per-operator estimate is more accurate than a per-airplane estimate. The cost does not include the estimated time for each inspection because this AD only requires revisions to certain operator maintenance documents to include new actions (e.g., inspections). Compliance with these actions is required by 14 CFR 91.403(c). We have not changed this final rule in this regard.

Conclusion

We reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the SNPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the SNPRM.

Related Service Information Under 1 CFR Part 51

Airbus has issued A350 Airworthiness Limitations Section (ALS) Part 3, Certification Maintenance Requirements (CMR), Revision 04, dated December 15, 2017, as supplemented by Airbus A350 ALS Part 3, Certification Maintenance Requirements (CMR), Variation 4.2, dated July 26, 2018. These documents describe mandatory maintenance requirements and airworthiness limitations that operators must perform at specified intervals. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

We estimate that this AD affects 11 airplanes of U.S. registry.

We estimate the following costs to comply with this AD. We have determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although this figure may vary from operator to operator. In the past, we have estimated that this action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), we have determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, we estimate the total cost per operator to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019–03–11 Airbus SAS: Amendment 39–19563; Docket No. FAA–2018–0508; Product Identifier 2018–NM–012–AD.

(a) Effective Date

This AD is effective March 29, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A350–941 and –1041 airplanes, certificated in any category, with an original certificate of airworthiness or original export certificate of airworthiness issued on or before July 26, 2018.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a determination that more restrictive maintenance requirements and airworthiness limitations are necessary. We are issuing this AD to address safety-significant latent failures that would, in combination with one or more other specific failures or events, result in a hazardous or catastrophic failure condition.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance or Inspection Program Revision

Within 90 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate Airbus A350 Airworthiness Limitations Section (ALS) Part 3, Certification Maintenance Requirements (CMR), Revision 04, dated December 15, 2017, as supplemented by Airbus A350 ALS Part 3, Certification Maintenance Requirements (CMR), Variation 4.2, dated July 26, 2018. The initial compliance time for accomplishing the actions is at the applicable times specified in Airbus A350 Airworthiness Limitations Section (ALS) Part 3, Certification Maintenance Requirements (CMR), Revision 04, dated December 15, 2017, as supplemented by Airbus A350 ALS Part 3, Certification Maintenance Requirements (CMR), Variation 4.2, dated July 26, 2018; or within 90 days after the effective date of this AD; whichever occurs later.

(h) No Alternative Actions or Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals, may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (i)(1) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* If any service information contains procedures or

tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018–0179, dated August 23, 2018; and EASA AD 2018–0004, dated January 9, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0508.

(2) For more information about this AD, contact Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3218.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus A350 Airworthiness Limitations Section (ALS) Part 3, Certification Maintenance Requirements (CMR), Revision 04, dated December 15, 2017.

(ii) Airbus A350 ALS Part 3, Certification Maintenance Requirements (CMR), Variation 4.2, dated July 26, 2018.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email continued-airworthiness.a350@airbus.com; internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on February 7, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–02924 Filed 2–21–19; 8:45 am]

BILLING CODE 4910–13–P