FAA-2023-2003; Project Identifier AD-2022-01620-T.

(a) Effective Date

This airworthiness directive (AD) is effective July 19, 2024.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 757–200, –200PF, –200CB, and –300 series airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 757–25A0319 RB, dated March 24, 2023.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

(e) Unsafe Condition

This AD was prompted by reports that operators have found, on multiple aircraft, frequent and severe damage to the blowout vent grilles throughout the lower lobe cargo compartment. The FAA is issuing this AD to address damage to the blowout vent grilles in the forward and aft lower lobe cargo compartments that could lead to latent failure of the decompression panels and pressure equalization valves. This latent failure, in combination with a fire, could make the cargo fire protection, detection, suppression, and containment system ineffective. Also, this latent failure, in combination with rapid decompression of the airplane, could prevent activation of the station (STA) 1640 decompression panels, which could damage the STA 1640 floor beam and cause loss of hydraulic systems components and flight control and damage to the auxiliary power unit (APU) fuel line. This unsafe condition, if not addressed, could result in the inability of the flightcrew to maintain safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 757–25A0319 RB, dated March 24, 2023, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757–25A0319 RB, dated March 24, 2023.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 757–25A0319, dated March 24, 2023, which is referred to in Boeing Alert Requirements Bulletin 757–25A0319 RB, dated March 24, 2023.

(h) Exceptions to Service Information Specifications

(1) For all airplanes: Where the Compliance Time columns of the tables in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 757–25A0319 RB,

- dated March 24, 2023, refer to the original issue date of Requirements Bulletin 757–25A0319 RB, this AD requires using the effective date of this AD.
- (2) For Groups 1, 2, and 4 airplanes identified in Boeing Alert Requirements Bulletin 757-25A0319 RB, dated March 24, 2023, that have been converted from a passenger to freighter configuration in accordance with VT Mobile Aerospace Engineering (MAE) Inc. Supplemental Type Certificate (STC) ST04242ÅT or STC ST03562AT or Precision Conversions LLC STC ST01529SE: Where the Compliance Time columns of tables 1, 2, 3, and 5 in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 757–25A0319 RB, dated March 24, 2023, specify "Within 5,425 Flight Hours" and "Within 16 months," this AD requires replacing that text with "Within 9,000 Flight Hours" and "Within 36
- months," respectively.
 (3) For Group 6 airplanes identified in Boeing Alert Requirements Bulletin 757–25A0319 RB, dated March 24, 2023: Where the Compliance Time column of table 7 in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 757–25A0319 RB, dated March 24, 2023, specifies "Within 5,425 Flight Hours" and "Within 16 months," this AD requires replacing that text with "Within 9,000 Flight Hours" and "Within 36 months," respectively.

(i) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, AIR–520 Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: AMOC@ faa.gov.
- (2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.
- (3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–520 Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

- (1) For more information about this AD, contact Katherine Venegas, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone: 562–627–5353; email: Katherine.Venegas@faa.gov.
- (2) Service information identified in this AD that is not incorporated by reference is available at the address specified in paragraph (k)(3) of this AD.

(k) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.
- (i) Boeing Alert Requirements Bulletin 757–25A0319 RB, dated March 24, 2023.
 - (ii) [Reserved]
- (3) For service information, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website *myboeingfleet.com*.
- (4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.
- (5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on May 23, 2024.

Suzanne Masterson,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service

[FR Doc. 2024–13014 Filed 6–13–24; 8:45 am] **BILLING CODE 4910–13–P**

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2023-2503; Airspace Docket No. 20-AGL-14]

RIN 2120-AA66

Establishment of Class E Airspace; Desmet, SD

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class E airspace at Desmet, SD. This action is due to the development of new public instrument procedures and to support instrument flight rule (IFR) operations.

DATES: Effective 0901 UTC, September 5, 2024. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: A copy of the Notice of Proposed Rulemaking (NPRM), all comments received, this final rule, and

all background material may be viewed online at www.regulations.gov using the FAA Docket number. Electronic retrieval help and guidelines are available on the website. It is available 24 hours each day, 365 days each year.

FAA Order JO 7400.11H, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at www.faa.gov/air_traffic/publications/. You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington DC 20591; telephone: (202) 267–8783.

FOR FURTHER INFORMATION CONTACT:

Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222–5711.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I. Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes Class E airspace extending upward from 700 feet above the surface at Wilder Airport, Desmet, SD, to support IFR operations at this airport.

History

The FAA published an NPRM for Docket No. FAA–2023–2503 in the **Federal Register** (88 FR 88552; December 22, 2023) proposing to establish Class E airspace at Desmet, SD. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Incorporation by Reference

Class E airspace designations are published in paragraph 6005 of FAA Order JO 7400.11, Airspace Designations and Reporting Points, which is incorporated by reference in 14 CFR 71.1 on an annual basis. This document amends the current version of that order, FAA Order JO 7400.11H, dated August 11, 2023, and effective

September 15, 2023. FAA Order JO 7400.11H is publicly available as listed in the **ADDRESSES** section of this document. These amendments will be published in the next update to FAA Order JO 7400.11.

FAA Order JO 7400.11H lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This amendment to 14 CFR part 71 establishes Class E airspace extending upward from 700 feet above the surface to within a 7-mile radius of Wilder Airport, Desmet, SD.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5–6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

Lists of Subjects in 14 CFR 71

Airspace, Incorporation by reference, Navigation (air).

The Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order JO 7400.11H, Airspace Designations and Reporting Points, dated August 11, 2023, and effective September 15, 2023, is amended as follows:

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.

AGL SD E5 Desmet, SD [Establish]

Wilder Airport, SD

(Lat 44°25′59" N, long 97°33′29" W)

That airspace extending upward from 700 feet above the surface within a 7-mile radius of Wilder Airport.

Issued in Fort Worth, Texas, on June 11,

Steven T. Phillips,

Acting Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2024–13132 Filed 6–13–24; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2024-0632; Airspace Docket No. 24-ANE-2]

RIN 2120-AA66

Amendment of Class E Airspace; Nashua, NH

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends Class E airspace extending upward from the surface for Boire Field Airport, Nashua, NH, by replacing the reference to Manchester Very High-Frequency Omnidirectional Range (VOR)/Distance Measuring Equipment (DME). This action does not change the airspace boundaries or operating requirements.

DATES: Effective 0901 UTC, September 5, 2024. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: A copy of the Notice of Proposed Rulemaking (NPRM), all comments received, this final rule, and all background material may be viewed