

the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends § 39.13 by adding a new airworthiness directive (AD) to read as follows:

PILATUS BRITTEN-NORMAN LTD.: Docket No. 2000-CE-47-AD

(a) *What airplanes are affected by this AD?* This AD affects the following Model BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T, BN-2T-4R, BN2A MK. III, BN2A MK. III-2, and BN2A MK. III-3 airplanes, all serial numbers, that are certificated in any category.

(b) *Who must comply with this AD?*

Anyone who wishes to operate any of the above airplanes must comply with this AD.

(c) *What problem does this AD address?*

The actions specified by this AD are intended to detect and correct loosening of the throttle friction adjustment beyond its normal limits. Such a condition could lead to damage to the throttle friction-adjuster or the retaining washer and split pin. This could allow the throttle quadrant shaft to laterally shift and impede the operation of the engine controls.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Actions	Compliance	Procedures
(1) Inspect the throttle friction-shaft for damage. Replace the split pin and washer.	Inspect within 100 hours time-in-service (TIS) after the effective date of this AD, and thereafter at intervals not to exceed 100 hours TIS. Accomplish the replacements prior to further flight after each inspection.	In accordance with the PROCEDURES section of BN Service Bulletin BN2/SB.272, dated July 2000.
(2) If damage is found on the throttle friction-shaft, replace the shaft.	Before further flight after each inspection where damage is found.	In accordance with the PROCEDURES section of BN Service Bulletin BN2/SB.272, dated July 2000.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 1: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *How do I get copies of the documents referenced in this AD?* You may obtain copies of the documents referenced in this AD from Pilatus Britten-Norman Limited, Bembridge,

Isle of Wight, United Kingdom PO35 5PR. You may examine these documents at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Note 2: The subject of this AD is addressed in British AD 003-07-2000, dated August 22, 2000.

Issued in Kansas City, Missouri, on October 26, 2001.

James E. Jackson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-27653 Filed 11-6-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA 2001-10666; Airspace Docket No. ASD 01-ASW-12]

Proposed Revision of Jet Route

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to revise that segment of Jet Route 180 (J-180) between the Daisetta, TX, Very High Frequency Omnidirectional Range/Tactical Air Navigation (VORTAC) and the Little Rock, AR, VORTAC by moving the route to the east over the new Sawmill, LA, VORTAC. The FAA is proposing this action to enhance aviation safety and the management of the aircraft operations in the Texas area.

DATES: Comments must be received on or before December 24, 2001.

ADDRESSES: Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket numbers FAA-2001-10666/Airspace Docket No. ASD 01-ASW-12 at the beginning of your comments.

You may also submit comments through the Internet to <http://dms.dot.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Dockets Office (telephone 1-800-647-5527) is on the plaza level of the NASSIF Building at the Department of Transportation at the above address.

An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division, Federal Aviation Administration, 2601 Meacham Blvd, Fort Worth, TX 76193-0500.

FOR FURTHER INFORMATION CONTACT: Steve Rohring, Airspace and Rules Division, ATA-400, Office of Air Traffic Airspace Management, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Nos. FAA 2001-10666/Airspace Docket No. ASD 01-ASW-12." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of comments received. All comments submitted will be available for examination in the Rules Docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration, Office of Air Traffic Airspace Management, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers of this NPRM. Persons interested in being placed on a mailing list for future NPRM's should call the FAA's Office of Rulemaking, (202) 267-9677, for a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

Background

The FAA is redesigning the nation's airspace to reduce the volume of air traffic operations in certain congested areas commonly referred to as "choke-

points." As part of this effort, the FAA believes that revising the affected segment of J-180 to reroute it over the new Sawmill, LA, VORTAC will alleviate air traffic congestion in specific "choke-point" areas. The FAA is therefore proposing this action to enhance air safety and the expeditious movement of aircraft through the area.

The Proposal

The FAA is proposing an amendment to 14 CFR part 71 to revise a segment of J-180 between the Daisetta, TX, VORTAC and the Little Rock, AR, VORTAC by moving the route eastward over the new Sawmill, LA, VORTAC. This action is necessary to support the national airspace redesign project to reduce air traffic congestion in identified choke-point" areas.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Jet routes are published in paragraph 2004 of FAA Order 7400.9J dated August 31, 2001, and effective September 16, 2001, which is incorporated by reference in 14 CFR 71.1. The jet route listed in this document would be published subsequently in the Order.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E, AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9J, Airspace Designations and Reporting Points, dated August 31, 2001, and effective September 16, 2001, is amended as follows:

Paragraph 2004—Jet Routes

* * * * *

J-180 [Revised]

From Humble, TX; Daisetta, TX; Sawmill, LA; Little Rock, AR.

* * * * *

Issued in Washington, DC, on November 1, 2001.

Reginald C. Matthews,

Manager, Airspace and Rules Division.

[FR Doc. 01-28001 Filed 11-6-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2001-9813; Airspace Docket No. 00-AWA-7]

RIN 2120-AA66

Proposed Modification of the Memphis Class B Airspace Area; TN

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to modify the Memphis, TN, Class B airspace area. Specifically, this action proposes to reconfigure the sub-area boundaries, add one new sub-area, and lower the altitude floor in certain segments of the Memphis Class B airspace area. In addition, the FAA is proposing to describe the boundaries of the Memphis Class B airspace area using the Memphis Very High Frequency Omnidirectional Range Tactical Air Navigation (VORTAC) facility as the reference point. The FAA is proposing this action to more efficiently align the Memphis Class B airspace area to better accommodate simultaneous parallel instrument landing system (ILS) approach procedures and simultaneous intersecting runway operations. This change would improve the management of air traffic operations and enhance safety in the Memphis Class B airspace area while accommodating the concerns of airspace users.