# **Proposed Rules**

Federal Register

Vol. 68, No. 94

Thursday, May 15, 2003

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

#### FEDERAL ELECTION COMMISSION

11 CFR Parts 104, 107, 110, 9003, 9004, 9008, 9032 Through 9036, and 9038

[Notice 2003-10]

**Extension of Public Comment Period** for Public Financing of Presidential Candidates and Nominating Conventions

**AGENCY:** Federal Election Commission. **ACTION:** Proposed rule; reopening of public comment period.

**SUMMARY:** This notice extends the public comment period on the Federal Election Commission's notice of proposed rulemaking on public financing of presidential candidates and nominating conventions to May 23, 2003. The Commission will hold a hearing on the proposed rules on June 6, 2003, at 10

DATES: Comments must be received on or before May 23, 2003. The Commission will hold a hearing on the proposed rules for June 6, 2003, at 10 a.m., if it receives sufficient requests to testify. Commenters wishing to testify at the hearing must so indicate in their written or electronic comments.

ADDRESSES: All comments should be addressed to Ms. Mai T. Dinh, Acting Assistant General Counsel, and must be submitted in either electronic or written form. Electronic mail comments should be sent to pubfund2004@fec.gov and must include the full name, electronic mail address and postal service address of the commenter. Electronic mail comments that do not contain the full name, electronic mail address and postal service address of the commenter will not be considered. If the electronic mail comments include an attachment, the attachment must be in the Adobe Acrobat (.pdf) or Microsoft Word (.doc) format. Faxed comments should be sent to (202) 219-3923, with printed copy follow-up to ensure legibility. Written comments and printed copies of faxed comments should be sent to the Federal Election Commission, 999 E Street,

NW., Washington, DC 20463. Commenters are strongly encouraged to submit comments electronically to ensure timely receipt and consideration. The Commission will make every effort to post public comments on its Web site within 10 business days of the close of the comment period. The hearing will be held in the Commission's ninth floor

meeting room, 999 E Street, NW., Washington, DC.

FOR FURTHER INFORMATION CONTACT: J. Duane Pugh Jr., Senior Attorney, 999 E Street, NW., Washington, DC, 20463, (202) 694–1650 or (800) 424–9530.

SUPPLEMENTARY INFORMATION: The Federal Election Commission recently requested comment on proposed changes to its rules governing publicly financed presidential candidates, in both the primary and general elections, and national nominating conventions. See Notice of Proposed Rulemaking on Public Financing of Presidential Candidates and Nominating Conventions, 68 FR 18484 (Apr. 15, 2003) ("Public Financing NPRM"). The document states that the public comment period closed on May 9, 2003, and a hearing on the proposed rules was tentatively scheduled for May 19, 2003. On May 2, 2003, the United States District Court for the District of Columbia issued a decision in McConnell v. FEC, Civ. No. 02-582, 2003 WL 21003144 (D.D.C. May 1, 2003), notice of appeal filed (U.S. May 2, 2003), which addresses certain provisions of the Bipartisan Campaign Reform Act of 2002, Public Law 107-155, 116 Stat. 81 (Mar. 27, 2002). A portion of the notice of proposed rulemaking concerned the application of the Bipartisan Campaign Reform Act and the Commission's implementing regulations to national nominating conventions. See Public Financing NPRM, 68 FR at 18502-07. In order to permit commenters the opportunity to consider the McConnell v. FEC decision and its impact on national nominating conventions, the Commission is extending the comment period until May 23, 2003, and rescheduling the hearing on the proposed rules to June 6, 2003, at 10 a.m.

Dated: May 8, 2003.

# Ellen L. Weintraub,

Chair. Federal Election Commission. [FR Doc. 03-11978 Filed 5-14-03; 8:45 am] BILLING CODE 6715-01-P

### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 25

[Docket No. NM254; Notice No. 25-03-02-

Special Conditions: Cessna Model 680 Sovereign: Side Facing Single **Occupant Seats** 

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed special

conditions.

**SUMMARY:** This document proposes special conditions for the Cessna Model 680 Sovereign airplane. This airplane will have a novel or unusual design feature(s) associated with side-facing single-occupant seats. The applicable airworthiness regulations do not contain adequate or appropriate safety standards for this design feature. These proposed special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

**DATES:** Comments must be received on or before June 30, 2003.

**ADDRESSES:** Comments on this proposal may be mailed in duplicate to: Federal Aviation Administration, Transport Airplane Directorate, Attn: Rules Docket (ANM-113), Docket No. NM254, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; or delivered in duplicate to the Transport Airplane Directorate at the above address. Comments must be marked: Docket No. NM254. Comments may be inspected in the Rules Docket weekdays, except Federal holidays, between 7:30 a.m. and 4 p.m.

# FOR FURTHER INFORMATION CONTACT:

Mark Quam, FAA, Standardization Branch, ANM-113, Transport Airplane Directorate, Aircraft Certification Service, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2145, facsimile (425) 227–1149.

# SUPPLEMENTARY INFORMATION:

# **Comments Invited**

The FAA invites interested persons to participate in this rulemaking by submitting written comments, data, or views. The most helpful comments

reference a specific portion of the special conditions, explain the reason for any recommended change, and include supporting data. We ask that you send us two copies of written comments.

We will file in the docket all comments we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning these special conditions. The docket is available for public inspection before and after the comment closing date. If you wish to review the docket in person, go to the address in the ADDRESSES section of this preamble between 7:30 a.m. and 4 p.m., Monday through Friday, except Federal holidays.

We will consider all comments we receive on or before the closing date for comments. We will consider comments filed late if it is possible to do so without incurring expense or delay. We may change these special conditions in light of the comments we receive.

If you want the FAA to acknowledge receipt of your comments on this proposal, include with your comments a pre-addressed, stamped postcard on which the docket number appears. We will stamp the date on the postcard and mail it back to you.

#### **Background**

On November 24, 1999, Cessna Aircraft Company, One Cessna Boulevard, Wichita, KS 67277, applied for type certificate for their new Cessna Model 680 Sovereign airplane. The Model 680 Sovereign is a twin engine pressurized executive jet airplane with standard seating provisions for 12 passenger/crew and allowance for baggage and optional equipment. This airplane will have a maximum takeoff weight of 30,000 pounds with a wingspan of 63.1 feet and will have two aft-mounted Pratt & Whitney 306C engines.

Čessna Model 680 offers interior arrangements, which include singleoccupant side-facing seat installations. These seats are installed on the LH and RH side of the cabin's forward section, forward of and opposite to the entry door respectively. Dynamic testing of all seats approved for occupancy during takeoff and landing is required by 14 CFR 25.562. The pass/fail criteria for the testing developed in Amendment 25-64 to § 25.562 focused primarily on fore/aft facing seats. Side facing seating installations were not adequately addressed for transport category airplane in this Amendment.

These special conditions are applicable to single-occupant sidefacing seats only. They are not intended to be used for multiple-occupant sidefacing divans or sofas, as they do not account for possible interaction among the occupants.

# **Type Certification Basis**

Under the provisions of 14 CFR 21.17, the Cessna Aircraft Company must show that the Model 680 Sovereign airplane meets the applicable provisions of 14 CFR part 25, effective February 1, 1965, as amended by Amendments 25–1 through 25–98; 14 CFR part 34, effective September 10, 1990, as amended by any amendment in effect on the date of certification. Subsequent changes have been made to § 21.101 as part of Amendment 21–77, but those changes do not become effective until June 10, 2003.

If the Administrator finds that the applicable airworthiness regulations (*i.e.*, 14 CFR part 25) do not contain adequate or appropriate safety standards for the Cessna Model 680 Sovereign airplane because of a novel or unusual design feature, special conditions are prescribed under the provisions of § 21.16.

In addition to the applicable airworthiness regulations and special conditions, the Cessna Model 680 Sovereign must comply with the fuel vent and exhaust emission requirements of part 34 and the noise certification requirements of part 36, and the FAA must issue a finding of regulatory adequacy pursuant to § 611 of Public Law 92–574, the "Noise Control Act of 1972."

Special conditions, as defined in 14 CFR 11.19, are issued in accordance with § 11.38 and become part of the type certification basis in accordance with § 21.17(a)(2), Amendment 21-69, effective September 16, 1991. Special conditions are initially applicable to the model for which they are issued. Should the type certificate for that model be amended later to include any other model that incorporates the same novel or unusual design feature, the special conditions would also apply to the other model under the provisions of § 21.101(a)(1), Amendment 21-69, effective September 16, 1991.

#### **Novel or Unusual Design Features**

The Cessna Model 680 offers interior arrangements, which include single-occupant side-facing seat installations. These seats are installed on the LH and RH side of the cabin's forward section, forward and opposite to the entry door respectively. Dynamic testing of all seats approved for occupancy during takeoff and landing is required by § 25.562. The pass/fail criteria for the testing developed in Amendment 25–64 to § 25.562 focused primarily on fore/aft

facing seats. Side facing seating installations were not adequately addressed for transport category airplanes in this Amendment.

#### Discussion

The following injury criteria and testing represent the minimum acceptable standards, and are being proposed for certification of the Model 680 single-occupant side-facing seats, and are to be included as requirements in the proposed special conditions. However, the existing requirements call for a "no yaw" test condition. Cessna is proposing to demonstrate values of thoracic trauma index (TTL) and lateral pelvic acceleration (LPA) for a "10 degree yaw" for which it has some test data. In this case, Cessna must show the "10 degree yaw" yields results that will only differ slightly from the "no yaw" condition and that these differences would not be of such magnitude as to exceed the maximum allowable.

## **Proposed Injury Criteria**

- (a) Existing Criteria. As referenced by § 25.785(b), all injury protection criteria of §§ 25.562(c)(1) through (c)(6) apply to the occupants of the single-occupant side-facing seats. Head injury criteria (HIC) assessments are only required for head contact with the seat and/or adjacent structures.
- (b) Body-to-wall/furnishing contact. The seat must be installed aft of a structure such as an interior wall or furnishing that will contact the pelvis, upper arm, chest, or head of an occupant seated next to the structure. A conservative representation of the structure and its stiffness must be included in the tests. It is recommended, but not required, that the contact surface of this structure be covered with at least two inches of energy absorbing protective padding (foam or equivalent), such as Ensolite.
- (c) Thoracic Trauma. Testing with a Side Impact Dummy (SID), as defined by 49 CFR part 572, subpart F, or its equivalent, must be conducted and TTI injury criteria acquired with the SID must be less than 85, as defined in 49 CFR part 572, subpart F. Side Impact Dummy TTI must be processed as defined in Federal Motor Vehicle Safety Standard (FMVSS) part 571.214, section S6.13.5. Rational analysis, comparing an installation with another installation where TTI data were acquired and found acceptable, may also be viable.
- (d) *Pelvis*. Pelvic lateral acceleration must not exceed 130g, pelvic acceleration data must be processed as defined in FMVSS part 571.214, section S6.13.5

(f) Shoulder Strap Loads. Where upper torso straps (shoulder straps) are used for sofa occupants, tension loads in individual straps must not exceed 1,750 pounds. If dual straps are used for restraining the upper torso, the total strap tension loads must not exceed 2,000 pounds.

# **Applicability**

As discussed above, these special conditions are applicable to the Cessna Model 680 Sovereign. Should Cessna Aircraft Company apply at a later date for a change to the type certificate to include another model incorporating the same novel or unusual design feature, the special conditions would apply to that model as well under the provisions of § 21.101(a)(1), Amendment 21–69, effective September 16, 1991.

#### Conclusion

This action affects only certain novel or unusual design features on the Cessna Model 680 Sovereign airplane. It is not a rule of general applicability, and it affects only the applicant who applied to the FAA for approval of these features on the airplane.

#### List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

The authority citation for these special conditions is as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

## **The Proposed Special Conditions**

Accordingly, the Federal Aviation Administration (FAA) proposes the following special conditions as part of the type certification basis for the Cessna Aircraft Company Model 680 Sovereign airplanes.

The minimum acceptable standards of injury criteria and testing requirements for dynamic certification of the Model 680 side-facing single-occupant seats are as follows:

(a) Existing Criteria. As referenced by § 25.785(b), all injury protection criteria of §§ 25.562(c)(1) through (c)(6) apply to the occupants of the side-facing seats. Head injury criteria (HIC) assessments are only required for head contact with the seat and/or adjacent structures.

(b) Body-to-wall/furnishing contact. The seat must be installed aft of a structure such as an interior wall or furnishing that will contact the pelvis, upper arm, chest, or head of an occupant seated next to the structure. A conservative representation of the structure and its stiffness must be included in the tests. It is recommended, but not required, that the contact surface of this structure must be

covered with at least two inches of energy absorbing protective padding (foam or equivalent), such as Ensolite.

(c) Thoracic Trauma. Testing with a Side Impact Dummy (SID), as defined by 49 CFR Part 572, Subpart F, or its equivalent, must be conducted and TTI injury criteria acquired with the SID must be less than 85, as defined in 49 CFR Part 572, Subpart F. SID TTI must be processed as defined in Federal Motor Vehicle Safety Standard (FMVSS) Part 571.214, section S6.13.5. Rational analysis, comparing an installation with another installation where TTI data were acquired and found acceptable, may also be viable.

(d) Pelvis. Pelvic lateral acceleration must not exceed 130g, pelvic acceleration data must be processed as defined in FMVSS Part 571.214, section S6.13.5

(f) Shoulder Strap Loads. Where upper torso straps (shoulder straps) are used for occupants, tension loads in individual straps must not exceed 1,750 pounds. If dual straps are used for restraining the upper torso, the total strap tension loads must not exceed 2,000 pounds.

Issued in Renton, Washington, on May 5, 2003.

#### Ali Bahrami.

Acting Manager, Transport Airplane
Directorate, Aircraft Certification Service.
[FR Doc. 03–12043 Filed 5–14–03; 8:45 am]
BILLING CODE 4910–13–P

### **DEPARTMENT OF TRANSPORTATION**

## **Federal Aviation Administration**

# 14 CFR Part 39

[Docket No. 2002-CE-05-AD]

# RIN 2120-AA64

Airworthiness Directives; Cessna Aircraft Company Models 401, 401A, 401B, 402, 402A, 402B, 411, and 411A Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking

(NPRM).

SUMMARY: This document proposes to supersede Airworthiness Directive (AD) 79–10–15 R2, which applies to all Cessna Aircraft Company (Cessna) Models 401, 401A, 401B, 402, 402A, 402B, 411, and 411A airplanes. AD 79–10–15 R2 currently requires repetitive inspections of the right and left wing spar lower cap areas for fatigue cracks and requires wing spar cap repair or replacement as necessary. Cessna has

performed fatigue and crack growth analyses of the wings of these airplanes, and the Federal Aviation Administration (FAA) has evaluated this information and determined that a wing spar modification is necessary as well as periodic inspections. This proposed AD would require you to repetitively inspect the wing spar caps for fatigue cracks with any necessary repair or replacement on all airplanes and incorporate a spar strap modification on each wing spar on certain airplanes. The actions specified by this proposed AD are intended to prevent wing spar cap failure due to undetected fatigue cracks. Such failure could result in loss of a wing with consequent loss of airplane control.

**DATES:** The FAA must receive any comments on this proposed rule on or before August 8, 2003.

**ADDRESSES:** Submit comments to FAA. Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2002-CE-05-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. You may view any comments at this location between 8 a.m. and 4 p.m., Monday through Friday, except Federal holidays. You may also send comments electronically to the following address: 9-ACE-7-Docket@faa.gov. Comments sent electronically must contain "Docket No. 2002–CE–05–AD" in the subject line. If you send comments electronically as attached electronic files, the files must be formatted in Microsoft Word 97 for Windows or ASCII text.

You may get service information that applies to this proposed AD from the Cessna Aircraft Company, Product Support, PO Box 7706, Wichita, Kansas 67277; telephone: (316) 517–5800; facsimile: (316) 942–9006. You may also view this information at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Paul Nguyen, Aerospace Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946–4125; facsimile: (316) 946–4107.

#### SUPPLEMENTARY INFORMATION:

## **Comments Invited**

How Do I Comment on This Proposed AD?

The FAA invites comments on this proposed rule. You may submit whatever written data, views, or arguments you choose. You need to include the rule's docket number and submit your comments to the address specified under the caption ADDRESSES.