

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2023–15–05 The Boeing Company:**

Amendment 39–22517; Docket No. FAA–2023–1650; Project Identifier AD–2023–00795–T.

**(a) Effective Date**

This airworthiness directive (AD) is effective August 25, 2023.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all The Boeing Company Model 737 airplanes equipped with CFM International, S.A. (CFM) Model LEAP–1B series turbofan engines, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 30, Ice and Rain Protection; 71, Powerplant.

**(e) Unsafe Condition**

This AD was prompted by a report indicating that use of engine anti-ice (EAI) in dry air for more than five minutes during certain environmental and operational conditions can cause overheating of the engine inlet inner barrel beyond the material design limit, resulting in failure of the engine inlet inner barrel and severe engine inlet cowl damage. The FAA is issuing this AD to address use of EAI in certain environmental

and operational conditions. The unsafe condition, if not addressed, could result in departure of the inlet and potential fan cowl failure and departure from the airplane. The departure of the inlet may cause fuselage and/or window damage, potentially resulting in decompression and hazard to window-seated passengers aft of the wing and/or impact damage to the wing, flight control surfaces, and/or empennage, which could result in loss of control of the airplane. Inlet loss also causes significantly increased aerodynamic drag and asymmetric lift due to wing blanking, which risks fuel exhaustion on certain flights, resulting in a forced off-airport landing and injury to passengers.


**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Airplane Flight Manual (AFM) Revision**

Within 15 days after the effective date of this AD: Revise the Limitations Section of the existing AFM to include the information specified in figure 1 to paragraph (g) of this AD. This may be done by inserting a copy of figure 1 to paragraph (g) of this AD into the existing AFM.

**Figure 1 to paragraph (g) - Engine anti-ice AFM revision**

**(h) Minimum Equipment List (MEL) Revision**

Within 15 days after the effective date of this AD or upon completion of the AFM revision required by paragraph (g) of this AD, whichever occurs first: Revise the operator's existing FAA-approved MEL to prohibit dispatch under the MEL item corresponding with Master Minimum Equipment List (MMEL) Item 30–21–01B (Engine (Cowl) Anti-Ice Valves).

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

**(j) Related Information**

For more information about this AD, contact James Laubaugh, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3622; email: james.laubaugh@faa.gov.

**(k) Material Incorporated by Reference**

None.

Issued on July 31, 2023.

**Victor Wicklund,**

*Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2023–17197 Filed 8–7–23; 4:15 pm]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

**[Docket No. FAA–2023–1010; Airspace Docket No. 23–AGL–15]**

**RIN 2120–AA66**

**Amendment of Class E Airspace; Yankton, SD**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action amends the Class E airspace at Yankton, SD. This action is the result of an airspace review caused by the decommissioning of the Yankton very high frequency omnidirectional range (VOR) as part of the VOR Minimum Operating Network (MON) Program.

**DATES:** Effective 0901 UTC, November 30, 2023. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

**ADDRESSES:** A copy of the Notice of Proposed Rulemaking (NPRM), all comments received, this final rule, and all background material may be viewed online at [www.regulations.gov](http://www.regulations.gov) using the FAA Docket number. Electronic retrieval help and guidelines are available on the website. It is available 24 hours each day, 365 days each year.

FAA Order JO 7400.11G, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

**FOR FURTHER INFORMATION CONTACT:** Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5711.

#### **SUPPLEMENTARY INFORMATION:**

##### **Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends the Class E surface airspace and the Class E airspace extending upward from 700 feet above the surface at Chan Gurney Municipal Airport, Yankton, SD, to support instrument flight rule operations at this airport.

#### **History**

The FAA published an NPRM for Docket No. FAA-2023-1010 in the **Federal Register** (88 FR 29568; May 8, 2023) proposing to amend the Class E airspace at Yankton, SD. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

#### **Incorporation by Reference**

Class E airspace designations are published in paragraphs 6002 and 6005 of FAA Order JO 7400.11, Airspace Designations and Reporting Points, which is incorporated by reference in 14 CFR 71.1 on an annual basis. This document amends the current version of that order, FAA Order JO 7400.11G, dated August 19, 2022, and effective September 15, 2022. FAA Order JO 7400.11G is publicly available as listed in the **ADDRESSES** section of this document. These amendments will be published in the next update to FAA Order JO 7400.11.

FAA Order JO 7400.11G lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

#### **The Rule**

This amendment to 14 CFR part 71: Modifies the Class E surface area to within a 5.1-mile (increased from a 4.1-mile) radius of Chan Gurney Municipal Airport, Yankton, SD; removes the Yankton VOR/DME and all associated extensions from the airspace legal description; and removes the city associated with the airport in the header of the airspace legal description to comply with changes to FAA Order JO 7400.2P, Procedures for Handling Airspace Matters;

And modifies the Class E airspace extending upward from 700 feet above the surface to within a 7.6-mile (decreased from a 7.8-mile) radius of Chan Gurney Municipal Airport; and removes the city associated with the airport in the header of the airspace legal description to comply with changes to FAA Order JO 7400.2P.

#### **Regulatory Notices and Analyses**

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated

impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### **Environmental Review**

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5-6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

#### **Lists of Subjects in 14 CFR 71**

Airspace, Incorporation by reference, Navigation (air).

#### **The Amendment**

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

#### **PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS**

- 1. The authority citation for 14 CFR part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

##### **§ 71.1 [Amended]**

- 2. The incorporation by reference in 14 CFR 71.1 of FAA Order JO 7400.11G, Airspace Designations and Reporting Points, dated August 19, 2022, and effective September 15, 2022, is amended as follows:

*Paragraph 6002 Class E Airspace Areas Designated as a Surface Area.*

\* \* \* \* \*

##### **AGL SD E2 Yankton, SD [Amended]**

Chan Gurney Municipal Airport, SD  
(Lat 42°55'00" N, long 97°23'09" W)

Within a 5.1-mile radius of the Chan Gurney Municipal Airport.

\* \* \* \* \*

*Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.*

\* \* \* \* \*

##### **AGL SD E5 Yankton, SD [Amended]**

Chan Gurney Municipal Airport, SD  
(Lat 42°55'00" N, long 97°23'09" W)

That airspace extending upward from 700 feet above the surface within a 7.6-mile radius of Chan Gurney Municipal Airport.

\* \* \* \* \*

Issued in Fort Worth, Texas, on August 3, 2023.

**Martin A. Skinner,**

*Acting Manager, Operations Support Group,  
ATO Central Service Center.*

[FR Doc. 2023–16952 Filed 8–9–23; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA–2023–1352; Airspace  
Docket No. 23–ASO–24]

**RIN 2120–AA66**

#### Amendment of Class D and Class E Airspace; Columbus, MS

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** A final rule was published in the **Federal Register** on June 30, 2023, amending Class D airspace, Class E surface airspace, and Class E airspace extending upward from 700 feet above the surface for Golden Triangle Regional Airport, Columbus, MS, by updating the airport's description header and geographic coordinates, as well as the geographic coordinates of Columbus AFB, Columbus-Lowndes County Airport, Oktibbeha Airport, and McCharen Field. This action corrects the Class E airspace extending upward from 700 feet above the surface description by correcting the geographic coordinates of Oktibbeha Airport.

**DATES:** Effective 0901 UTC, October 5, 2023. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

**FOR FURTHER INFORMATION CONTACT:** John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Ave., College Park, GA 30337; Telephone (404) 305–6364.

#### SUPPLEMENTARY INFORMATION:

##### Authority for This Rulemaking

##### History

The FAA published a final rule in the **Federal Register** (88 FR 42227, June 30, 2023) for Doc. No. FAA–2023–1352, updating the geographic coordinates of

Golden Triangle Regional Airport, Columbus AFB, Columbus-Lowndes County Airport, Oktibbeha Airport, and McCharen Field. After publication, the FAA found the geographic coordinates for Oktibbeha Airport were inadvertently transposed. This action corrects this error.

#### Correction to the Final Rule

Pursuant to the authority delegated to me, the amendment of Class E airspace extending upward from 700 feet above the surface for Columbus, MS, in Docket No. FAA–2023–1352, as published in the **Federal Register** on June 30, 2023 (88 FR 42227), is corrected as follows:

#### § 71.1 [Corrected]

■ 1. On page 42228, in the second column, correct the geographic coordinates for Oktibbeha Airport to read:

(Lat 33°29'52" N, long 88°40'53" W)

Issued in College Park, Georgia, on August 2, 2023.

**Andrees C. Davis,**

*Manager Airspace & Procedures Team South,  
Eastern Service Center, Air Traffic  
Organization.*

[FR Doc. 2023–16761 Filed 8–9–23; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA–2023–1004; Airspace  
Docket No. 23–ASO–18]

**RIN 2120–AA66**

#### Amendment of Class E Airspace; Greenville, NC

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action amends Class E surface airspace and Class E airspace extending upward from 700 feet above the surface for the Greenville, NC area, as a new instrument approach procedure has been designed for ECU Health Medical Center Heliport. This action also makes an editorial change.

**DATES:** Effective 0901 UTC, October 5, 2023. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

**ADDRESSES:** A copy of the Notice of Proposed Rulemaking (NPRM), all comments received, this final rule, and

all background material may be viewed online at [www.regulations.gov](http://www.regulations.gov) using the FAA Docket number. Electronic retrieval helps and guidelines are available on the website. It is available 24 hours a day, 365 days a year.

FAA Order JO 7400.11G Airspace Designations and Reporting Points and subsequent amendments can be viewed online at [www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

**FOR FURTHER INFORMATION CONTACT:** John Goodson, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Avenue, College Park, GA 30337; Telephone: (404) 305–5966.

#### SUPPLEMENTARY INFORMATION:

##### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority, as it amends Class E airspace in Greenville, NC, to support IFR operations in the area.

##### History

The FAA published a notice of proposed rulemaking for Docket No. FAA 2023–1004 in the **Federal Register** (88 FR 29557; May 8, 2023), proposing to amend Class E airspace for Greenville, NC. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

##### Incorporation by Reference

Class E airspace designations are published in paragraphs 6002 and 6005 of FAA Order JO 7400.11, Airspace Designations and Reporting Points, incorporated by reference in 14 CFR 71.1 annually. This document amends the current version of that order, FAA Order JO 7400.11G, dated August 19, 2022, and effective September 15, 2022. FAA Order JO 7400.11G is publicly available as listed in the **ADDRESSES**