

Proposed Rules

Federal Register

Vol. 79, No. 177

Friday, September 12, 2014

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-0624 Directorate Identifier 2014-NM-005-AD]

RIN 2120-AA64

Airworthiness Directives; the Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all The Boeing Company Model 717-200 airplanes; Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40 and DC-10-40F airplanes; Model MD-10-10F and MD-10-30F airplanes; Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) airplanes; Model MD-88 airplanes; and Model MD-90-30 airplanes. This proposed AD was prompted by reports of latent air data transducer degradation. This proposed AD would require revising the maintenance or inspection program, as applicable, to incorporate special compliance items (SCIs). We are proposing this AD to prevent erroneous air data information, which could lead to a mid-air collision within reduced vertical separation minimum (RVSM) airspace.

DATES: We must receive comments on this proposed AD by October 27, 2014.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room

W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, CA 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0624; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Jen Pei, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5320; fax: 562-627-5210; email: jen.pei@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2014-0624; Directorate Identifier 2014-NM-005-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the

closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received reports of latent air data transducer degradation. This condition, if not corrected, could result in erroneous air data information, which could lead to a mid-air collision within reduced vertical separation minimum (RVSM) airspace.

Relevant Service Information

We reviewed the following service information, which describes procedures for doing a functional test of the captain's and first officer's altimeters.

- Boeing Report No. MDC-02K1003, Trijet Special Compliance Item (SCI) Report 34-4, "Functional Test of the Captain and First Officer's Altimeter," Revision K, dated February 1, 2013.

- Boeing Report No. MDC-92K9145, Twinjet SCI Report 34-1—"Functional Test of the Captain and First Officer's Altimeter," Revision M, dated February 5, 2013.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require revising the maintenance or inspection program, as applicable, to incorporate special compliance items (SCIs).

This proposed AD requires revisions to certain operator maintenance documents to include new inspections. Compliance with these inspections is required by section 91.403(c) of the Federal Aviation Regulations (14 CFR 91.403(c)). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these inspections, an operator might not be able to accomplish the inspections described in the revisions. In this situation, to comply with 14 CFR

91.403(c), the operator must request approval of an alternative method of compliance (AMOC) in accordance with the provisions of paragraph (i) of this proposed AD. The request should include a description of changes to the required inspections that will ensure the continued operational safety of the airplane.

Differences Between This Proposed AD and the Service Information

Boeing Report No. MDC-02K1003, Trijet SCI Report 34-4, "Functional Test of the Captain and First Officer's Altimeter," Revision K, dated February 1, 2013, describes actions that apply to The Boeing Company Model MD-11 and MD-11F airplanes. Based on in-service data, we have determined that

rulemaking action is unnecessary at this time for these airplanes. However, we might consider additional rulemaking if further data is received that identifies an unsafe condition on these airplanes.

Costs of Compliance

We estimate that this proposed AD affects 716 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Maintenance or inspection program revision ...	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$60,860

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. Amend § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA-2014-0624; Directorate Identifier 2014-NM-005-AD.

(a) Comments Due Date

We must receive comments by October 27, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company airplanes identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category.

(1) The Boeing Company Model 717-200 airplanes.

(2) The Boeing Company Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, and DC-10-40F airplanes; and Model MD-10-10F and MD-10-30F airplanes.

(3) The Boeing Company Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) airplanes; Model MD-88 airplanes; and Model MD-90-30 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Unsafe Condition

This AD was prompted by reports of latent air data transducer degradation. We are issuing this AD to prevent erroneous air data information, which could lead to a mid-air collision within reduced vertical separation minimum (RVSM) airspace.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance or Operations Program Revision

Within 30 days after the effective date of this AD, revise the maintenance or inspection program, as applicable, by incorporating the information specified in paragraphs (g)(1), (g)(2), or (g)(3) of this AD, as applicable. The initial compliance time for the tasks is within 18 months after the effective date of this AD.

(1) For Model 717-200 airplanes; Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) airplanes; Model MD-88 airplanes; and Model MD-90-30 airplanes: Incorporate Special Compliance Item (SCI) 34-1, "Functional Test of the Captain and First Officer's Altimeter" into the Boeing Modification Services MDC-92K9145, "Twinjet Special Compliance Items Report," Revision M, dated February 5, 2013.

(2) For Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40 and DC-10-40F airplanes; Incorporate SCI 34-4, "Functional Test of the Captain and First Officer's Altimeter" into the Boeing Modification Services MDC-02K1003, "Trijet Special Compliance Item Report," Revision K, dated February 1, 2013.

(3) For and Model MD-10-10F and MD-10-30F airplanes: Incorporate SCI 34-4, "Functional Test of the Captain and First Officer's Altimeter" into the Boeing Modification Services MDC-02K1003, "Trijet Special Compliance Item Report," Revision K, dated February 1, 2013.

(h) No Alternative Actions and Intervals

After accomplishment of the revision required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-LACO-AMOC-REQUESTS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

(1) For more information about this AD, contact Jen Pei, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5320; fax: 562-627-5210; email: jen.pei@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, CA 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on September 5, 2014.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 2014-21763 Filed 9-11-14; 8:45 am]

BILLING CODE 4910-13-P

FEDERAL COMMUNICATIONS COMMISSION**47 CFR Part 73**

[MB Docket No. 14-139, RM-11732; DA 14-1273]

Television Broadcasting Services; Mount Vernon, Illinois

AGENCY: Federal Communications Commission.

ACTION: Proposed rule.

SUMMARY: The Commission has before it a petition for rulemaking filed by WPXS, Inc. ("WPXS"), the licensee of station WPXS(TV), channel 21, Mount Vernon, Illinois, requesting the substitution of channel 11 for channel 21 at Mount Vernon. While the Commission instituted a freeze on the acceptance of full power television rulemaking petitions requesting channel substitutions in May 2011, it recently adopted rules to implement the broadcast television spectrum incentive auction authorized by the Spectrum Act which facilitates the voluntary return of television spectrum usage rights and reorganizes the broadcast television bands. The Commission will be able to recover a portion of ultra-high frequency ("UHF") spectrum for new, flexible-use licenses suitable for mobile broadband services. By relinquishing channel 21, a UHF channel, the proposed channel substitution will assist the Commission in the repacking process by freeing up a UHF channel, which serves the public interest.

DATES: Comments must be filed on or before October 14, 2014, and reply comments on or before October 27, 2014.

ADDRESSES: Federal Communications Commission, Office of the Secretary, 445 12th Street SW., Washington, DC 20554. In addition to filing comments with the FCC, interested parties should serve counsel for petitioner as follows: John R. Feore, Esq., Cooley LLP, 1299 Pennsylvania Avenue NW., Suite 700, Washington, DC 20004-2400.

FOR FURTHER INFORMATION CONTACT:

Joyce Bernstein, Joyce.Bernstein@fcc.gov, Media Bureau, (202) 418-1600.

SUPPLEMENTARY INFORMATION: This is a synopsis of the Commission's Notice of Proposed Rule Making, MB Docket No. 14-139, adopted September 4, 2014, and released September 4, 2014. The full text of this document is available for public inspection and copying during normal business hours in the FCC's Reference Information Center at Portals II, CY-A257, 445 12th Street SW., Washington, DC 20554. This document

will also be available via ECFS (<http://www.fcc.gov/cgb/ecfs/>). (Documents will be available electronically in ASCII, Word 97, and/or Adobe Acrobat.) This document may be purchased from the Commission's duplicating contractor, Best Copy and Printing, Inc., 445 12th Street SW., Room CY-B402, Washington, DC 20554, telephone 1-800-478-3160 or via email www.BCPIWEB.com. To request this document in accessible formats (computer diskettes, large print, audio recording, and Braille), send an email to fcc504@fcc.gov or call the Commission's Consumer and Governmental Affairs Bureau at (202) 418-0530 (voice), (202) 418-0432 (TTY). This document does not contain proposed information collection requirements subject to the Paperwork Reduction Act of 1995, Public Law 104-13. In addition, therefore, it does not contain any proposed information collection burden "for small business concerns with fewer than 25 employees," pursuant to the Small Business Paperwork Relief Act of 2002, Public Law 107-198, see 44 U.S.C. 3506(c)(4).

Provisions of the Regulatory Flexibility Act of 1980 do not apply to this proceeding. Members of the public should note that from the time a Notice of Proposed Rule Making is issued until the matter is no longer subject to Commission consideration or court review, all *ex parte* contacts (other than *ex parte* presentations exempt under 47 CFR 1.1204(a)) are prohibited in Commission proceedings, such as this one, which involve channel allotments. See 47 CFR 1.1208 for rules governing restricted proceedings.

For information regarding proper filing procedures for comments, see 47 CFR 1.415 and 1.420.

List of Subjects in 47 CFR Part 73

Television.

Federal Communications Commission.

Barbara A. Kreisman,

Chief, Video Division, Media Bureau.

Proposed Rules

For the reasons discussed in the preamble, the Federal Communications Commission proposes to amend 47 CFR part 73 as follows:

PART 73—RADIO BROADCAST SERVICES

■ 1. The authority citation for Part 73 continues to read as follows:

Authority: 47 U.S.C. 154, 303, 334, 336, and 339.