

Actions	Compliance	Procedures
(4) Replace vertical stabilizer attach fitting P/N 40301-7 with P/N 95266-3, replace horizontal stabilizer attach fitting P/N 40303-1/-4/-7 or 95267-1 with P/N 95267-5, and replace attachment bolt NAS1105-68 with NAS6207-68 bolt.	Within the next 2,000 hours TIS after the effective date of this AD or within 2 years after the effective date of this AD, whichever occurs first. This action terminates the repetitive inspections required in paragraph (e)(1) of this AD, including the inspections of the vertical fin aft spar, P/N 40261-24 or 95253-1.	Follow Thrush Aircraft, Inc. Service Bulletin No. SB-AG-45, Revision B, dated June 1, 2007.

Special Flight Permit

(f) Under 14 CFR part 39.23, we are limiting the special flight permits authorized for this AD to ferry aircraft to a maintenance facility for inspection by the following conditions:

- (1) Hopper must be empty.
- (2) Vne reduced to 126 m.p.h. (109 knots); and
- (3) No flight into known turbulence.

Alternative Methods of Compliance (AMOCs)

(g) The Manager, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Cindy Lorenzen, Aerospace Engineer, ACE-115A, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Blvd., Suite 450, Atlanta, GA 30349; telephone: (770) 703-6078; facsimile: (770) 703-6097; e-mail: cindy.lorenzen@faa.gov; or Mike Cann, Aerospace Engineer, ACE-117A, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Blvd., Suite 450, Atlanta, Georgia 30349; telephone: (770) 703-6038; facsimile: (770) 703-6097; e-mail: michael.cann@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Related Information

(h) To get copies of the service information referenced in this AD, contact Thrush Aircraft, Inc., P.O. Box 3149, 300 Old Pretoria Road, Albany, Georgia 31706-3149; telephone: 229-883-1440; facsimile: 229-436-4856; or on the Internet at: <http://www.thrushaircraft.com>. To view the AD docket, go to U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, or on the Internet at <http://dms.dot.gov>. The docket number is Docket No. FAA-2007-28432; Directorate Identifier 2007-CE-051-AD.

Issued in Kansas City, Missouri, on July 20, 2007.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-14433 Filed 7-25-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 301

[REG-149036-04]

RIN 1545-BE07

Application of Section 6404(g) of the Internal Revenue Code Suspension Provisions; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Correction to notice of proposed rulemaking by cross-reference to temporary regulations.

SUMMARY: This document contains corrections to notice of proposed rulemaking by cross-reference to temporary regulations (REG-149036-04) that were published in the **Federal Register** on Thursday, June 21, 2007 (72 FR 34204) relating to the application of section 6404(g) of the Internal Revenue Code suspension provisions.

FOR FURTHER INFORMATION CONTACT: Stuart Spielman, (202) 622-7950 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

The notice of proposed rulemaking by cross-reference to temporary regulations that are the subject of this correction are under section 6404(g) of the Internal Revenue Code.

Need for Correction

As published, proposed regulations (REG-149036-04) contains an error that may prove to be misleading and is in need of clarification.

Correction of Publication

Accordingly, the publication of the proposed regulations (REG-149036-04), which was the subject of FR Doc. E7-12085, is corrected as follows:

On page 34204, column 1, in the preamble, under the caption **SUMMARY**, lines 11 through 13, the language “the gulf Opportunity zone act of 2005, and the Tax Relief and Health Care Act of 2006. The regulations provide” is corrected to read “the Gulf Opportunity

Zone Act of 2005, the Tax Relief and Health Care Act of 2006, and the Small Business and Work Opportunity Tax Act of 2007. The regulations provide”.

LaNita Van Dyke,

Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel (Procedure and Administration).

[FR Doc. E7-14400 Filed 7-25-07; 8:45 am]

BILLING CODE 4830-01-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 301

[REG-149036-04]

RIN 1545-BG75

Application of Section 6404(g) of the Internal Revenue Code Suspension Provisions; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Correction to notice of proposed rulemaking.

SUMMARY: This document contains corrections to the notice of proposed rulemaking (REG-149036-04) that were published in the **Federal Register** on Thursday, June 21, 2007 (72 FR 34199) proposing regulations for the suspension of interest, penalties, additions to tax or additional amounts under section 6404(g) of the Internal Revenue Code that explain the general rules for suspension as well as exceptions to those general rules.

FOR FURTHER INFORMATION CONTACT: Stuart Spielman, (202) 622-7950 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

The notice of proposed rulemaking that is the subject of this correction is under section 6404(g) of the Internal Revenue Code.

Need for Correction

As published, the proposed regulations (REG-149036-04) contain errors that may prove to be misleading and are in need of clarification.