

For the reasons discussed, I certify that this AD:

(1) Is not a “significant regulatory action” under Executive Order 12866, and

(2) Will not affect intrastate aviation in Alaska.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

#### 2025–06–07 Airbus Helicopters:

Amendment 39–22995; Docket No. FAA–2025–0468; Project Identifier MCAI–2023–00872–R.

#### (a) Effective Date

This airworthiness directive (AD) is effective April 18, 2025.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Airbus Helicopters Model AS332C1 helicopters, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

#### (e) Unsafe Condition

This AD was prompted by new or more restrictive airworthiness limitations. The FAA is issuing this AD to prevent failure of critical parts and primary structural components, which if not addressed, could result in loss of control of the helicopter.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Action

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency AD 2023–0144, dated July 14, 2023 (EASA AD 2023–0144).

#### (h) Exceptions to EASA AD 2023–0144

(1) Where EASA AD 2023–0144 defines “the ALS,” this AD requires replacing that text with “Airbus Airworthiness Limitations Section (ALS) AS 332 C1, Issue Date May 28, 2014, Revision 10, dated July 26, 2023.”

(2) Where EASA AD 2023–0144 refers to its effective date, this AD requires using the effective date of this AD.

(3) This AD does not adopt paragraphs (1), (2), (4) and (5) of EASA AD 2023–0144.

(4) Where paragraph (3) of EASA AD 2023–0144 specifies “Within 12 months after the effective date of this AD, revise the approved AMP,” this AD requires replacing that text with “Within 30 days after the effective date of this AD, revise the airworthiness limitations section of the existing maintenance manual or instructions for continued airworthiness and the existing approved maintenance or inspection program, as applicable.”

(5) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2023–0144 is on or before the applicable “limitations” and “associated thresholds” as incorporated by the requirements of paragraph (3) of EASA AD 2023–0144 or within 30 days after the effective date of this AD, whichever occurs later.

(6) This AD does not adopt the “Remarks” section of EASA AD 2023–0144.

#### (i) Provisions for Alternative Actions and Intervals

After the action required by paragraph (g) of this AD has been done, no alternative actions and associated thresholds and intervals, including life limits, are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2023–0144.

#### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: [AMOC@faa.gov](mailto:AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (k) Additional Information

For more information about this AD, contact Adam Hein, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (316) 946–4116; email: [Adam.Hein@faa.gov](mailto:Adam.Hein@faa.gov).

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2023–0144, dated July 14, 2023.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website: [easa.europa.eu](http://easa.europa.eu). You may find the EASA material on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu).

(4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on March 27, 2025.

**Steven W. Thompson,**

*Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2025–05711 Filed 3–31–25; 11:15 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 97

[Docket No. 31598; Amdt. No. 4159]

#### Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This rule establishes, amends, suspends, or removes Standard Instrument Approach Procedures (SIAPS) and associated Takeoff Minimums and Obstacle Departure Procedures (ODPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective April 3, 2025. The compliance date for each

SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 3, 2025.

**ADDRESSES:** Availability of matters incorporated by reference in the amendment is as follows:

#### For Examination

1. U.S. Department of Transportation, Docket Ops-M30, 1200 New Jersey Avenue SE, West Bldg., Ground Floor, Washington, DC 20590-0001.

2. The FAA Air Traffic Organization Service Area in which the affected airport is located;

3. The office of Aeronautical Information Services, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

#### Availability

All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit the National Flight Data Center at [nfdc.faa.gov](http://nfdc.faa.gov) to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from the FAA Air Traffic Organization Service Area in which the affected airport is located.

#### FOR FURTHER INFORMATION CONTACT:

Romana B. Wolf, Manager, Flight Procedures and Airspace Group, Flight Technologies and Procedures Division, Office of Safety Standards, Flight Standards Service, Aviation Safety, Federal Aviation Administration. Mailing Address: FAA Mike Monroney Aeronautical Center, Flight Procedures and Airspace Group, 6500 South MacArthur Blvd., STB Annex, Bldg. 26, Room 217, Oklahoma City, OK 73099. Telephone (405) 954-1139.

**SUPPLEMENTARY INFORMATION:** This rule amends 14 CFR part 97 by establishing, amending, suspending, or removes SIAPs, Takeoff Minimums and/or ODPs. The complete regulatory description of each SIAP and its associated Takeoff Minimums or ODP for an identified airport is listed on FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR 97.20. The applicable FAA Forms are 8260-3, 8260-4, 8260-5, 8260-15A,

8260-15B, when required by an entry on 8260-15A, and 8260-15C.

The large number of SIAPs, Takeoff Minimums and ODPs, their complex nature, and the need for a special format make publication in the **Federal Register** expensive and impractical. Further, pilots do not use the regulatory text of the SIAPs, Takeoff Minimums or ODPs, but instead refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP, Takeoff Minimums and ODP listed on FAA form documents is unnecessary. This amendment provides the affected CFR sections and specifies the types of SIAPs, Takeoff Minimums and ODPs with their applicable effective dates. This amendment also identifies the airport and its location, the procedure, and the amendment number.

#### Availability and Summary of Material Incorporated by Reference

The material incorporated by reference is publicly available as listed in the **ADDRESSES** section.

The material incorporated by reference describes SIAPs, Takeoff Minimums and/or ODPs as identified in the amendatory language for part 97 of this final rule.

#### The Rule

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP, Takeoff Minimums and ODP as amended in the transmittal. Some SIAP and Takeoff Minimums and textual ODP amendments may have been issued previously by the FAA in a Flight Data Center (FDC) Notice to Air Missions (NOTAM) as an emergency action of immediate flights safety relating directly to published aeronautical charts.

The circumstances that created the need for some SIAP and Takeoff Minimums and ODP amendments may require making them effective in less than 30 days. For the remaining SIAPs and Takeoff Minimums and ODPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs and Takeoff Minimums and ODPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these SIAPs and Takeoff Minimums and ODPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs, Takeoff Minimums and

ODPs, and safety in air commerce, I find that notice and public procedure under 5 U.S.C. 553(b) are impracticable and contrary to the public interest and, where applicable, under 5 U.S.C. 553(d), good cause exists for making some SIAPs effective in less than 30 days.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### Lists of Subjects in 14 CFR Part 97

Air Traffic Control, Airports, Incorporation by reference, Navigation (Air).

Issued in Washington, DC, on March 28, 2025.

**Romana B. Wolf,**

*Manager, Flight Procedures and Airspace Group, Flight Technologies and Procedures Division, Office of Safety Standards, Flight Standards Service, Aviation Safety, Federal Aviation Administration.*

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me, 14 CFR part 97 is amended by establishing, amending, suspending, or removing Standard Instrument Approach Procedures and/or Takeoff Minimums and Obstacle Departure Procedures effective at 0901 UTC on the dates specified, as follows:

#### PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

■ 1. The authority citation for part 97 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44701, 44719, 44721-44722.

■ 2. Part 97 is amended to read as follows:

*Effective 12 June 2025*

Palm Springs, CA, PSP, RNAV (RNP) Y RWY 31L, Amdt 2

Palm Springs, CA, PSP, RNAV (RNP) Z RWY 13R, Amdt 2

Denver, CO, DEN, RNAV (RNP) Z RWY 16R, Amdt 1

Rifle, CO, RIL, RNAV (RNP) Y RWY 26, Amdt 2

Rifle, CO, RIL, RNAV (RNP) Z RWY 26, Amdt 2

Thomaston, GA, OPN, ILS OR LOC RWY 30, Amdt 4

Thomaston, GA, OPN, NDB RWY 30, Amdt 4, CANCELED

Warsaw, IN, ASW, RNAV (GPS) RWY 9, Amdt 1A

Eureka, KS, 13K, Takeoff Minimums and Obstacle DP, Amdt 1

Covington, KY, CVG, ILS OR LOC RWY 18C, ILS RWY 18C (SA CAT I), ILS RWY 18C (SA CAT II), Amdt 24

Covington, KY, CVG, ILS OR LOC RWY 18L, Amdt 8

Covington, KY, CVG, ILS OR LOC RWY 18R, ILS RWY 18R (CAT II), Amdt 2

Covington, KY, CVG, RNAV (GPS) Y RWY 18C, Amdt 2

Covington, KY, CVG, RNAV (GPS) Y RWY 18L, Amdt 2

Covington, KY, CVG, RNAV (GPS) Y RWY 18R, Amdt 2

Covington, KY, CVG, RNAV (RNP) Z RWY 9, Amdt 1

Covington, KY, CVG, RNAV (RNP) Z RWY 18C, Amdt 1

Covington, KY, CVG, RNAV (RNP) Z RWY 18L, Amdt 1

Covington, KY, CVG, RNAV (RNP) Z RWY 18R, Amdt 1

Covington, KY, CVG, RNAV (RNP) Z RWY 27, Amdt 1

Madisonville, KY, 2I0, Takeoff Minimums and Obstacle DP, Orig-A

Caribou, ME, CAR, Takeoff Minimums and Obstacle DP, Amdt 2

Bad Axe, MI, BAX, Takeoff Minimums and Obstacle DP, Amdt 4A

Cook, MN, CQM, Takeoff Minimums and Obstacle DP, Amdt 1A

David City, NE, 93Y, Takeoff Minimums and Obstacle DP, Amdt 1A

Bryan, OH, 0G6, Takeoff Minimums and Obstacle DP, Orig-A

Mount Gilead, OH, 4I9, Takeoff Minimums and Obstacle DP, Amdt 3

Waverly, TN, 0M5, Takeoff Minimums and Obstacle DP, Orig-A

Devine, TX, 23R, Takeoff Minimums and Obstacle DP, Amdt 1A

Fort Worth, TX, AFW, Takeoff Minimums and Obstacle DP, Amdt 3

Kountze/Silsbee, TX, 45R, Takeoff Minimums and Obstacle DP, Orig-A

Winters, TX, 77F, RNAV (GPS) RWY 18, Amdt 1

Winters, TX, 77F, RNAV (GPS) RWY 36, Amdt 1

Winters, TX, 77F, Takeoff Minimums and Obstacle DP, Amdt 1

Toledo, WA, TDO, ATASY THREE, Graphic DP

Boscobel, WI, OVS, Takeoff Minimums and Obstacle DP, Amdt 1A

[FR Doc. 2025-05714 Filed 4-2-25; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 97

[Docket No. 31599; Amdt. No. 4160]

#### Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This rule amends, suspends, or removes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide for the safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective April 3, 2025. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 3, 2025.

**ADDRESSES:** Availability of matter incorporated by reference in the amendment is as follows:

#### For Examination

1. U.S. Department of Transportation, Docket Ops-M30, 1200 New Jersey Avenue SE, West Bldg., Ground Floor, Washington, DC 20590-0001;

2. The FAA Air Traffic Organization Service Area in which the affected airport is located;

3. The office of Aeronautical Information Services, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA).

For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

#### Availability

All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit the National Flight Data Center online at [nfdc.faa.gov](http://nfdc.faa.gov) to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from the FAA Air Traffic Organization Service Area in which the affected airport is located.

#### FOR FURTHER INFORMATION CONTACT:

Romana B. Wolf, Manager, Flight Procedures and Airspace Group, Flight Technologies and Procedures Division, Office of Safety Standards, Flight Standards Service, Aviation Safety, Federal Aviation Administration. Mailing Address: FAA Mike Monroney Aeronautical Center, Flight Procedures and Airspace Group, 6500 South MacArthur Blvd., STB Annex, Bldg. 26, Room 217, Oklahoma City, OK 73099. Telephone (405) 954-1139.

**SUPPLEMENTARY INFORMATION:** This rule amends 14 CFR part 97 by amending the referenced SIAPs. The complete regulatory description of each SIAP is listed on the appropriate FAA Form 8260, as modified by the National Flight Data Center (NFDC)/Permanent Notice to Air Missions (P-NOTAM), and is incorporated by reference under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR 97.20. The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, pilots do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained on FAA form documents is unnecessary. This amendment provides the affected CFR sections, and specifies the SIAPs and Takeoff Minimums and ODPs with their applicable effective dates. This amendment also identifies the airport and its location, the procedure and the amendment number.

#### Availability and Summary of Material Incorporated by Reference

The material incorporated by reference is publicly available as listed in the **ADDRESSES** section.

The material incorporated by reference describes SIAPs, Takeoff Minimums and ODPs as identified in the amendatory language for part 97 of this final rule.