

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022-17-13 Piaggio Aero Industries S.p.A.:
Amendment 39-22151; Docket No. FAA-2022-0397; Project Identifier MCAI-2021-01354-A.

(a) Effective Date

This airworthiness directive (AD) is effective October 11, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Piaggio Aero Industries S.p.A. Model P-180 airplanes, serial number (S/N) 1002 and S/Ns 1105 through 3010 inclusive, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 3417, Air Data Computer.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as altimetry system errors in the air data computers (ADCs) and stand-by instrument systems. The FAA is issuing this AD to prevent a mean altimetry system error measurement from exceeding the limits defined for operations within airspace designed as reduced vertical separation minimum (RVSM) airspace. The unsafe condition, if not addressed, could result in a potential mid-air collision within RVSM airspace.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 24 months after the effective date of this AD, revise the Limitations section of the existing airplane flight manual (AFM) for your airplane by adding the information in Piaggio Aviation P.180 Avanti II/EVO Temporary Change No. 107, dated September 17, 2019. Using a different document with language identical to that on page 2-33-bis or 2-33.C-bis (as applicable to the S/N of your airplane) of Piaggio Aviation P.180 Avanti II/EVO Temporary Change No. 107, dated September 17, 2019, is acceptable for compliance with this requirement.

(2) Within 660 hours time-in-service after the effective date of this AD or 24 months after the effective date of this AD, whichever occurs first, modify the airplane by replacing the ADCs and detachable configuration module (DCM) in accordance with the Accomplishment Instructions, paragraphs (5) through (14), of Piaggio Aero Industries S.p.A. A.S. Service Bulletin No. 80-0467, Revision 2, dated March 6, 2020, and revise the instructions for continued airworthiness

for your airplane by incorporating the information in Piaggio Aviation P.180 Avanti EVO Maintenance Manual Temporary Revision No. 126, dated June 6, 2019.

(3) The AFM revision required by paragraph (g)(1) of this AD, if included, may be removed after completing the actions required by paragraph (g)(2) of this AD.

(4) As of the effective date of this AD, do not install on any airplane an ADC part number (P/N) 822-1109-018, DCM P/N 501-1870-31, or DCM P/N 501-1870-51.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Mike Kiesov, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4144; email: mike.kiesov@faa.gov.

(2) Refer to MCAI European Union Aviation Safety Agency (EASA) AD 2019-0269, dated October 29, 2019, for related information. You may examine the EASA AD at www.regulations.gov by searching for and locating Docket No. FAA-2022-0397.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Piaggio Aero Industries S.p.A. A.S. Service Bulletin No. 80-0467, Revision 2, dated March 6, 2020.

(ii) Piaggio Aviation P.180 Avanti EVO Maintenance Manual Temporary Revision No. 126, dated June 6, 2019.

(iii) Piaggio Aviation P.180 Avanti II/EVO Temporary Change No. 107, dated September 17, 2019.

(3) For service information identified in this AD, contact Piaggio Aero Industries S.p.A., P180 Customer Support, via Pionieri e Aviatori d'Italia, snc—16154 Genoa, Italy; phone: (+39) 331 679 74 93; email: technicalsupport@piaggioaerospace.it.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on

the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on August 12, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-19055 Filed 9-2-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2022-0475; Airspace Docket No. 21-AEA-16]

RIN 2120-AA66

Establishment of Area Navigation (RNAV) Routes; Northeast United States

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes three low altitude United States Area Navigation (RNAV) routes (T-routes) in the northeast United States to support the VHF Omnidirectional Range (VOR) Minimum Operational Network (MON) Program. The purpose is to enhance the efficiency of the National Airspace System (NAS) by transitioning from a ground-based to a satellite-based navigation system.

DATES: Effective date 0901 UTC, November 3, 2022. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at www.faa.gov/air_traffic/publications/. For further information, you can contact the Rules and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence

Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it modifies the route structure as necessary to preserve the safe and efficient flow of air traffic within the NAS.

History

The FAA published a notice of proposed rulemaking for Docket No. FAA-2022-0475, in the **Federal Register** (87 FR 27956; May 10, 2022) establishing six RNAV T-routes in the northeast United States to support the VOR MON Program. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal. No comments were received.

United States RNAV T-routes are published in paragraph 6011 of FAA Order JO 7400.11F, dated August 10, 2021, and effective September 15, 2021, which is incorporated by reference in 14 CFR 71.1. The RNAV routes listed in this document will be subsequently published in FAA Order JO 7400.11.

Difference From the NPRM

The FAA proposed to establish six RNAV T routes. However, subsequent to the NPRM, the FAA determined that further coordination is required on routes T-428, T-434, and T-436 before they can be implemented. Therefore, those three routes are removed from this rule and will be implemented at a later date under a separate docket. This rule establishes only T-416, T-430, and T-438 as proposed.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021.

FAA Order JO 7400.11F is publicly available as listed in the **ADDRESSES** section of this document. FAA Order JO 7400.11F lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This action amends 14 CFR part 71 by establishing three low altitude RNAV T-routes, designated T-416, T-430, and T-438, in the northeast United States to support the VOR MON Program.

T-416: T-416 extends between the Smyrna, DE (ENO), VHF Omnidirectional Range and Tactical Air Navigational System (VORTAC) and the PREPI, OA, Fix (OA means "Offshore Atlantic"). The route overlays VOR Federal airway V-312 between the ALBEK, NJ, Fix, and the PREPI Fix. At the PREPI Fix, T-416 connects with the oceanic route structure.

T-430: T-430 extends between the Philipsburg, PA (PSB), VORTAC, and the Solberg, NJ (SBJ), VOR/DME. The route overlays airway V-30 between the Philipsburg VORTAC and the Solberg VOR/DME.

T-438: T-438 extends between the RASHE, PA, Fix, and the PREPI, OA, Fix. It overlays airway V-276 between the RASHE Fix and the PREPI Fix.

FAA Order JO 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action of establishing three low altitude RNAV T-routes, designated T-416, T-430, and T-438, in the northeast United

States, in support of efforts transitioning the NAS from ground-based to satellite-based navigation, qualifies for categorical exclusion under the National Environmental Policy Act (42 U.S.C. 4321 *et seq.*) and its implementing regulations at 40 CFR part 1500, and in accordance with FAA Order 1050.1F, Environmental Impacts: Policies and Procedures, paragraph 5-6.5a, which categorically excludes from further environmental impact review rulemaking actions that designate or modify classes of airspace areas, airways, routes, and reporting points (see 14 CFR part 71, Designation of Class A, B, C, D, and E Airspace Areas; Air Traffic Service Routes; and Reporting Points). As such, this action is not expected to result in any potentially significant environmental impacts. In accordance with FAA Order 1050.1F, paragraph 5-2 regarding Extraordinary Circumstances, the FAA has reviewed this action for factors and circumstances in which a normally categorically excluded action may have a significant environmental impact requiring further analysis. Accordingly, the FAA has determined that no extraordinary circumstances exist that warrant preparation of an environmental assessment or environmental impact study.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021, is amended as follows:

Paragraph 6011 United States Area Navigation Routes.

* * * * *

T-416 Smyrna, DE (ENO) to PREPI, OA [New]

Smyrna, DE (ENO)	VORTAC	(Lat. 39°13'53.93" N, long. 075°30'57.49" W)
TEBEE, NJ	FIX	(Lat. 39°30'13.97" N, long. 075°19'37.19" W)
LULOO, NJ	WP	(Lat. 39°36'35.96" N, long. 075°12'57.43" W)
RIDNG, NJ	WP	(Lat. 39°45'30.23" N, long. 075°05'59.95" W)
ALBEK, NJ	FIX	(Lat. 39°46'39.92" N, long. 074°54'25.99" W)
Coyle, NJ (CYN)	VORTAC	(Lat. 39°49'02.42" N, long. 074°25'53.85" W)
PREPI, OA	FIX	(Lat. 39°48'41.06" N, long. 073°15'40.70" W)

* * * * *

T-430 Philipsburg, PA (PSB) to Solberg, NJ (SBJ) [New]

Philipsburg, PA (PSB)	VORTAC	(Lat. 40°54'58.53" N, long. 077°59'33.78" W)
Selinsgrove, PA (SEG)	VOR/DME	(Lat. 40°47'27.09" N, long. 076°53'02.55" W)
East Texas, PA (ETX)	VOR/DME	(Lat. 40°34'51.74" N, long. 075°41'02.51" W)
BOPLY, PA	FIX	(Lat. 40°32'47.79" N, long. 075°11'07.06" W)
Solberg, NJ (SBJ)	VOR/DME	(Lat. 40°34'58.96" N, long. 074°44'30.45" W)

* * * * *

T-438 RASHE, PA to PREPI, OA [New]

RASHE, PA	FIX	(Lat. 40°40'36.04" N, long. 077°38'38.94" W)
Ravine, PA (RAV)	VORTAC	(Lat. 40°33'12.21" N, long. 076°35'57.77" W)
HIKES, PA	FIX	(Lat. 40°22'55.93" N, long. 075°36'54.90" W)
MAZIE, PA	FIX	(Lat. 40°19'19.55" N, long. 075°06'35.28" W)
Yardley, PA (ARD)	VOR/DME	(Lat. 40°15'12.03" N, long. 074°54'27.41" W)
Robbinsville, NJ (RBV)	VORTAC	(Lat. 40°12'08.65" N, long. 074°29'42.09" W)
PREPI, OA	FIX	(Lat. 39°48'41.06" N, long. 073°15'40.70" W)

* * * * *

Issued in Washington, DC, on August 30, 2022.

Scott M. Rosenbloom,

Manager, Airspace Rules and Regulations.

[FR Doc. 2022–19101 Filed 9–2–22; 8:45 am]

BILLING CODE 4910–13–P

CONSUMER PRODUCT SAFETY COMMISSION

16 CFR Part 1229

[Docket No. CPSC–2015–0028]

Safety Standard for Infant Bouncer Seats

AGENCY: Consumer Product Safety Commission.

ACTION: Direct final rule.

SUMMARY: In September 2017, the U.S. Consumer Product Safety Commission (CPSC or Commission) published a consumer product safety standard for infant bouncer seats under section 104 of the Consumer Product Safety Improvement Act of 2008 (CPSIA). The standard incorporated by reference the ASTM voluntary standard for infant bouncer seats that had been adopted earlier in 2017 and was in effect at the time. ASTM updated the mandatory standard for infant bouncer seats in 2019 and again in 2022. Consistent with the CPSIA's process for updating mandatory standards for durable infant or toddler products that are based on a voluntary standard, when the voluntary standards organization revises the standard, this direct final rule updates the mandatory standard for infant bouncer seats to incorporate by

reference ASTM's 2022 version of the voluntary standard.

DATES: The rule is effective on December 19, 2022, unless CPSC receives a significant adverse comment by October 6, 2022. If CPSC receives such a comment, it will publish a document in the **Federal Register**, withdrawing this direct final rule before its effective date. The incorporation by reference of the publication listed in this rule is approved by the Director of the Federal Register as of December 19, 2022.

ADDRESSES: You can submit comments, identified by Docket No. CPSC–2015–0028, by any of the following methods:

Electronic Submissions: Submit electronic comments to the Federal eRulemaking Portal at: www.regulations.gov. Follow the instructions for submitting comments. Do not submit through this website: confidential business information, trade secret information, or other sensitive or protected information that you do not want to be available to the public. CPSC typically does not accept comments submitted by electronic mail (email), except as described below.

Mail/Hand Delivery/Courier/Confidential Written Submissions: CPSC encourages you to submit electronic comments by using the Federal eRulemaking Portal. You may, however, submit comments by mail, hand delivery, or courier to: Office of the Secretary, Consumer Product Safety Commission, 4330 East-West Highway, Bethesda, MD 20814; telephone: (301) 504–7479.

Instructions: All submissions must include the agency name and docket number. CPSC may post all comments without change, including any personal

identifiers, contact information, or other personal information provided, to: www.regulations.gov. If you wish to submit confidential business information, trade secret information, or other sensitive or protected information that you do not want to be available to the public, you may submit such comments by mail, hand delivery, or courier, or you may email them to: cpsc-os@cpsc.gov.

Docket: For access to the docket to read background documents or comments received, go to: www.regulations.gov, and insert the docket number, CPSC–2015–0028, into the “Search” box, and follow the prompts.

FOR FURTHER INFORMATION CONTACT: Keysha Walker, Compliance Officer, U.S. Consumer Product Safety Commission, 4330 East-West Highway, Bethesda, MD 20814; telephone: (301) 504–6820; email: KWalker@cpsc.gov.

SUPPLEMENTARY INFORMATION:

A. Background

1. Statutory Authority

Section 104(b)(1) of the CPSIA requires the Commission to assess the effectiveness of voluntary standards for durable infant or toddler products and to adopt mandatory standards for these products. 15 U.S.C. 2056a(b)(1). A mandatory standard must be “substantially the same as” the corresponding voluntary standard, or it may be “more stringent than” the voluntary standard, if the Commission determines that more stringent requirements would further reduce the risk of injury associated with the product. *Id.*

Section 104(b)(4)(B) of the CPSIA specifies the process for updating the