

(e) Reason

This AD was prompted by a report of a capacitive density condensator (cadensicon) coil overheating during testing. We are issuing this AD to detect and correct potential overheating of the cadensicon coil, which could create an ignition source inside a fuel tank, which, in combination with flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Actions

Within 30 months after the effective date of this AD, inspect to determine whether any fuel quantity indication computer (FQIC) Type 1, having part number (P/N) SIC5054 or P/N SIC5051 (as applicable to the airplane model), is installed, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A300–28–6024, Revision 02, dated January 19, 2011; or Airbus Mandatory Service Bulletin A310–28–2039, Revision 01, dated January 19, 2011; as applicable. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number of the FQIC can be conclusively determined from that review. If any FQIC Type 1 having P/N SIC5054 or P/N SIC5051 is installed, within 30 months after the effective date of this AD, replace the FQIC Type 1 with a FQIC Type 2 having P/N SIC5055, P/N SIC5076, P/N SIC5082, or P/N SIC5083 (as applicable to Model A310 series airplanes) or with a FQIC Type 2 having P/N SIC5077 (as applicable to Model A300 B4–600 series airplanes), and modify the associated wiring, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A300–28–6024, Revision 02, dated January 19, 2011; or Airbus Mandatory Service Bulletin A310–28–2039, Revision 01, dated January 19, 2011; as applicable.

(h) Parts Installation Prohibition

As of the effective date of this AD, no person may install any FQIC Type 1 having P/N SIC5054 or P/N SIC5051, on any airplane.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to Attn: Dan Rodina, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone (425) 227–2125; fax (425)

227–1149. Information may be emailed to: 9–ANM–116–AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(j) Related Information

Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2011–0186, dated September 23, 2011, and the service information specified in paragraphs (j)(1) and (j)(2) of this AD, for related information.

(1) Airbus Mandatory Service Bulletin A300–28–6024, Revision 02, dated January 19, 2011.

(2) Airbus Mandatory Service Bulletin A310–28–2039, Revision 01, dated January 19, 2011.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the following service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Mandatory Service Bulletin A300–28–6024, Revision 02, dated January 19, 2011.

(ii) Airbus Mandatory Service Bulletin A310–28–2039, Revision 01, dated January 19, 2011.

(3) For Airbus service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202–741–6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on July 31, 2012.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012–19254 Filed 8–13–12; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF COMMERCE**Bureau of Industry and Security****15 CFR Part 774****The Commerce Control List***CFR Correction*

In the **Federal Register** published on July 26, 2012, on page 43711, in the third column, in instruction 3.C., “5A003” is corrected to read “5A002”. [FR Doc. 2012–19955 Filed 8–13–12; 8:45 am]

BILLING CODE 1505–01–D

FEDERAL MINE SAFETY AND HEALTH REVIEW COMMISSION**29 CFR Parts 2700, 2701, 2702, 2704, 2705, 2706****Commission Address Change**

AGENCY: Federal Mine Safety and Health Review Commission (FMSHRC).

ACTION: Final rule.

SUMMARY: The Federal Mine Safety and Health Review Commission is relocating its Headquarters office and is amending its regulations to inform the public of the address change.

DATES: This final rule will take effect on August 27, 2012.

ADDRESSES: This final rule is available on FMSHRC’s Web site, <http://www.fmsshr.gov>.

FOR FURTHER INFORMATION CONTACT:

Sarah Stewart, Deputy General Counsel, Office of the General Counsel, Federal Mine Safety and Health Review Commission, at (202) 434–9935 or sstewart@fmsshr.gov.

SUPPLEMENTARY INFORMATION:**A. Background**

On August 24, 2012, FMSHRC will move its Headquarters office from 601 New Jersey Avenue NW., Suite 9500, Washington, DC 20001 to 1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710.

B. Notice and Public Procedure

Because this amendment deals with agency management and procedures, the notice and comment provisions of the Administrative Procedure Act do not apply pursuant to 5 U.S.C. 553(a)(2) and (b)(3)(A).

Good cause exists to dispense with the usual 30-day delay in the effective date because the amendments are of a minor and administrative nature dealing with only a change in address.

The Commission is an independent regulatory agency and, as such, is not

subject to the requirements of E.O. 12866, E.O. 13132, or the Unfunded Mandates Reform Act, 2 U.S.C. 1501 *et seq.*

The Commission has determined that this rulemaking is exempt from the requirements of the Regulatory Flexibility Act (5 U.S.C. 601 *et seq.*) because a general notice of proposed rulemaking is not required under 5 U.S.C. 553(b).

This rule does not contain a new or amended information collection requirement subject to the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*).

The Commission has determined that the Congressional Review Act, 5 U.S.C. 801, is not applicable here because, pursuant to 5 U.S.C. 804(3)(C), this rule “does not substantially affect the rights or obligations of non-agency parties.”

List of Subjects

29 CFR Part 2700

Administrative practice and procedure, Mine safety and health, Penalties, Whistleblowing.

29 CFR Part 2701

Sunshine Act.

29 CFR Part 2702

Freedom of information.

29 CFR Part 2704

Claims, Equal access to justice, Lawyers.

29 CFR Part 2705

Privacy.

29 CFR Part 2706

Administrative practice and procedure, Civil rights, Equal employment opportunity, Federal buildings and facilities, Individuals with disabilities.

Accordingly, Chapter XXVII of Title 29 of the Code of Federal Regulations is amended as follows:

PART 2700—PROCEDURAL RULES

■ 1. The authority citation for part 2700 continues to read as follows:

Authority: 30 U.S.C. 815, 820, 823, and 876.

§ 2700.1 [Amended]

■ 2. In § 2700.1(a)(1), remove “601 New Jersey Avenue NW., Suite 9500, Washington, DC 20001” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

§ 2700.4 [Amended]

■ 3. In § 2700.4(b)(1), remove “601 New Jersey Avenue NW., Suite 9500,

Washington, DC 20001” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

§ 2700.5 [Amended]

■ 4. In § 2700.5:

■ a. In paragraph (b)(1), remove “601 New Jersey Avenue NW., Suite 9500, Washington, DC 20001” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

■ b. In paragraph (i), remove “601 New Jersey Avenue NW., Suite 9500, Washington, DC 20001” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

§ 2700.82 [Amended]

■ 5. In § 2700.82(d), remove “601 New Jersey Avenue NW., Suite 9500, Washington, DC 20001” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

PART 2701—GOVERNMENT IN THE SUNSHINE ACT REGULATIONS

■ 6. The authority citation for part 2701 continues to read as follows:

Authority: Sec. 113, Federal Mine Safety and Health Act of 1977, Pub. L. 95–165 (30 U.S.C. 823).

§ 2701.4 [Amended]

■ 7. In § 2701.4, remove “601 New Jersey Avenue NW., Suite 9500, Washington, DC 20001” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

PART 2702—REGULATIONS IMPLEMENTING THE FREEDOM OF INFORMATION ACT

■ 8. The authority citation for part 2702 continues to read as follows:

Authority: Sec. 113, Federal Mine Safety and Health Act of 1977, Pub. L. 95–165 (30 U.S.C. 801 *et seq.*); 5 U.S.C. 552; Pub. L. 104–231, October 2, 1996, 110 Stat. 3048.

■ 9. Section 2702.2 is revised to read as follows:

§ 2702.2 Location of headquarters.

The Commission maintains its Headquarters office at 1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710. The locations of other Commission offices may be obtained from the Commission’s Web site (<http://www.fmshrc.gov>).

§ 2702.3 [Amended]

■ 10. In § 2702.3(a), remove “601 New Jersey Avenue NW., Suite 9500,

Washington, DC 20001–2021” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

§ 2702.4 [Amended]

■ 11. In § 2702.4(a), remove “601 New Jersey Ave., NW., Suite 9500, Washington, DC” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

PART 2704—IMPLEMENTATION OF THE EQUAL ACCESS TO JUSTICE ACT IN COMMISSION PROCEEDINGS

■ 12. The authority citation for part 2704 continues to read as follows:

Authority: (5 U.S.C. 504(c)(1); Pub. L. 99–80, 99 Stat. 183; Pub. L. 104–121, 110 Stat. 862.

§ 2704.201 [Amended]

■ 13. In § 2704.201(a), remove “601 New Jersey Avenue NW., Suite 9500, Washington, DC 20001” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

§ 2704.308 [Amended]

■ 14. In § 2704.308(b), remove “601 New Jersey Avenue NW., Suite 9500, Washington, DC 20001” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

PART 2705—PRIVACY ACT IMPLEMENTATION

■ 15. The authority citation for part 2705 continues to read as follows:

Authority: 5 U.S.C. 552a; Pub. L. 93–579.

§ 2705.4 [Amended]

■ 16. In § 2705.4, remove “601 New Jersey Avenue NW., Suite 9500, Washington, DC 20001” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

§ 2705.8 [Amended]

■ 17. In § 2705.8, remove “601 New Jersey Avenue NW., Suite 9500, Washington, DC 20001” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

PART 2706—ENFORCEMENT OF NONDISCRIMINATION ON THE BASIS OF HANDICAP IN PROGRAMS OR ACTIVITIES CONDUCTED BY THE FEDERAL MINE SAFETY AND HEALTH REVIEW COMMISSION

■ 18. The authority citation for part 2706 continues to read as follows:

Authority: 29 U.S.C. 794.

§ 2706.170 [Amended]

■ 19. In § 2706.170(c), remove “601 New Jersey Avenue NW., Suite 9500, Washington, DC 20001” and add in its place “1331 Pennsylvania Avenue NW., Suite 520N, Washington, DC 20004–1710”.

Dated: August 7, 2012.

Mary Lu Jordan,

Chairman, Federal Mine Safety and Health Review Commission.

[FR Doc. 2012–19828 Filed 8–13–12; 8:45 am]

BILLING CODE 6735–01–P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 165

[Docket Number USCG–2012–0494]

RIN 1625–AA00

Safety Zone for Fireworks Display, Pamlico and Tar Rivers; Washington, NC

AGENCY: Coast Guard, DHS.

ACTION: Temporary final rule.

SUMMARY: The Coast Guard is establishing a temporary safety zone on the Pamlico and Tar Rivers, Washington, NC. This action is necessary to protect the life and property of the maritime public from the hazards posed by fireworks displays. This zone is intended to restrict vessels from a portion of the Pamlico River and Tar River during Beaufort County’s 300th Anniversary Celebration Fireworks.

DATES: This rule is effective on September 22, 2012, from 8:00 p.m. until 10:00 p.m.

ADDRESSES: Documents mentioned in this preamble are part of docket [USCG–2012–0494]. To view documents mentioned in this preamble as being available in the docket, go to <http://www.regulations.gov>, type the docket number in the “SEARCH” box and click “SEARCH.” Click on Open Docket Folder on the line associated with this rulemaking. You may also visit the Docket Management Facility in Room W12–140 on the ground floor of the Department of Transportation West Building, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or

email CWO4 Joseph M. Edge, Sector North Carolina Waterways Management, Coast Guard; telephone 252–247–4525, email Joseph.M.Edge@uscg.mil. If you have questions on viewing or submitting material to the docket, call Renee V. Wright, Program Manager, Docket Operations, telephone (202) 366–9826.

SUPPLEMENTARY INFORMATION:

Table of Acronyms

DHS Department of Homeland Security
FR Federal Register
NPRM Notice of Proposed Rulemaking

A. Regulatory History and Information

On June 21, 2012 a Notice of Proposed Rule Making (NPRM) was published in 77 FR 37356. We received no comments on the proposed rule. No public meeting was requested, and none was held.

B. Basis and Purpose

On September 22, 2012 fireworks will be launched from a point on land near the Pamlico and Tar Rivers to commemorate Beaufort County’s 300th anniversary. The temporary safety zone created by this rule is necessary to ensure the safety of vessels and spectators from hazards associated with the fireworks display. Such hazards include obstructions to the waterway that may cause death, serious bodily harm, or property damage. Establishing a safety zone to control vessel movement around the location of the launch area will help ensure the safety of persons and property in the vicinity of this event and help minimize the associated risks.

C. Discussion of Comments, Changes and the Final Rule

We received no comments on the proposed rule. No public meeting was requested, and none was held.

A temporary safety zone is necessary to ensure the safety of spectators and vessels during the setup, loading, and launching of the Beaufort County 300th Anniversary Fireworks Display. The fireworks display will occur for approximately 25 minutes from 9 p.m. to 9:25 p.m. on September 22, 2012. However, the Safety Zone will be enforced from 8 p.m. until 10 p.m. in order to ensure safety during the setup, loading and removal of the display equipment.

The safety zone will encompass all waters on the Pamlico and Tar Rivers within a 300 yard radius of the launch site on land at position 35°32’25” N, longitude 077°03’42” W. All geographic coordinates are North American Datum 1983 (NAD 83). The effect of this temporary safety zone will be to restrict

navigation in the regulated area during the enforcement period.

All persons and vessels shall comply with the instructions of the Coast Guard Captain of the Port or the designated on scene patrol personnel. Entry into, transiting, or anchoring within the safety zone is prohibited unless authorized by the Captain of the Port Sector North Carolina or his designated representative. The Captain of the Port or his designated representative may be contacted via VHF Channel 16. Notification of the temporary safety zone will be provided to the public via marine information broadcasts.

D. Regulatory Analyses

We developed this rule after considering numerous statutes and executive orders related to rulemaking. Below we summarize our analyses based on 13 of these statutes or executive orders.

1. Regulatory Planning and Review

This rule is not a significant regulatory action under section 3(f) of Executive Order 12866, Regulatory Planning and Review, as supplemented by Executive Order 13563, Improving Regulation and Regulatory Review, and does not require an assessment of potential costs and benefits under section 6(a)(3) of Executive Order 12866 or under section 1 of Executive Order 13563. The Office of Management and Budget has not reviewed it under those Orders. Although this regulation will restrict access to the area, the effect of this rule will not be significant because: (i) The safety zone will only be in effect from 8 p.m. to 10 p.m. on September 22, 2012, (ii) the Coast Guard will give advance notification via maritime advisories so mariners can adjust their plans accordingly, and (iii) although the safety zone will apply to the section of the Pamlico River and Tar River, vessel traffic will be able to transit safely around the safety zone.

2. Impact on Small Entities

The Regulatory Flexibility Act of 1980 (RFA), 5 U.S.C. 601–612, as amended, requires federal agencies to consider the potential impact of regulations on small entities during rulemaking. The Coast Guard received no comments from the Small Business Administration on this rule. The Coast Guard certifies under 5 U.S.C. 605(b) that this rule will not have a significant economic impact on a substantial number of small entities. This rule will affect the following entities, some of which may be small entities: The owners or operators of vessels intending to transit through or anchor in the specified portion of