

Unsafe Condition

(d) This AD results from analysis by the manufacturer that MP159 material pylon bolts do not meet the full life cycle torque check interval requirement, in a bolt-out condition. We are issuing this AD to prevent front pylon mount bolt and primary mount thrust load path failure, which could result in an engine separating from the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

INCO 718 Material Bolts Torque Checks

(f) Perform initial and repetitive torque checks of INCO 718 material front pylon mount bolts, P/N 54T670, and replace, if necessary, with new bolts, using the Accomplishment Instructions of PW Alert Service Bulletin (ASB) PW4G-100-A71-9, Revision 1, dated November 24, 1997, as follows:

(1) For front pylon mount bolts, P/N 54T670, with fewer than 1,000 cycles-since-new (CSN) on the effective date of this AD, do the following using Part (A) of the Accomplishment Instructions of the ASB:

(i) Perform an initial torque check before accumulating 1,250 CSN or at the next engine removal for cause, whichever occurs sooner.

(ii) Thereafter, perform torque checks at intervals of no fewer than 750 or no more than 1,250 cycles-in-service (CIS) since last torque check, not to exceed the life limit of 11,000 CSN.

(2) For front pylon mount bolts, P/N 54T670, with 1,000 CSN or more but fewer than 5,750 CSN on the effective date of this AD, do the following using Part (A) of the Accomplishment Instructions of the ASB:

(i) Perform an initial torque check within 250 CIS after the effective date of this AD, or at the next engine removal for any cause, whichever occurs sooner.

(ii) Thereafter, perform torque checks at intervals of no fewer than 750 or no more than 1,250 CIS since last torque check, not to exceed the life limit of 11,000 CSN.

(3) For front pylon mount bolts, P/N 54T670, with 5,750 CSN or more on the effective date of this AD, do the following using Part (B) of the Accomplishment Instructions of the ASB:

(i) Perform an initial torque check within 250 CIS after the effective date of this AD, or before the next engine removal for any cause, whichever occurs sooner.

(ii) Thereafter, perform torque checks at intervals of no fewer than 750 or no more than 1,250 CIS since last torque check, not to exceed the front pylon mount bolt P/N 54T670, life limit of 11,000 CSN.

(4) Before further flight, replace all four bolts using Part (A), Paragraph 1(D) of the Accomplishment Instructions of the ASB, if any of the bolts are loose or broken.

MP159 Material Bolts Inspections

(g) Perform initial and repetitive torque checks of front pylon mount bolts, P/N 51U615, using the Accomplishment Instructions of PW ASB PW4G-100-A71-32, dated April 15, 2005, as follows:

(1) For front pylon mount bolts with fewer than 2,200 CSN on the effective date of this AD, perform the initial torque inspection before accumulating 2,700 CSN, or at the next engine removal for any cause, whichever occurs sooner.

(2) For front pylon mount bolts with 2,200 CSN or more on the effective date of this AD, perform the initial torque check within the next 500 CIS, or at the next engine removal for any cause, whichever occurs sooner.

(3) Thereafter, perform torque inspections at intervals not to exceed 2,700 CIS since last torque inspection.

(4) Before further flight, replace all four bolts using Paragraph 1.E. of the Accomplishment Instructions of the ASB, if any are loose or broken.

Primary Mount Thrust Load Path Inspections

(h) Perform initial and repetitive visual inspections of the primary mount thrust load path using the Accomplishment Instructions of PW ASB PW4G-100-A71-18, Revision 2, dated January 15, 2002, as follows:

(1) For forward engine mount assemblies with fewer than 1,000 CSN on the effective date of this AD, perform the initial visual inspection at the earlier of the following:

- (i) Before accumulating 1,250 CSN; or
- (ii) The next engine removal for any cause.

(2) For forward engine mount assemblies with 1,000 CSN or more on the effective date of this AD, perform the initial visual inspection within 250 CIS after the effective date of this AD, or the next engine removal for any cause, whichever occurs sooner.

(3) Thereafter, perform visual inspections at intervals of no fewer than 750 or no more than 1,250 CIS since last visual inspection.

(4) Before further flight, replace all cracked parts with serviceable parts and inspect the primary thrust load path components using Paragraph 4 of the Accomplishment Instructions of the ASB.

Terminating Action

(i) Replacement of the forward engine mount bearing housing, P/N 59T794 or P/N 54T659 with P/N 52U420, using SB PW4G-100-71-22, dated January 15, 2002, constitutes terminating action to the inspection requirements of paragraph (h) of this AD.

Alternative Methods of Compliance

(j) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(k) None.

Issued in Burlington, Massachusetts, on December 22, 2005.

Peter A. White,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E5-8020 Filed 12-28-05; 8:45 am]

BILLING CODE 4910-13-P

FEDERAL TRADE COMMISSION**16 CFR Chapter I****Notice of Intent To Request Public Comments**

AGENCY: Federal Trade Commission.

ACTION: Notice of intent to request public comments.

SUMMARY: As part of its ongoing systematic review of all Federal Trade Commission rules and guides, the Commission gives notice that, during 2006, it intends to request public comments on the rules and guides listed below. The Commission will request comments on, among other things, the economic impact of, and the continuing need for, the rules and guides; possible conflict between the rules and guides and state, local, or other federal laws or regulations; and the effect on the rules and guides of any technological, economic, or other industry changes. No Commission determination on the need for or the substance of the rules and guides should be inferred from the notice of intent to publish requests for comments. In addition, the Commission announces a revised 10-year regulatory review schedule.

FOR FURTHER INFORMATION CONTACT:

Further details may be obtained from the contact person listed for the particular rule.

SUPPLEMENTARY INFORMATION: The Commission intends to initiate a review of and solicit public comments on the following rules and guides during 2006:

(1) *Guides for the Nursery Industry*, 16 CFR part 18. Agency Contact: Janice Frankle (202) 326-3022, Federal Trade Commission, Bureau of Consumer Protection, Division of Enforcement, 600 Pennsylvania Ave., NW., Washington, DC 20580.

(2) *Test Procedures and Labeling Standards for Recycled Oil*, 16 CFR part 311. Agency Contact: Neil Blickman, (202) 326-3038, Federal Trade Commission, Bureau of Consumer Protection, Division of Enforcement, 600 Pennsylvania Ave., NW., Washington, DC 20580.

(3) *Used Motor Vehicle Trade Regulation Rule*, 16 CFR part 455. Agency Contact: John Hallerud, (312) 960-5615, Federal Trade Commission, Midwest Region, 55 East Monroe Street, Suite 1860, Chicago, Illinois 60603.

In addition, the Commission previously announced that regulatory review of the Appliance Labeling Rule, 16 CFR part 305, would be combined with rulemaking required by Section 137 of the Energy Policy Act of 2005. An Advance Notice of Proposed

Rulemaking in that proceeding was published on November 2, 2005, 70 FR 66307, and comments are due on January 13, 2006.

As part of its ongoing program to review all current Commission rules and guides, the Commission also has

tentatively scheduled reviews of other rules and guides for 2007 through 2016. A copy of this tentative schedule is appended. The Commission, in its discretion, may modify or reorder the schedule in the future to incorporate new legislative rules, or to respond to

external factors (such as changes in the law) or other considerations.

Authority: 15 U.S.C. 41–58.

By direction of the Commission.

Donald S. Clark,
Secretary.

APPENDIX—REGULATORY REVIEW MODIFIED TEN-YEAR SCHEDULE

16 CFR part	Topic	Year to review
24	Guides for Select Leather and Imitation Leather Products	2007
435	Mail or Telephone Order Merchandise Rule	2007
500	Regulations Under Section 4 of the Fair Packaging and Labeling Act (FPLA)	2007
501	Exemptions from Part 500 of the FPLA	2007
502	Regulations Under Section 5(C) of the FPLA	2007
503	Statements of General Policy or Interpretations Under the FPLA	2007
306	Automotive Fuel Ratings, Certification and Posting Rule	2008
424	Retail Food Store Advertising and Marketing Practices Rule	2008
429	Rule concerning Cooling-Off Period for Sales Made at Homes or at Certain Other Locations	2008
444	Credit Practices Rule	2008
601	Summary of Consumer Rights, Notice of User Responsibilities, and Notice of Furnisher Responsibilities under the Fair Credit Reporting Act.	2008
254	Guides for Private Vocational and Distance Education Schools	2009
260	Guides for the Use of Environmental Marketing Claims	2009
300	Rules and Regulations under the Wool Products Labeling Act	2009
301	Rules and Regulations under the Fur Products Labeling Act	2009
303	Rules and Regulations under the Textile Fiber Products Identification Act	2009
425	Rule Concerning the Use of Negative Option Plans	2009
239	Guides for the Advertising of Warranties and Guarantees	2010
433	Preservation of Consumers' Claims and Defenses Rule	2010
700	Interpretations of Magnuson-Moss Warranty Act	2010
701	Disclosure of Written Consumer Product Warranty Terms and Conditions	2010
702	Pre-sale Availability of Written Warranty Terms	2010
703	Informal Dispute Settlement Procedures	2010
14	Administrative Interpretations, General Policy Statements, and Enforcement Policy Statements	2011
23	Guides for the Jewelry, Precious Metals, and Pewter Industries	2011
423	Care Labeling Rule	2011
20	Guides for the Rebuilt, Reconditioned and Other Used Automobile Parts Industry	2012
233	Guides Against Deceptive Pricing	2012
238	Guides Against Bait Advertising	2012
240	Guides for Advertising Allowances and Other Merchandising Payments and Services	2012
251	Guide Concerning Use of the Word "Free" and Similar Representations	2012
259	Guide Concerning Fuel Economy Advertising for New Automobiles	2012
310	Telemarketing Sales Rule	2013
801	Hart-Scott-Rodino Antitrust Improvements Act Coverage Rules	2013
802	Hart-Scott-Rodino Antitrust Improvements Act Exemption Rules	2013
803	Hart-Scott-Rodino Antitrust Improvements Act Transmittal Rules	2013
304	Rules and Regulations under the Hobby Protection Act	2014
309	Labeling Requirements for Alternative Fuels and Alternative Fueled Vehicles	2014
314	Standards for Safeguarding Customer Information	2014
315	Contact Lens Rule	2015
316	Rules Implementing the CAN-SPAM Act of 2003	2015
456	Ophthalmic Practice Rules	2015
603	Fair Credit Reporting Act (FCRA) Rules—Definitions	2015
610	FCRA Rules—Free Annual File Disclosures	2015
611	FCRA Rules—Prohibition Against Circumventing Treatment as a Nationwide Consumer Reporting Agency	2015
613	FCRA Rules—Duration of Active Duty Alerts	2015
614	FCRA Rules—Appropriate Proof of Identity	2015
698	FCRA Rules—Summaries, Notices, and Forms	2015
460	Labeling and Advertising of Home Insulation	2016
682	FCRA Rules—Disposal of Consumer Report Information and Records	2016