

radius of 955.0 feet, a distance of 390.76 feet to the Northeasterly 40 foot right of way as described in said Document Number 200009390; thence along said 40 foot right of way, North 46 degrees 05 minutes 15 seconds West along the line aforesaid, a distance of 288.78 feet to a point of curve; thence Northerly and continuing along said 40 foot right of way along a circular curve to the right having a radius of 260.00 feet, a distance of 351.96 feet to a point of tangent; thence continuing along said 40 foot right of way, North 31 degrees 28 minutes 25 seconds East along said tangent, a distance of 155.80 feet to the West 50 foot right of way per the plans aforesaid; thence Northeasterly along said 50 foot right of way on a non tangent circular curve to the right having a radius of 955.0 feet, a distance of 279.74 feet to the Northwesterly 40 foot right of way of the Indianapolis Road as described in the Document Number aforesaid, the chord of which bears North 14 degrees 47 minutes 42 seconds East, 278.74 feet; thence South 31 degrees 28 minutes 25 seconds West along said 40 foot right of way, a distance of 422.82 feet to a point of curve; thence Southerly and continuing on said 40 foot right of way along a circular curve to the left having a radius of 340.00 feet, a distance of 460.26 feet to a point of tangent; thence continuing along said 40 foot right of way South 46 degrees 05 minutes 15 seconds East, a distance of 580.05 feet to a point of curve; thence continuing along said 40 foot right of way on a circular curve to the left having a radius of 340.00 feet, a distance of 265.45 feet to the point of beginning, containing 2.5964 Acres of land, more or less.

#### Part of Parcel 6-4

Part of the North half of the Southeast Quarter of Section 6, Township 29 North, Range 12 East, Allen County, Indiana, more particularly described as follows:

Commencing at the Southeast corner of the said southeast Quarter of Section 6, thence North 00 degrees 42 minutes 18 seconds West (bearing from Dalman Road Project INDOT STP-RS6602(4) and used for all subsequent bearings in this description) along the East line of the said Southeast Quarter of Section 6, said line being within the boundaries of the public highway known as Smith Road, a distance of 1326.91 feet to the Southeast corner of the said North half of the Southeast Quarter, thence South 88 degrees 59 minutes 17 seconds West (south 89 degrees 00 minutes 12 seconds West from Recorded Document #970038227 owner County of Allen, State of Indiana) along the South line of

the said North half of the Southeast Quarter a distance of 79.49 feet to the point of beginning, said point being on the Westerly right of way line of Smith Road relocated; thence continuing South 88 degrees 59 minutes 17 seconds West along the said South line of the North half of the Southeast Quarter a distance of 661.77 feet; thence North 00 degrees 42 minutes 18 seconds West and parallel with said East line of the Southeast Quarter a distance of 290.00 feet; thence North 88 degrees 59 minutes 17 seconds East and parallel with the said South line of the North half of the Southeast Quarter a distance of 518.05 feet to a point on the said Westerly right of way line of Smith Road relocated; thence South 35 degrees 31 minutes 41 seconds East along said right of way line a distance of 77.30 feet; thence South 27 degrees 48 minutes 13 seconds East along said Westerly right of way line a distance of 187.36 feet; thence South 14 degrees 16 minutes 14 seconds East along the said Westerly right of way line a distance of 60.67 feet to the point of beginning, containing 4.00 acres of land more or less.

Issued in Des Plaines, Illinois on August 24, 2004.

**Philip M. Smithmeyer,**

*Manager, Chicago Airports District Office, FAA, Great Lakes Region.*

[FR Doc. 04-20177 Filed 9-2-04; 8:45 am]

**BILLING CODE 4910-13-M**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

[Policy Statement No. ANE-2000-33.87-R3]

#### Policy for 14 CFR 33.87, Endurance Test

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of issuance; policy statement.

**SUMMARY:** The Federal Aviation Administration (FAA) announces the availability of policy for 14 CFR 33.87, Endurance test.

**DATES:** The FAA issued policy statement number ANE-2000-33.87-R3 on August 24, 2004.

#### FOR FURTHER INFORMATION CONTACT:

Karen Grant, FAA, Engine and Propeller Standards Staff, ANE-110, 12 New England Executive Park, Burlington, MA 01803; e-mail: [karen.m.grant@faa.gov](mailto:karen.m.grant@faa.gov); telephone: (781) 238-7119; fax: (781) 238-7199. The policy statement is available on the Internet at the following address: <http://www.airweb.faa.gov/rgl>. If you do not have access to the Internet,

you may request a copy of the policy by contacting the individual listed in this section.

We have filed in the docket all comments we received, as well as a report summarizing each substantive public contact with FAA personnel concerning this policy. The docket is available for public inspection before and after the comment closing date. If you wish to review the docket in person, go to the above address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**SUPPLEMENTARY INFORMATION:** The FAA published a notice in the **Federal Register** on February 25, 2003 (68 FR 8794) to announce the availability of the proposed policy and invite interested parties to comment.

#### Background

The FAA was asked to consider a 2-minute gas temperature overshoot limit approval within the 5-minute steady state gas temperature limit associated with the takeoff power or thrust rating established under § 33.7, for certain engine operating conditions. This policy provides additional guidance to establish a uniform approach for Aircraft Certification Offices (ACOs) to evaluate and approve up to a 2-minute gas temperature overshoot limit caused by thermal mismatch of engine hardware. This policy does not create any new requirements.

**Authority:** 49 U.S.C. 106(g), 40113, 44701-44702, 44704.

Issued in Burlington, Massachusetts, on August 24, 2004.

**Robert Guyotte,**

*Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 04-20176 Filed 9-2-04; 8:45 am]

**BILLING CODE 4910-13-M**

## DEPARTMENT OF TRANSPORTATION

### Surface Transportation Board

[STB Docket No. AB-862X]

#### Twin State Railroad Company— Abandonment Exemption—in Caledonia and Essex Counties, VT

The Twin State Railroad Company (TSRR) has filed a notice of exemption under 49 CFR part 1152 subpart F—*Exempt Abandonments* to abandon approximately 20 route miles of rail line between milepost 0.057 in St. Johnsbury and Railroad Engineering Station 5503 at River Road (Town Road) in Lunenburg (Gilman), in Caledonia and