

provides insufficient bond resistance margin between the fuel pump motor/impeller and structure. The FAA is issuing this AD to address insufficient bond resistance margin between the fuel pump motor/impeller and structure. In the event of a fuel pump electrical fault, this condition might cause arcs at the existing fuel pump/tank interfaces and an ignition of fuel vapor in the wing fuel tank, which could result in a fuel tank explosion and consequent loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

For the purposes of this AD, the definitions specified in paragraphs (g)(1) through (4) of this AD apply.

(1) Group 1 airplanes: L/Ns 1 through 167 inclusive.

(2) Group 2 airplanes: L/Ns 168 through 971 inclusive.

(3) Group 3 airplanes: L/Ns 972 through 1161 inclusive.

(4) Group 4 airplanes: L/Ns 1162 through 1229 inclusive.

(h) Replacement, Installation, and Inspection

Within 60 months after the effective date of this AD, do the applicable actions specified in paragraphs (h)(1) through (4) of this AD, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747-28-2228, Revision 1, dated September 27, 2001.

(1) For Groups 1, 2, and 3 airplanes: Do the actions specified in paragraphs (h)(1)(i) and (ii) of this AD.

(i) Do a general visual inspection of the six override/jettison fuel pumps to determine if the bonding jumper has a one-piece braid or two-piece braid. If the bonding jumper has a one-piece braid, within 60 months after the effective date of this AD, replace the existing bonding jumper.

(ii) Install a second bonding jumper.

(2) For Groups 1, 2 and 3 airplanes with horizontal stabilizer fuel tanks: Do the actions specified in paragraphs (h)(2)(i) and (ii) of this AD.

(i) Do a general visual inspection of the two transfer/jettison fuel pumps to determine if the bonding jumper has a one-piece braid or a two-piece braid. If the bonding jumper has a one-piece braid, within 60 months after the effective date of this AD, replace the existing bonding jumper.

(ii) Install a second bonding jumper.

(3) For all airplanes: Replace the bonding jumpers on the auxiliary power unit (APU) fuel pump.

(4) For Groups 1 and 2 airplanes: Replace the bonding jumper on the electrical scavenge fuel pump.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your

principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

(1) For more information about this AD, contact Jeffrey Rothman, Aerospace Engineer, Propulsion Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3558; email: jeffrey.rothman@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on October 29, 2019.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-24329 Filed 11-7-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2019-0785; Airspace Docket No. 19-AEA-14]

Proposed Revocation of Class E Airspace; Grundy, VA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to remove Class E airspace at Grundy, VA, as Grundy Municipal Airport has been abandoned, and controlled airspace is

no longer required. This action would enhance the safety and management of controlled airspace within the national airspace system.

DATES: Comments must be received on or before December 23, 2019.

ADDRESSES: Send comments on this rule to: U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE, West Building Ground Floor, Room W12-140, Washington, DC 20590; Telephone: (800) 647-5527, or (202) 366-9826. You must identify the Docket No. FAA-2019-0785; Airspace Docket No. 19-AEA-14, at the beginning of your comments. You may also submit comments through the internet at <https://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays.

FAA Order 7400.11D, Airspace Designations and Reporting Points, and subsequent amendments can be viewed on line at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue, SW, Washington, DC, 20591; telephone: 202-267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11D at NARA, email fedreg.legal@nara.gov or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Ave, College Park, GA 30337; telephone (404) 305-6364.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This proposed rulemaking is promulgated under the authority described in Subtitle VII, part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would

remove Class E airspace extending upward from 700 feet above the surface at Grundy Municipal Airport, Grundy, VA, due to the closing of the airport.

Comments Invited

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–2019–0785 and Airspace Docket No. 19–AEA–14) and be submitted in triplicate to the DOT Docket Operations (see **ADDRESSES** section for address and phone number). You may also submit comments through the internet at <https://www.regulations.gov>.

Persons wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: “Comments to FAA Docket No. FAA–2019–0785; Airspace Docket No. 19–AEA–14.” The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. All comments submitted will be available for examination in the public docket both before and after the comment closing date. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded from and comments submitted through <https://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA’s web page at https://www.faa.gov/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the

ADDRESSES section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays. An informal docket may also be examined between 8:00 a.m. and 4:30 p.m., Monday through Friday, except federal holidays at the office of the Eastern Service Center, Federal Aviation Administration, room 350, 1701 Columbia Avenue, College Park, Georgia 30337.

Availability and Summary of Documents for Incorporation by Reference

This document proposes to amend FAA Order 7400.11D, Airspace Designations and Reporting Points, dated August 8, 2019, and effective September 15, 2019. FAA Order 7400.11D is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11D lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Proposal

The FAA proposes an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to remove Class E airspace extending upward from 700 feet above the surface at Grundy Municipal Airport, Grundy, VA, as the airport has closed. Therefore, the airspace is no longer necessary. This action would enhance the safety and management of controlled airspace within the national airspace system.

Class E airspace designations are published in Paragraph 6005 of FAA Order 7400.11D, dated August 8, 2019, and effective September 15, 2019, which is incorporated by reference in 14 CFR 71.1.

The Class E airspace designation listed in this document will be published subsequently in the Order.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

Regulatory Notices and Analyses

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies

and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

This proposal would be subject to an environmental analysis in accordance with FAA Order 1050.1F, “Environmental Impacts: Policies and Procedures” prior to any FAA final regulatory action.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

- 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

- 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.11D, Airspace Designations and Reporting Points, dated August 8, 2019, effective September 15, 2019, is amended as follows:

Paragraph 6005 Class E Airspace Areas Extending Upward from 700 feet or More Above the Surface of the Earth.

* * * * *

AEA VA E5 Grundy, VA [Removed]

Issued in College Park, Georgia, on October 30, 2019.

Debra Hogan,

Acting Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.

[FR Doc. 2019–24346 Filed 11–7–19; 8:45 am]

BILLING CODE 4910–13–P