# **Proposed Rules**

#### Federal Register

Vol. 89, No. 220

Thursday, November 14, 2024

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

### **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### 14 CFR Part 39

[Docket No. FAA-2024-2409; Project Identifier MCAI-2024-00410-T]

RIN 2120-AA64

### Airworthiness Directives; ATR-GIE Avions de Transport Régional Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking

(NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all ATR-GIE Avions de Transport Régional Model ATR42 and Model ATR72 airplanes. This proposed AD was prompted by the insufficient accuracy of a certain Angle of Attack (AoA) probe at low airspeeds which could lead to a delayed activation of the stick pusher in a flaps-extended configuration. This proposed AD would require replacing each affected part with a serviceable part, and would also prohibit the installation of affected parts, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by December 30, 2024.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.
  - Fax: 202–493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2024–2409; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA material identified in this proposed AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.
- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206–231–3220; email shahram.daneshmandi@faa.gov.

# SUPPLEMENTARY INFORMATION:

#### **Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the ADDRESSES section. Include "Docket No. FAA—2024—2409; Project Identifier MCAI—2024—00410—T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency

will also post a report summarizing each substantive verbal contact received about this NPRM.

#### **Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Shahram Daneshmandi, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206-231-3220; email shahram.daneshmandi@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

# **Background**

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2024-0140, dated July 12, 2024 (EASA AD 2024-0140) (also referred to as the MCAI), to correct an unsafe condition for all ATR-GIE Avions de Transport Régional Model ATR42-200, -300, -320, -400, and -500 airplanes; and Model ATR72-101, -102, -201, -202, -211, -212, and –212A airplanes. Model ATR42–400 airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this proposed AD therefore does not include those airplanes in the applicability. The MCAI states that during an acceptance flight of an airplane fitted with an affected part, an issue has been identified on the stall warning system. Further investigation highlighted an insufficient accuracy of the affected parts at low airspeeds, which could lead to a delayed activation of the stick pusher in a flaps-extended configuration. This condition, if not

corrected, in combination with flight at a high angle of attack, could lead to nonactivation of the stick pusher and ultimately to a loss of control of the airplane.

The FAA is proposing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2024–2409.

## Material Incorporated by Reference Under 1 CFR Part 51

EASA AD 2024–0140 specifies procedures for replacing each Angle of Attack (AoA) probe having Part Number (P/N) 0861GP with a serviceable part and would also prohibit the installation of the affected part. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

#### **FAA's Determination**

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

# Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2024–0140 described previously.

# **Explanation of Required Compliance Information**

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2024–0140 by

reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2024-0140 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2024-0140 does not mean that operators need to comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times,' compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in EASA AD 2024-0140. Material required by EASA AD 2024-0140 for compliance will be available at regulations.gov under Docket No. FAA-2024-2409 after the FAA final rule is published.

# **Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 77 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

#### **ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 5 work-hours × \$85 per hour = \$425	Up to \$151,633	Up to \$152,058	Up to \$11,708,466.

#### **Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order

13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

# The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

ATR-GIE Avions de Transport Régional: Docket No. FAA-2024-2409; Project Identifier MCAI-2024-00410-T.

# (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by December 30, 2024.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all ATR—GIE Avions de Transport Régional Model ATR42–200, –300, –320, and –500 airplanes; and Model ATR72–101, –102, –201, –202, –211, –212, and –212A airplanes, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

#### (e) Unsafe Condition

This AD was prompted by the insufficient accuracy of a certain Angle of Attack (AoA) probe at low airspeeds which could lead to a delayed activation of the stick pusher in flaps-extended configuration. The FAA is issuing this AD to address this unsafe condition, which if not addressed, could, in combination with flight at a high angle of attack, result in non-activation of the stick pusher and ultimately to a loss of control of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraph (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2024–0140, dated July 12, 2024 (EASA AD 2024–0140).

#### (h) Exceptions to EASA AD 2024-0140

- (1) Where EASA AD 2024–0140 refers to its effective date, this AD requires using the effective date of this AD.
- (2) Where EASA AD 2024–0140 defines a serviceable part as "AoA probe, eligible for installation, in accordance with ATR instructions, which is not an affected part," for this AD replace that text with "AoA probe, eligible for installation, which is not an affected part."
- (3) This AD does not adopt the "Remarks" section of EASA AD 2024–0140.

#### (i) No Reporting Requirement

Although the material referenced in EASA AD 2024–0140 requires the submittal of certain information to the manufacturer, this AD does not include that requirement.

#### (j) Additional AD Provisions

The following provisions also apply to this AD:

- (1) Alternative Methods of Compliance (AMOCs): The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.
- (2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or ATR—GIE Avions de Transport Régional's EASA Design

Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (k) Additional Information

For more information about this AD, contact Shahram Daneshmandi, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206–231–3220; email shahram.daneshmandi@faa.gov.

#### (l) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.
- (i) European Union Aviation Safety Agency (EASA) AD 2024–0140, dated July 12, 2024.
  - (ii) [Reserved]
- (3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.
- (4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.
- (5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locationsoremailfr.inspection@nara.gov.

Issued on November 7, 2024.

### Victor Wicklund.

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2024–26260 Filed 11–13–24; 8:45 am]

BILLING CODE 4910-13-P

# DEPARTMENT OF HOMELAND SECURITY

#### **Coast Guard**

#### 33 CFR Part 165

[Docket Number USCG-2024-1001] RIN 1625-AA00

Safety Zone; Bay St. Louis, MS

**AGENCY:** Coast Guard, DHS.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** The Coast Guard is proposing to establish an annually recurring safety zone for certain waters of St. Louis Bay. This action is necessary to provide for the safety of life on these navigable waters near Bay St. Louis, MS during the Swim Across the Bay swim event. This proposed rulemaking would

prohibit persons and vessels from being in the safety zone unless authorized by the Captain of the Port Mobile or a designated representative. We invite your comments on this proposed rulemaking.

**DATES:** Comments and related material must be received by the Coast Guard on or before December 16, 2024.

ADDRESSES: You may submit comments identified by docket number USCG—2024—1001 using the Federal Decision-Making Portal at https://www.regulations.gov. See the "Public Participation and Request for

Comments" portion of the

**SUPPLEMENTARY INFORMATION** section for further instructions on submitting comments. This notice of proposed rulemaking with its plain-language, 100-word-or-less proposed rule summary will be available in this same docket.

FOR FURTHER INFORMATION CONTACT: If you have questions about this proposed rulemaking, call or email Lieutenant Lawrence J. Schad, Waterways Management Division, Sector Mobile, U.S. Coast Guard, telephone 251–441–5678, email sectormobilewaterways@uscg.mil.

#### SUPPLEMENTARY INFORMATION:

### I. Table of Abbreviations

CFR Code of Federal Regulations DHS Department of Homeland Security FR Federal Register NPRM Notice of proposed rulemaking § Section U.S.C. United States Code

# II. Background, Purpose, and Legal Basis

On July 11, 2024, an organization notified the Coast Guard that it will be conducting Swim Across the Bay, an annual recurring swim event that will occur on the 3rd or 4th Saturday or Sunday of September in St. Louis Bay. The Captain of the Port Sector Mobile (COTP) has determined that potential hazards associated with the swim event would be a safety concern for non-participants within the designated area, extending the entire width of the channel, approximately 1 mile south of the Hwy. 90 Bridge in Bay St. Louis, MS.

The purpose of this rulemaking is to ensure the safety of participants, authorized vessels, and the navigable waters within the course of the swim before, during and after the scheduled marine event. The Coast Guard is proposing this rulemaking under authority in 46 U.S.C. 70034.

# III. Discussion of Proposed Rule

The COTP is proposing to establish a permanent safety zone to protect