The correct marking required by FMVSS No. 109 is as follows: "Tread Plies: 2 Polyester + 2 Steel + 1 Polyamide, Sidewall Plies: 2 Polyester.

"Michelin stated that the noncompliant tires were actually constructed with more sidewall and tread plies than indicated on the sidewall marking (2 tread and sidewall plies rather than 1). Therefore, this noncompliance is particularly unlikely to have an adverse safety impact and is clearly inconsequential to motor vehicle safety. The noncompliant tires meet or exceed all performance requirements of FMVSS No. 109 and will have no impact on the operational performance or safety of vehicles on which these tires are mounted.

Interested persons are invited to submit written data, views, and arguments on the application described above. Comments should refer to the docket number and be submitted to: U.S. Department of Transportation, Docket Management, Room PL–401, 400 Seventh Street, SW., Washington, DC 20590. It is requested that two copies be submitted.

All comments received before the close of business on the closing date indicated below will be considered. The application and supporting materials, and all comments received after the closing date, will also be filed and will be considered to the extent possible. When the application is granted or denied, the notice will be published in the **Federal Register** pursuant to the authority indicated below. Comment closing date: January 2, 2003.

(49 U.S.C. 301118, 301120; delegations of authority at 49 CFR 1.50 and 501.8)

Issued on: November 26, 2002.

Stephen R. Kratzke,

Associate Administrator for Rulemaking. [FR Doc. 02–30522 Filed 12–2–02; 8:45 am] BILLING CODE 4910–59–P

DEPARTMENT OF TRANSPORTATION

Research and Special Programs Administration

Notification of the Susceptibility to Premature Brittle-Like Cracking of Older Plastic Pipe

AGENCY: Research and Special Programs Administration (RSPA), DOT.

ACTION: Notice; correction.

SUMMARY: In the Federal Register of November 26, 2002, (67 FR 70806) the Research and Special Programs Administration (RSPA) published a notice document issuing an advisory bulletin on the susceptibility to premature brittle-like cracking of older plastic pipe (ADB-02-7). RSPA is submitting this correction notice to reflect minor wording changes and include a website address.

EFFECTIVE DATE: This correction takes effect November 26, 2002.

FOR FURTHER INFORMATION CONTACT:

Gopala K. Vinjamuri, (202) 366–4503, or by email at

gopala.vinjamuri@rspa.dot.gov.

SUPPLEMENTARY INFORMATION:

Correction

The last sentence in the first paragraph of the Supplementary Information heading under I. Background, reads:

Copies of this report may be obtained by calling NTSB's Public Inquiry Office at 202–314–6551.

We are revising this sentence to add NTSB's website address. The sentence is revised to read as follows:

Copies of this report may be obtained by calling NTSB's Public Inquiry Office at 202–314–6551, or on the NTSB website at *www.ntsb.gov*.

In the fourth paragraph under **SUPPLEMENTARY INFORMATION**, the first sentence reads:

In the fourth paragraph under Supplementary Information, the third sentence reads:

NTSB alleges that Remove the word "alleges" and replace with the word "concluded".

Under II. Advisory Bulletin (ADB-02-7) of the SUPPLEMENTARY INFORMATION heading, in the second paragraph under *Advisory*. The fourth sentence reads:

These older polyethylene pipe materials include the following:

The sentence is revised to read as follows:

These older polyethylene pipe materials include, but are not limited to:

Issued in Washington, DC on November 27, 2002.

James K. O'Steen,

 $\label{lem:poly} \textit{Deputy Associate Administrator for Pipeline} \\ \textit{Safety}.$

[FR Doc. 02–30615 Filed 12–2–02; 8:45 am] **BILLING CODE 4910–60–P**

DEPARTMENT OF THE TREASURY

Submission for OMB Review; Comment Request

November 22, 2002.

The Department of Treasury has submitted the following public information collection requirement(s) to OMB for review and clearance under the Paperwork Reduction Act of 1995, Public Law 104–13. Copies of the submission(s) may be obtained by calling the Treasury Bureau Clearance Officer listed. Comments regarding this information collection should be addressed to the OMB reviewer listed and to the Treasury Department Clearance Officer, Department of the Treasury, Room 11000, 1750 Pennsylvania Avenue, NW., Washington, DC 20220.

Dates: Written comments should be received on or before January 2, 2003 to be assured of consideration.

Internal Revenue Service (IRS)

OMB Number: 1545-0499.

Form Number: IRS Form 5305-SEP.

Type of Review: Extension.

Title: Simplified Employee Pension-Individual Retirement Accounts Contribution Agreement.

Description: This form is used by an employer to make an agreement to provide benefits to all employees under a Simplified Employee Pension (SEP) described in section 408(k). This form is not filed with the IRS but to be retained in the employer's records as proof establishing a SEP and justifying a deduction for contributions to the SEP. The data is used to verify the deduction.

Respondents: Business or other forprofit.

Estimated Number of Respondents/ Recordkeepers: 100,000.

Estimated Burden Hours Per Respondent/Recordkeeper:

Recordkeeping	1 hr., 40 min.
Learning about the law or	
the form	1 hr., 35 min.
Preparing the form	1 hr., 41 min.

 $Frequency\ of\ Response: \ On\ occasion.$

Estimated Total Reporting/ Recordkeeping Burden: 495,000 hours.

Clearance Officer: Glenn Kirkland, (202) 622–3428, Internal Revenue Service, Room 6411–03, 1111 Constitution Avenue, NW., Washington, DC 20224.

OMB Reviewer: Joseph F. Lackey, Jr., (202) 395–7316, Office of Management and Budget, Room 10235, New Executive Office Building, Washington, DC 20503.

Lois K. Holland.

Departmental Reports Management Officer. [FR Doc. 02–30575 Filed 12–2–02; 8:45 am]

BILLING CODE 4830-01-P