

(87 FR 72871) is delayed until further notice. The FAA will publish a document in the **Federal Register** announcing the new effective date. The Director of the Federal Register approved this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Background

The FAA published a final rule in the **Federal Register** for Docket No. FAA-2022-0245 (87 FR 72871, November 28, 2022), establishing RNAV route T-380 in the vicinity of Emmonak, AK. The effective date for that final rule is April 20, 2023. Subsequent to the final rule, it was determined that the required flight inspection of T-380 was not completed due to weather conditions. The onset of winter weather conditions in Alaska will further impact the completion of flight inspections.

To facilitate the safe and continuous use of existing air traffic procedures and allow sufficient time for completion of the required flight inspection of route T-380, the effective date of this rule is delayed until further notice. The FAA will publish a document in the **Federal Register** announcing the new effective date.

Delay of Effective Date

Accordingly, pursuant to the authority delegated to me, the effective date of the final rule, Airspace Docket No. 19-AAL-49, as published in the **Federal Register** on November 28, 2022 (87 FR 72871), is hereby delayed until further notice.

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., P. 389.

* * * * *

Issued in Washington, DC, on March 3, 2023.

Brian Konie,

Acting Manager, Airspace Rules and Regulations.

[FR Doc. 2023-04769 Filed 3-8-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 31474; Amdt. No. 4049]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This rule establishes, amends, suspends, or removes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures (ODPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective March 9, 2023. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of March 9, 2023.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination

1. U.S. Department of Transportation, Docket Ops-M30, 1200 New Jersey Avenue SE, West Bldg., Ground Floor, Washington, DC 20590-0001.

2. The FAA Air Traffic Organization Service Area in which the affected airport is located;

3. The office of Aeronautical Information Services, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Availability

All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit the National Flight Data Center at nfdc.faa.gov to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from the FAA Air Traffic Organization Service Area in which the affected airport is located.

FOR FURTHER INFORMATION CONTACT:

Thomas J. Nichols, Flight Procedures and Airspace Group, Flight Technologies and Procedures Division, Flight Standards Service, Federal Aviation Administration. Mailing Address: FAA Mike Monroney Aeronautical Center, Flight Procedures and Airspace Group, 6500 South MacArthur Blvd., STB Annex, Bldg. 26, Room 217, Oklahoma City, OK 73099. Telephone (405) 954-1139.

SUPPLEMENTARY INFORMATION: This rule amends 14 CFR part 97 by establishing, amending, suspending, or removes SIAPs, Takeoff Minimums and/or ODPs. The complete regulatory description of each SIAP and its associated Takeoff Minimums or ODP for an identified airport is listed on FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR part 97.20. The applicable FAA Forms 8260-3, 8260-4, 8260-5, 8260-15A, 8260-15B, when required by an entry on 8260-15A, and 8260-15C.

The large number of SIAPs, Takeoff Minimums and ODPs, their complex nature, and the need for a special format make publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, Takeoff Minimums or ODPs, but instead refer to their graphic depiction on charts printed by publishers or aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP, Takeoff Minimums and ODP listed on FAA form documents is unnecessary. This amendment provides the affected CFR sections and specifies the typed of SIAPs, Takeoff Minimums and ODPs with their applicable effective dates. This amendment also identifies the airport and its location, the procedure, and the amendment number.

Availability and Summary of Material Incorporated by Reference

The material incorporated by reference is publicly available as listed in the **ADDRESSES** section.

The material incorporated by reference describes SIAPs, Takeoff

Minimums and/or ODPs as identified in the amendatory language for Part 97 of this final rule.

The Rule

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP, Takeoff Minimums and ODP as amended in the transmittal. Some SIAP and Takeoff Minimums and textual ODP amendments may have been issued previously by the FAA in a Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flights safety relating directly to published aeronautical charts.

The circumstances that created the need for some SIAP and Takeoff Minimums and ODP amendments may require making them effective in less than 30 days. For the remaining SIAPs and Takeoff Minimums and ODPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs and Takeoff Minimums and ODPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these SIAPs and Takeoff Minimums and ODPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs, Takeoff Minimums and ODPs, and safety in air commerce, I find that notice and public procedure under 5 U.S.C. 553(b) are impracticable and contrary to the public interest and, where applicable, under 5 U.S.C. 553(d), good cause exists for making some SIAPs effective in less than 30 days.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Lists of Subjects in 14 CFR Part 97

Air traffic control, Airports, Incorporation by reference, Navigation (air).

Issued in Washington, DC, on February 17, 2023.

Thomas J. Nichols,

Manager, Aviation Safety, Flight Standards Service, Standards Section, Flight Procedures & Airspace Group, Flight Technologies & Procedures Division.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me, 14 CFR part 97 is amended by establishing, amending, suspending, or removing Standard Instrument Approach Procedures and/or Takeoff Minimums and Obstacle Departure Procedures effective at 0901 UTC on the dates specified, as follows:

PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

- 1. The authority citation for part 97 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44701, 44719, 44721–44722.

- 2. Part 97 is amended to read as follows:

Effective 23 March 2023

Cape Girardeau, MO, KCGI, Takeoff Minimums and Obstacle DP, Amdt 10

Effective 20 April 2023

Colusa, CA, O08, Takeoff Minimums and Obstacle DP, Orig-B

Tampa, FL, KTPA, ILS OR LOC RWY 19L, ILS RWY 19L (SA CAT I), ILS RWY 19L (CAT II), Amdt 41

Blairsville, GA, KDZJ, RNAV (GPS) RWY 8, Amdt 1

Blairsville, GA, KDZJ, Takeoff Minimums and Obstacle DP, Amdt 1

Greensboro, GA, KCPP, LOC RWY 25, Amdt 3F

Greensboro, GA, KCPP, RNAV (GPS) RWY 7, Amdt 1G

Greensboro, GA, KCPP, RNAV (GPS) RWY 25, Amdt 2B

Greensboro, GA, KCPP, Takeoff Minimums and Obstacle DP, Amdt 3A

Greensboro, GA, KCPP, VOR–B, Amdt 3B

Portland, IN, KPLD, RNAV (GPS) RWY 9, Amdt 2A

Rochester, MN, KRST, RADAR–1, Amdt 9

Rochester, MN, KRST, RNAV (GPS) RWY 3, Amdt 3E

Rochester, MN, KRST, RNAV (GPS) RWY 21, Amdt 2E

Rochester, MN, KRST, Takeoff Minimums and Obstacle DP, Orig–A

Fort Leonard Wood, MO, KTBN, RNAV (GPS) RWY 33, Amdt 2

Hazen, ND, KHZE, RNAV (GPS) RWY 15, Amdt 1B

Hazen, ND, KHZE, RNAV (GPS) RWY 33, Amdt 1B

Hazen, ND, KHZE, Takeoff Minimums and Obstacle DP, Amdt 1

Newark, NJ, KEWR, GLS RWY 22L, Amdt 1A

Rochester, NY, KROC, ILS OR LOC RWY 22, Amdt 9

Allentown, PA, KABE, VOR–A, Amdt 10A, CANCELED

Fort Worth, TX, KAFW, ILS OR LOC RWY 16L, ILS RWY 16L (CAT II), ILS RWY 16L (CAT III), Amdt 8

Fort Worth, TX, KAFW, ILS OR LOC RWY 34R, Amdt 8

Houston, TX, KIAH, GLS RWY 26R, Amdt 2A

[FR Doc. 2023–04803 Filed 3–8–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 31475; Amdt. No. 4050]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This rule amends, suspends, or removes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide for the safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective March 9, 2023. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of March 9, 2023.

ADDRESSES: Availability of matter incorporated by reference in the amendment is as follows:

For Examination

1. U.S. Department of Transportation, Docket Ops–M30, 1200 New Jersey Avenue SE, West Bldg., Ground Floor, Washington, DC 20590–0001;

2. The FAA Air Traffic Organization Service Area in which the affected airport is located;

3. The office of Aeronautical Information Services, 6500 South