

included pursuant to the requirements of Section 567.4.

The agency believes the true measure of inconsequentiality with respect to the noncompliance with FMVSS No. 120, paragraph S5.3, is whether the GVWR and GAWR information is readily available to consumers. One of the reasons that FMVSS No. 120 requires that both labels include the GVWR and GAWR information is the fact that the labels need not be located close to one another. According to Volkswagen, the vehicle certification label, which includes the GVWR and GAWR, and the tire information label are adjacent to one another on the noncompliant vehicles. Both labels are mounted on the driver's side B-pillar, negating the need for both labels to include the GVWR and GAWR information. The agency believes this reduces the likelihood that consumers would not be able to locate this information.

In consideration of the foregoing, NHTSA has decided that the applicant has met its burden of persuasion that the noncompliance described is inconsequential to motor vehicle safety. Accordingly, Volkswagen's application is hereby granted, and the applicant is exempted from the obligation of providing notification of, and a remedy for, the noncompliance.

(49 U.S.C. 30118, 30120; delegations of authority at 49 CFR 1.50 and 501.8)

Issued on: April 17, 2002.

**Stephen R. Kratzke,**  
*Associate Administrator for Safety Performance Standards.*

[FR Doc. 02-9830 Filed 4-22-02; 8:45 am]

BILLING CODE 4910-59-P

## DEPARTMENT OF TRANSPORTATION

### National Highway Traffic Safety Administration

[Docket No. NHTSA 2001-10695; Notice 2]

#### Volkswagen of America, Inc., Grant of Application for Decision of Inconsequential Noncompliance

Volkswagen of America, Inc., (Volkswagen) has determined that approximately 5,772 vehicles produced between July 2000 and June 22, 2001, do not meet the labeling requirements of paragraph S5.3(b) of Federal Motor Vehicle Safety Standard (FMVSS) No. 120 "Tire Selection and Rims for Motor Vehicles Other than Passenger Cars." Pursuant to 49 U.S.C. 30118(d) and 30120(h), Volkswagen has petitioned for a determination that this noncompliance is inconsequential to motor vehicle safety and has filed an

appropriate report pursuant to 49 CFR part 573, "Defect and Noncompliance Reports."

Notice of receipt of the application was published, with a 30-day comment period, on October 3, 2001, in the **Federal Register** (66 FR 50500). NHTSA received no comments.

The noncompliant vehicles were produced by Audi AG and were imported by Volkswagen. The noncompliance relates to MPVs produced and imported under the Audi Allroad Quattro model designation. On these vehicles, the manufacturer did not include tire size and rim designation on the certification label specified by 49 CFR part 567, but rather utilized the option in S5.3(b) of FMVSS 120 to provide that information on the separate tire information label. In doing so however, Volkswagen neglected to include the required vehicle GVWR and GAWR information on the tire information label.

Volkswagen believes that the failure of the tire information label to include the vehicle weight values is inconsequential to motor vehicle safety because the weights are included on the certification label and both labels are mounted on the driver side B-pillar of the vehicle. Consumers interested in the vehicle weights would be able to find the values on the certification label where they are included pursuant to the requirements of Section 567.4.

The agency believes the true measure of inconsequentiality with respect to the noncompliance with FMVSS No. 120, paragraph S5.3, is whether the GVWR and GAWR information is readily available to consumers. One of the reasons that FMVSS No. 120 requires that both labels include the GVWR and GAWR information is the fact that the labels need not be located close to one another. According to Volkswagen, the vehicle certification label, which includes the GVWR and GAWR, and the tire information label are adjacent to one another on the noncompliant vehicles. Both labels are mounted on the driver's side B-pillar, negating the need for both labels to include the GVWR and GAWR information. The agency believes this reduces the likelihood that consumers would not be able to locate this information.

In consideration of the foregoing, NHTSA has decided that the applicant has met its burden of persuasion that the noncompliance described is inconsequential to motor vehicle safety. Accordingly, Volkswagen's application is hereby granted, and the applicant is exempted from the obligation of providing notification of, and a remedy for, the noncompliance.

(49 U.S.C. 30118, 30120; delegation of authority at 49 CFR 1.50 and 501.8)

Issued on: April 17, 2002.

**Stephen R. Kratzke,**

*Associate Administrator for Safety Performance Standards.*

[FR Doc. 02-9831 Filed 4-22-02; 8:45 am]

BILLING CODE 4910-59-P

## DEPARTMENT OF THE TREASURY

### Fiscal Service

#### Surety Companies Acceptable on Federal Bonds: Name Change and Change in State of Incorporation—Commercial Casualty Insurance Company of Georgia

**AGENCY:** Financial Management Service, Fiscal Service, Department of the Treasury.

**ACTION:** Notice.

**SUMMARY:** This is Supplement No. 20 to the Treasury Department Circular 570; 2001 Revision, published July 2, 2001, at 66 FR 35024.

**FOR FURTHER INFORMATION CONTACT:** Surety Bond Branch at (202) 874-6779.

#### SUPPLEMENTARY INFORMATION:

Commercial Casualty Insurance Company of Georgia has formally changed its name to Commercial Casualty Insurance Company of North Carolina and has redomesticated from the state of Georgia to the state of North Carolina, effective December 21, 2001. The Company was last listed as an acceptable surety on Federal bonds at 66 FR 35033, July 2, 2001.

Federal bond-approving officers should annotate their reference copies of the Treasury Circular 570, 2001 revision, on page 35033 to reflect this change.

The Circular may be viewed and downloaded through the Internet at <http://www.fms.treas.gov/c570/index.html>. A hard copy may be purchased from the Government Printing Office (GPO), Subscription Service, Washington, DC, telephone (202) 512-1800. When ordering the Circular from GPO, use the following stock number: 769-004-04067-1.

Questions concerning this notice may be directed to the U.S. Department of the Treasury, Financial Management Service, Funds Management Division, Surety Bond Branch, 3700 East-West Highway, Room 6F07, Hyattsville, MD 20782.

Dated: April 11, 2002.

**Wanda J. Rogers,**

*Director, Financial Accounting and Services Division, Financial Management Service.*

[FR Doc. 02-9924 Filed 4-22-02; 8:45 am]

BILLING CODE 4810-35-M

## DEPARTMENT OF THE TREASURY

### Fiscal Service

#### **Surety Companies Acceptable on Federal Bonds: Name Change—Chrysler Insurance Company**

**AGENCY:** Financial Management Service, Fiscal Service, Department of the Treasury.

**ACTION:** Notice.

**SUMMARY:** This is Supplement No. 23 to the Treasury Department Circular 570; 2001 Revision, published July 2, 2001, at 66 FR 35024.

**FOR FURTHER INFORMATION CONTACT:**

Surety Bond Branch at (202) 874-6765.

**SUPPLEMENTARY INFORMATION:**

CHRYSLER INSURANCE COMPANY, a Michigan corporation, has formally changed its name to DaimlerChrysler Insurance Company, effective June 30, 2001. The Company was last listed as an acceptable surety on Federal bonds at 66 FR 35032, July 2, 2001.

A Certificate of Authority as an acceptable surety on Federal bonds, dated today, is hereby issued under Sections 9304 to 9308 of Title 31 of the United States Code, to DaimlerChrysler Insurance Company. This new Certificate replaces the Certificate of Authority issued to the Company under its former name. The underwriting limitation of \$19,610,000 established for the June 30, 2002.

Certificates of Authority expire on June 30, each year, unless revoked prior to that date. The Certificates are subject to subsequent annual renewal as long as the Company remains qualified (31 CFR part 223). A list of qualified companies is published annually as of July 1, in the Department Circular 570, which outlines details as to underwriting limitations, areas in which licensed to transact surety business and other information. Federal bond-approving officers should annotate their reference copies of the Treasury Circular 570, 2001 Revisions, at page 35032 to reflect this change.

The Circular may be viewed and downloaded through the Internet at <http://www.fms.treas.gov/c570/index.html>. A hard copy may be purchased from the Government Printing Office (GPO), Subscription Service, Washington, DC, telephone (202) 512-1800. When ordering the

Circular from GPO, use the following stock number: 769-004-04067-1.

Questions concerning this notice may be directed to the U.S. Department of the Treasury, Financial Management Service, Financial Accounting and Services Division, Surety Bond Branch, 3700 East-West Highway, Room 6F07, Hyattsville, MD 20782.

Dated: April 15, 2002.

**Wanda J. Rogers,**

*Director, Financial Accounting and Services Division, Financial Management Service.*

[FR Doc. 02-9927 Filed 4-22-02; 8:45 am]

BILLING CODE 4810-35-M

## DEPARTMENT OF THE TREASURY

### Fiscal Service

#### **Surety Companies Acceptable on Federal Bonds: Name Change—Employers Insurance of Wausau a Mutual Company**

**AGENCY:** Financial Management Service, Fiscal Service, Department of the Treasury.

**ACTION:** Notice.

**SUMMARY:** This is Supplement No. 21 to the Treasury Department Circular 570; 2001 Revision, published July 2, 2001, at 66 FR 35024.

**FOR FURTHER INFORMATION CONTACT:**

Surety Bond Branch at (202) 874-6765.

**SUPPLEMENTARY INFORMATION:**

EMPLOYERS INSURANCE OF WAUSAU A Mutual Company, a Wisconsin corporation, has formally changed its name to Employers Insurance Company of Wausau, effective November 21, 2001. The Company was last listed as an acceptable surety on Federal bonds at 66 FR 35034, July 2, 2001.

A Certificate of Authority as an acceptable surety on Federal bonds, dated today, is hereby issued under Sections 9304 to 9308 of Title 31 of the United States Code, to Employers Insurance Company of Wausau, Wausau, Wisconsin. This new Certificate replaces the Certificate of Authority issued to the Company under its former name. The underwriting limitation of \$5,050,000 established for the Company as of July 2, 2001, remains unchanged until June 30, 2002.

Certificates of Authority expire on June 30, each year, unless revoked prior to that date. The Certificates are subject to subsequent annual renewal as long as the Company remains qualified (31 CFR part 223). A list of qualified companies is published annually as of July 1, in the Department Circular 570, which outlines details as to underwriting limitations, areas in which licensed to transact surety business and other

information. Federal bond-approving officers should annotate their reference copies of the Treasury Circular 570, which outlines details as to underwriting limitations, areas in which licensed to transact surety business and other information. Federal bond-approving officers should annotate their reference copies of the Treasury Circular 570, 2001 Revision, at page 35034 to reflect this change.

The Circular may be viewed and downloaded through the Internet (<http://fms.trea.gov/c570/index.html>). A hard copy may be purchased from the Government Printing Office (GPO), Subscription Service, Washington, DC, telephone (202) 512-1800. When ordered the Circular from GPO, use the following stock number: 769-004-04067-1.

Questions concerning this notice may be delivered to the U.S. Department of the Treasury, Financial Management Service, Financial Accounting and Services Division, Surety Bond Branch, 3700 East-West Highway, Room 6F07, Hyattsville, MD 20782.

Dated: April 11, 2002.

**Wanda J. Rogers,**

*Director, Financial Accounting and Services Division, Financial Management Service.*

[FR Doc. 02-9925 Filed 4-22-02; 8:45 am]

BILLING CODE 4810-35-M

## DEPARTMENT OF THE TREASURY

### Fiscal Service

#### **Surety Companies Acceptable on Federal Bonds: Pacific Indemnity Insurance Company**

**AGENCY:** Financial Management Service, Fiscal Service, Department of the Treasury.

**ACTION:** Notice.

**SUMMARY:** This is Supplement No. 19 to the Treasury Department Circular 570; 2001 Revision, published July 2, 2001, at 66 FR 35024.

**FOR FURTHER INFORMATION CONTACT:**

Surety Bond Branch at (202) 874-7116.

**SUPPLEMENTARY INFORMATION:**

A Certificate of Authority as an acceptable surety on Federal bonds is hereby issued to the following Company under 31 U.S.C. 9304 to 9308. Federal bond-approving officers should annotate their reference copies of the Treasury Circular 570, 2001 Revision, on page 35050 to reflect this addition:

Company Name: Pacific Indemnity Insurance Company, Business Address: 378 W. O'Brien Drive, Agana, and GU 96932, Phone: (671) 477-8801, Underwriting Limitation b/: \$302,000, Surety Licenses c/: GU. Incorporated In: Guam.