**ACTION:** Notice of Availability.

SUMMARY: The FAA, Eastern Service Area is issuing this notice to advise the public of the availability of the Categorical Exclusion/Record of Decision (CATEX/ROD) for the Newark Liberty International Airport EWR RNAV (GPS) X Runway 29 (RWY 29) procedure. The FAA reviewed the action and determined it to be categorically excluded from further environmental documentation.

FOR FURTHER INFORMATION CONTACT: Mr. Ryan W. Almasy, Federal Aviation Administration, Operations Support Group, Eastern Service Center, 1701 Columbia Avenue, College Park, Georgia 30337, (404) 305–5601 or http://www.faa.gov/air\_traffic/environmental issues/.

SUPPLEMENTARY INFORMATION: The EWR RNAV (GPS) X RWY 29 procedure at Newark Liberty International Airport will be used as an overflow procedure when EWR is landing RWY 4Left/Right and is anticipated to be used only between the hours of 7:00 a.m. and 10:00 p.m., by approximately 1,700 aircraft annually. This is approximately 3 percent of total landing operation on RWY 29. The FAA reviewed the action and determined it to be categorically excluded from further environmental documentation according to FAA Order 1050.1F, Environmental Impacts: Policies and Procedures. The applicable categorical exclusion is  $\S 5-6.5(q.)$ .

Issued in College Park, Georgia, on April 13, 2017.

#### Geoff Lelliott,

Acting Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.

[FR Doc. 2017–08101 Filed 4–20–17; 8:45 am] **BILLING CODE 4910–13–P** 

## **DEPARTMENT OF TRANSPORTATION**

Federal Aviation Administration [Summary Notice No. PE-2017-18]

## Petition for Exemption; Summary of Petition Received

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of petition for exemption

received.

**SUMMARY:** This notice contains a summary of a petition seeking relief from specified requirements of Title 14, Code of Federal Regulations (14 CFR). The purpose of this notice is to improve the public's awareness of, and participation in, this aspect of the FAA's regulatory activities. Neither publication

of this notice nor the inclusion or omission of information in the summary is intended to affect the legal status of the petition or its final disposition.

**DATES:** Comments on this petition must identify the petition docket number involved and must be received on or before May 11, 2017.

**ADDRESSES:** You may send comments identified by docket number FAA—2017—0180 using any of the following methods:

- Government-wide rulemaking Web site: Go to http://www.regulations.gov and follow the instructions for sending your comments digitally.
- *Mail:* Send comments to the Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12–140, Washington, DC 20590.
- *Fax:* Fax comments to the Docket Management Facility at 202–493–2251.
- Hand Delivery: Bring comments to the Docket Management Facility in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Privacy: We will post all comments we receive, without change, to http://www.regulations.gov, including any personal information you provide. Using the search function of our docket Web site, anyone can find and read the comments received into any of our dockets, including the name of the individual sending the comment (or signing the comment for an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the Federal Register published on April 11, 2000 (65 FR 19477–78).

Docket: To read background documents or comments received, go to http://www.regulations.gov at any time or to the Docket Management Facility in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

# FOR FURTHER INFORMATION CONTACT:

Lynette Mitterer, ANM–113, Federal Aviation Administration, 1601 Lind Avenue SW., Renton, WA 98057–3356, email *Lynette.Mitterer@faa.gov*, phone (425) 227–1047.

This notice is published pursuant to 14 CFR 11.85.

Issued in Renton, Washington, on April 11, 2017.

### Victor Wicklund,

Manager, Transport Standards Staff.

### **Petition for Exemption**

Docket No.: FAA-2017-0180.

Petitioner: L-3 Communications
Integrated Systems, L.P.

Section of 14 CFR Affected: §§ 25.562 and 25.785(b).

Description of Relief Sought: Allow certification of a medical stretcher carrier for transport of persons whose medical condition dictates such accommodation.

[FR Doc. 2017–07610 Filed 4–20–17; 8:45 am] BILLING CODE 4910–13–P

## **DEPARTMENT OF TRANSPORTATION**

## Federal Motor Carrier Safety Administration

[Docket No. FMCSA-2010-0177]

Parts and Accessories Necessary for Safe Operation; Exemption Renewal for the Flatbed Carrier Safety Group

**AGENCY:** Federal Motor Carrier Safety Administration (FMCSA), DOT.

**ACTION:** Notice of renewal of exemption; request for comments.

**SUMMARY:** FMCSA renews the Flatbed Carrier Safety Group's (FCSG) exemption which allows the securement of metal coils on a flatbed vehicle, in a sided vehicle, or in an intermodal container loaded with eyes crosswise, grouped in rows, in which the coils are loaded to contact each other in the longitudinal direction. Motor carriers may continue to use the pre-January 1, 2004, cargo securement regulations for the transportation of groups of metal coils with eyes crosswise, as this loading configuration is not currently covered under the Agency's commodityspecific rules for securing metal coils in 49 CFR 393.120. The Agency has concluded that granting this exemption renewal will maintain a level of safety that is equivalent to, or greater than, the level of safety achieved without the exemption.

**DATES:** This decision is effective April 21, 2017. Comments on the decision must be received on or before May 22, 2017.

**ADDRESSES:** You may submit comments bearing the Federal Docket Management System (FDMS) Docket ID FMCSA—2010–0177 using any of the following methods:

• Web site: http:// www.regulations.gov. Follow the