

(Catalog of Federal Domestic Assistance Program Number 20.205, Highway Research, Planning and Construction. The regulations impending Executive Order 12372 regarding intergovernmental consultation on Federal programs and activities apply to this program)

Issued on: July 30, 2004.

Jeffrey Berna,

Environmental Specialist, Salt Lake City, Utah.

[FR Doc. 04-17863 Filed 8-4-04; 8:45 am]

BILLING CODE 4910-22-M

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2004-18755; Notice 1]

Coupled Products, Inc., Receipt of Petition for Decision of Inconsequential Noncompliance

Coupled Products, Inc. (Coupled Products) has determined that certain hydraulic brake hose assemblies that it produced do not comply with S5.3.4 of 49 CFR 571.106, Federal Motor Vehicle Safety Standard (FMVSS) No. 106, "Brake hoses." Coupled Products has filed an appropriate report pursuant to 49 CFR part 573, "Defect and Noncompliance Reports."

Pursuant to 49 U.S.C. 30118(d) and 30120(h), Coupled Products has petitioned for an exemption from the notification and remedy requirements of 49 U.S.C. chapter 301 on the basis that this noncompliance is inconsequential to motor vehicle safety.

This notice of receipt of Coupled Product's petition is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of the petition.

A total of approximately 24,622 brake hose assemblies, consisting of 3,092 assemblies bearing Part Number 5478 and 21,530 assemblies bearing Part Number 5480 are affected. S5.3.4 of FMVSS No. 106, tensile strength, requires that "a hydraulic brake hose assembly shall withstand a pull of 325 pounds without separation of the hose from its end fittings." The potentially affected hoses were manufactured using a "straight cup" procedure rather than the appropriate "step cup" procedure. Compliance testing by the petitioner of eight sample hose assemblies from two separate manufacturing lots of these hoses revealed that seven of the eight samples experienced hose separation from the end fittings at from 224 to 317 pounds.

Coupled Products believes that the noncompliance is inconsequential to

motor vehicle safety and that no corrective action is warranted. Coupled Products states that these hoses were shipped exclusively to EZ Loader, a manufacturer of boat trailers, the sole customer of the affected hoses. Coupled Products states:

Both Part Numbers 5478 and 5480 are utilized in specific boat trailer applications of a single trailer manufacturer. * * * [T]he routing and placement of the hoses on the particular boat trailers involved, and the shielded nature of the end fittings on those trailers are such that a linear, end-to-end "straight pull" on the hose assembly, such as that specified in the FMVSS No. 106 tensile strength test procedure, is unlikely to occur in real-world use. Because of the manner in which these hose assemblies are installed, rather than a "straight pull," it is more likely that the free length of the hose itself could be entangled or caught on a piece of road debris or other obstruction, resulting in a "side pull" on the assembly. With this potential in mind, [Coupled Products] conducted a side pull tensile test on a sample of the subject brake hose assemblies to simulate the possible effect of a side pull on the integrity of the assembly. This was accomplished by creating special mounting fixtures and apparatus to the standard testing equipment. * * * The "side pull" test results show that the tensile load achieved prior to the ends separating from the hose exceeded 530 pounds in each of the five samples tested—well in excess of the 325 pound requirement.

Coupled Products further states:

We believe that it is likely that in order for such a [side] pull to occur, the debris or obstacle in question would need to be of such size and/or weight that its encounter with the trailer would result in significant structural impact and thus have immediate effect on the operation of the trailer. While we have not been able to devise a test that would verify this theory, we believe that this is a realistic scenario. As a result, it seems likely that the trailer would likely incur an operational impact even before the possible loss of braking capability resulting from hose assembly failure.

The axles used in the trailers in question are stationary. Unlike sliding axles that are used in some trailers, the axles used in these trailers are in a fixed location. Consequently, the possibility that the sliding movement of the axle might result in unintended pull on the hose is remote. * * *

Because the braking system on the trailer is independent of the towing vehicle's braking system, any failure of the hose assembly due to excessive tensile force—unlikely as that may be—will not result in a loss of braking capability of the towing vehicle. Thus, in the unlikely event of separation, the driver would still retain full braking capability of the towing vehicle and would be able to stop the vehicle (although additional stopping distance may be required depending on the type of vehicle being used).

Coupled Products states that in other cases NHTSA determined that a FMVSS

No. 106 noncompliance is inconsequential where, because of the specific vehicle application involved, the hose assembly would not be subject to the type of forces specified in the standard. Coupled Product says:

See, e.g., General Motors Grant of Petition * * * 57 FR 1511 (January 14, 1992) (granting petition with respect to adhesion test noncompliance because, among other reasons, the "end use of the hoses was such that they were subject to pressure, not vacuum applications"), and *Mitsubishi Motors America Grant of Petition* * * * 57 FR 45868 (October 5, 1992) (same).

Coupled Products states it cannot estimate the percentage of the affected population that may be noncompliant, but the test results indicate that it is likely to be less than 100 percent. Coupled Products indicates that the problem has been corrected.

Interested persons are invited to submit written data, views, and arguments on the petition described above. Comments must refer to the docket and notice number cited at the beginning of this notice and be submitted by any of the following methods. Mail: Docket Management Facility, U.S. Department of Transportation, Nassif Building, Room PL-401, 400 Seventh Street, SW., Washington, DC 20590-0001. Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC. It is requested, but not required, that two copies of the comments be provided. The Docket Section is open on weekdays from 10 a.m. to 5 p.m. except Federal holidays. Comments may be submitted electronically by logging onto the Docket Management System Web site at <http://dms.dot.gov>. Click on "Help" to obtain instructions for filing the document electronically. Comments may be faxed to 1-202-493-2251, or may be submitted to the Federal eRulemaking Portal: go to <http://www.regulations.gov>. Follow the online instructions for submitting comments.

The petition, supporting materials, and all comments received before the close of business on the closing date indicated below will be filed and will be considered. All comments and supporting materials received after the closing date will also be filed and will be considered to the extent possible. When the petition is granted or denied, notice of the decision will be published in the **Federal Register** pursuant to the authority indicated below.

Comment closing date: September 7, 2004.

(Authority: 49 U.S.C. 30118, 30120; delegations of authority at CFR 1.50 and 501.8.)

Issued on: August 2, 2004.

Kenneth N. Weinstein,

Associate Administrator for Enforcement.

[FR Doc. 04-17932 Filed 8-4-04; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF THE TREASURY

Submission for OMB Review; Comment Request

July 29, 2004.

The Department of Treasury has submitted the following public information collection requirement(s) to OMB for review and clearance under the Paperwork Reduction Act of 1995, Public Law 104-13. Copies of the submission(s) may be obtained by calling the Treasury Bureau Clearance Officer listed. Comments regarding this information collection should be addressed to the OMB reviewer listed and to the Treasury Department Clearance Officer, Department of the Treasury, Room 11000, 1750 Pennsylvania Avenue, NW., Washington, DC 20220.

DATES: Written comments should be received on or before September 7, 2004 to be assured of consideration.

Internal Revenue Service (IRS)

OMB Number: 1545-0070.

Regulation Project Number: PS-163-84 Final.

Type of Review: Extension.

Title: Treatment of Transactions Between Partners and Partnerships.

Description: Section 707(a)(2) provides that if there is a transfer of money or property by a partner to a partnership, the transfer will be treated, in certain situations, as a disguised sale between the partner and the partnership. The regulations provide

that the partner or the partnership should disclose the transfers and certain attendant facts in some situations.

Respondents: Business of other for-profit.

Estimated Number of Respondents: 7,500.

Estimated Burden Hours Respondent: 20 minutes.

Frequency of response: Annually.

Estimated Total Reporting Burden: 2,500 hours.

Clearance Officer: Glenn P. Kirkland (202) 622-3428, Internal Revenue Service, Room 6411-03, 1111 Constitution Avenue, NW., Washington, DC 20224.

OMB Reviewer: Joseph F. Lackey, Jr. (202) 395-7316, Office of Management and Budget, Room 10235, New Executive Office Building, Washington, DC 20503.

Lois K. Holland,

Treasury PRA Clearance Officer.

[FR Doc. 04-17888 Filed 8-4-04; 8:45 am]

BILLING CODE 4830-01-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

Proposed Collection; Comment Request for Form 8847; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Correction to notice and request for comments.

SUMMARY: This document corrects a notice and request for comments that was published in the **Federal Register** on Monday, July 26, 2004 (66 FR 44567). This notice relates to the Department of the Treasury's invitation to the general public and other Federal

agencies to submit public comments on proposed and/or continuing information collections.

FOR FURTHER INFORMATION CONTACT:

Allan Hopkins, (202) 622-6665 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

The notice and request for comments that is the subject of this correction is required by the Paperwork Reduction Act of 1995, Public Law 104-13 (44 U.S.C. 3506(c)(2)(A)).

Need for Correction

As published, the notice and request for comments contains an error that may prove to be misleading and is in need of clarification.

Correction of Publication

Accordingly, the notice and request for comments which was the subject of FR Doc. 04-16968, is corrected as follows:

On page 44567, column 2, under the caption **SUPPLEMENTARY INFORMATION:**, the paragraph "Current Actions:" is corrected to read as follows: "Old lines 8b through 8i were collapsed into new line 8b. Lines 8j through 8m were renumbered lines 8c through 8f. IRS made this change to reduce taxpayer burden. Most filers do not have any of the credits on old lines b through i, thus the change reduces the number of lines they must consider to one".

LaNita Van Dyke,

Acting Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel, (Procedures and Administration).

[FR Doc. 04-17903 Filed 8-4-04; 8:45 am]

BILLING CODE 4830-01-P