holidays. The Dockets Office (telephone 1–800–647–5527) is on the plaza level of the NASSIF Building at the Department of Transportation at the above address. Also, you may review public dockets on the Internet at http://dms.dot.gov.

# FOR FURTHER INFORMATION CONTACT:

Forest Rawls (202) 267–8033, Sandy Buchanan-Sumter (202) 267–7271, or Vanessa Wilkins (202) 267–8029, Office of Rulemaking (ARM–1) Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591.

This notice is published pursuant to 14 CFR 11.85 and 11.91.

Issued in Washington, DC, on March 21, 2002.

#### Gary A. Michel,

 $\label{lem:acting Assistant Chief Counsel for Regulations.} Acting Assistant Chief Counsel for Regulations.$ 

## **Petitions for Exemption**

Docket No.: FAA–2001–11169 Petitioner: Lockheed Martin Section of 14 CFR Affected: 14 CFR SFAR–88

Description of Relief Sought:
To permit Lockheed Model L–188
airplanes to operate without meeting the
requirements of SFAR–88.

## **Dispositions of Petitions**

Docket No: 30122

Petitioner: Bombardier Aerospace Dallas/Fort Worth Customer Training Center

Section of 14 CFR Affected: 14 CFR from 91.105(a) and 135.338(f)

Description of Relief Sought/ Disposition:

To permit persons assigned as required crewmembers on aircraft operated by Bombardier Aerospace to temporarily relinquish their crewmember stations to Bombardier Aerospace DFW–CTC instructors for the purpose of meeting the requirements of 14 CFR 142.53(b)(1) when those instructors do no hold valid medical certificates issued by the FAA. In addition, the proposed exemption would permit individuals who meet the requirements of § 142.53(b)(1) to be considered to meet the requirements of § 135.338(f)(1).

Denial, 02/28/2002, Exemption No. 7732

Docket No.: FAA-2001-11011
Petitioner: Executive Jet International
Section of 14 CFR Affected: 14 CFR
135.152(i)

Description of Relief Sought/ Disposition:

To permit EJI to operate one Gulfstream Model GV (GV) airplane (Serial No. 687) without that airplane being equipped with the required flight data recorder after the August 19, 2002, compliance date. The FAA notes that EJI did not own the indicated aircraft at the time the petition was submitted; the airplane manufacturer (Gulfstream Aerospace Incorporated) petitioned for relief on behalf of EJI, citing EJI's "willingness to accept" this GV airplane if the requested relief were granted.

Denial, 02/25/2002, Exemption No. 77735

[FR Doc. 02-7509 Filed 3-27-02; 8:45 am] BILLING CODE 4910-13-M

### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

Aviation Rulemaking Advisory Committee Meeting on Air Carrier and General Aviation Maintenance Issues

**AGENCY:** Federal Aviation Administration (FAA) DOT.

**ACTION:** Notice of public meeting.

SUMMARY: The Federal Aviation Administration (FAA) is issuing this notice to advise the public of a meeting of the FAA Aviation Rulemaking Advisory Committee to discuss Air Carrier and General Aviation Maintenance Issues. Specifically, the committee will discuss tasks concerning quality assurance and ratings for aeronautical repair stations.

**DATES:** The meeting will be held April 17–18, 2002, from 10 a.m. to 5 p.m. Arrange for teleconference capability and presentations no later than 3 business days before the meeting.

ADDRESSES: The meeting will be held at the Helicopter Association International, 1635 Prince Street, Alexandria, VA 22134–2818.

# FOR FURTHER INFORMATION CONTACT:

Vanessa R. Wilkins, Federal Aviation Administration, Office of Rulemaking (ARM–207), 800 Independence Avenue, SW., Washington, DC 20591, telephone (202) 267–8029; fax (202) 267–5075.

SUPPLEMENTARY INFORMATION: Pursuant to § 10(a)(2) of the Federal Advisory Committee Act (Public Law 92–463; 5 U.S.C. App. II), notice is hereby given of a meeting of the Aviation Rulemaking Advisory Committee to discuss air carrier and general aviation maintenance issues. The meeting will be held April 17–18, 2002, from 10 a.m. to 5 p.m. at the Helicopter Association International, 1635 Prince Street, Alexandria, VA 22134–2818. The committee will discuss quality assurance and ratings for aeronautical repair stations.

Attendance is open to the public, but will be limited to the space available. The FAA will arrange teleconference capability for individuals wishing to participate by teleconference if we receive notification no later than 3 business days before the meeting. Arrangements to participate by teleconference can be made by contacting the person listed in the FOR FURTHER INFORMATION CONTACT section. Callers outside the Washington metropolitan area will be responsible for paying long distance charges.

To present oral statements at the meeting, members of the public must make arrangements no later than 3 business days before the meeting. The public may present written statements to the committee at any time by providing 25 copies to the Assistant Executive Director, or by bringing the copies to the meeting. In addition, sign and oral interpretation can be made available at the meeting, as well as assistive listening device, if requested no later than 10 calendar days before the meeting. Arrangements may be made by contacting the person listed under the heading FOR FURTHER INFORMATION CONTACT.

Issued in Washington, DC, on March 25, 2002.

## Anthony F. Fazio,

Executive Director, Aviation Rulemaking Advisory Committee.

[FR Doc. 02–7482 Filed 3–27–02; 8:45 am]

BILLING CODE 4910-13-M

## **DEPARTMENT OF TRANSPORTATION**

## **Federal Aviation Administration**

# Aviation Rulemaking Advisory Committee; Airport Certification Issues Meeting

**AGENCY:** Federal Aviation Administrative (FAA), DOT. **ACTION:** Notice of public meeting.

**SUMMARY:** This notice announces a public meeeting of the Federal Aviation Administration's Aviation Rulemaking Advisory Committee to discuss Airport Certification issues.

**DATES:** The meeting will be held on April 8, 2002, from 1:00 p.m. to 4:00 p.m. Arrange presentations by April 1, 2002.

**ADDRESSES:** The meeting will be held at the Federal Aviation Administration, 800 Independence Ave. SW, Room 600 East, Washington, DC 20591.

## FOR FURTHER INFORMATION CONTACT: Marisa Mullen, FAA, Office of Rulemaking (ARM–205), 800

Independence Avenue, SW,