

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2023–0103, dated May 23, 2023 (EASA AD 2023–0103).

**(h) Exceptions to EASA AD 2023–0103**

(1) Where EASA AD 2023–0103 refers to its effective date, this AD requires using the effective date of this AD.

(2) This AD does not adopt the “Remarks” section of EASA AD 2023–0103.

(3) Where EASA AD 2023–0103 specifies “The SB: Airbus DS Service Bulletin (SB) SB235–53–0070C (for CN–235, CN–235–200 and CN–235–300 aeroplanes) and SB295–53–0025C (for C–295 aeroplanes), as applicable,” for this AD replace those words with “The SB: Airbus DS Service Bulletin (SB) SB235–53–0070C (for CN–235, CN–235–200 and CN–235–300 aeroplanes), SB235–53–0070M (for CN–235–100 aeroplanes), and SB295–53–0025C (for C–295 aeroplanes), as applicable.”

(4) Where EASA AD 2023–0103 specifies “Groups: Group 1 aeroplanes are CN–235, CN–235–200 aeroplanes. Group 2 aeroplanes are CN–235–300 and C–295 aeroplanes,” for this AD replace those words with “Groups: Group 1 aeroplanes are CN–235, CN–235–100, and CN–235–200 aeroplanes. Group 2 aeroplanes are CN–235–300 and C–295 aeroplanes.”

(5) Where the column header of Table 1 of EASA AD 2023–0103 is titled “Accumulated Flight Hours (FH) and Flight Cycles (FC)”, for this AD replace those words with “Accumulated Flight Hours (FH) and Flight Cycles (FC), as of March 30, 2021 (the effective date of AD 2021–02–18).”

(6) Where EASA AD 2023–0103 specifies a compliance time of “During the next A-check, or within 300 FH after 30 July 2020 [the effective date of EASA AD 2020–0159], whichever occurs later,” for this AD replace those words with “Within 300 FH after March 30, 2021 (the effective date of AD 2021–02–18).”

(7) Where EASA AD 2023–0103 specifies a compliance time of “Within 50 FH or 50 FC, whichever occurs first after 30 July 2020 [the effective date of EASA AD 2020–0159],” for this AD replace those words with “Within 50 FH or 50 FC, whichever occurs first after March 30, 2021 (the effective date of AD 2021–02–18).”

(8) Where paragraph (2) of EASA AD 2023–0103 specifies to “contact Airbus DS for approved instructions and accomplish those instructions accordingly” if discrepancies are detected, for this AD if any cracking is detected, the cracking must be repaired before further flight using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus Defense and Space S.A.’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

**(i) No Reporting Requirement**

Although the service information referenced in EASA AD 2023–0103 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

**(j) Additional AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov).

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus Defense and Space S.A.’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (j)(2) of this AD, if any service information referenced in EASA AD 2023–0103 contains paragraphs that are labeled as RC, the instructions in RC paragraphs, including subparagraphs under an RC paragraph, must be done to comply with this AD; any paragraphs, including subparagraphs under those paragraphs, that are not identified as RC are recommended. The instructions in paragraphs, including subparagraphs under those paragraphs, not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the instructions identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to instructions identified as RC require approval of an AMOC.

**(k) Additional Information**

For more information about this AD, contact Shahram Daneshmandi, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 206–231–3220; email: [shahram.daneshmandi@faa.gov](mailto:shahram.daneshmandi@faa.gov).

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2023–0103, dated May 23, 2023.

(ii) [Reserved]

(3) For EASA AD 2023–0103, contact EASA, Konrad-Adenauer-Ufer 3, 50668

Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find this EASA AD on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu).

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](http://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on October 11, 2023.

**Victor Wicklund,**

*Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2023–22885 Filed 10–17–23; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA–2023–2105; Airspace Docket No. 22–AAL–61]

**RIN 2120–AA66**

**Amendment of Alaskan Very High Frequency Omnidirectional Range Federal Airway V–506 in the Vicinity of Kodiak, AK**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to amend Alaskan Very High Frequency Omnidirectional Range Federal airway (VOR) V–506 in the vicinity of Kodiak, AK. The FAA is taking this action due to the loss of signal from the Kodiak, AK, VOR and due to the pending decommissioning of the Hotham, AK, Nondirectional Radio Beacon (NDB).

**DATES:** Comments must be received on or before December 4, 2023.

**ADDRESSES:** Send comments identified by FAA Docket No. FAA–2023–2105 and Airspace Docket No. 22–AAL–61 using any of the following methods:

\* *Federal eRulemaking Portal:* Go to [www.regulations.gov](http://www.regulations.gov) and follow the online instructions for sending your comments electronically.

\* *Mail:* Send comments to Docket Operations, M–30; U.S. Department of Transportation, 1200 New Jersey Avenue SE, Room W12–140, West Building Ground Floor, Washington, DC 20590–0001.

\* *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

\* *Fax:* Fax comments to Docket Operations at (202) 493-2251.

*Docket:* Background documents or comments received may be read at [www.regulations.gov](http://www.regulations.gov) at any time. Follow the online instructions for accessing the docket or go to the Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FAA Order JO 7400.11H, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

**FOR FURTHER INFORMATION CONTACT:** Steven Roff, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

#### **SUPPLEMENTARY INFORMATION:**

##### **Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would modify the airway structure as necessary to preserve the safe and efficient flow of air traffic within the National Airspace System.

##### **Comments Invited**

The FAA invites interested persons to participate in this rulemaking by submitting written comments, data, or views. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the

proposal. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should submit only one time if comments are filed electronically, or commenters should send only one copy of written comments if comments are filed in writing.

The FAA will file in the docket all comments it receives, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, the FAA will consider all comments it receives on or before the closing date for comments. The FAA will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. The FAA may change this proposal in light of the comments it receives.

*Privacy:* In accordance with 5 U.S.C. 553(c), DOT solicits comments from the public to better inform its rulemaking process. DOT posts these comments, without edit, including any personal information the commenter provides, to [www.regulations.gov](http://www.regulations.gov), as described in the system of records notice (DOT/ALL-14 FDMS), which can be reviewed at [www.dot.gov/privacy](http://www.dot.gov/privacy).

##### **Availability of Rulemaking Documents**

An electronic copy of this document may be downloaded through the internet at [www.regulations.gov](http://www.regulations.gov). Recently published rulemaking documents can also be accessed through the FAA's web page at [www.faa.gov/air\\_traffic/publications/airspace\\_amendments/](http://www.faa.gov/air_traffic/publications/airspace_amendments/).

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Operations office (see **ADDRESSES** section for address, phone number, and hours of operations). An informal docket may also be examined during normal business hours at the office of the Western Service Center, Federal Aviation 2200 South 216th St., Des Moines, WA 98198.

##### **Incorporation by Reference**

Alaskan VOR Federal airways are published in paragraph 6010(b) of FAA Order JO 7400.11, Airspace Designations and Reporting Points, which is incorporated by reference in 14 CFR 71.1 on an annual basis. This document proposes to amend the current version of that order, FAA Order JO 7400.11H, dated August 11, 2023,

and effective September 15, 2023. These updates would be published in the next update to FAA Order JO 7400.11. That order is publicly available as listed in the **ADDRESSES** section of this document.

FAA Order JO 7400.11H lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

##### **Background**

In 2003, Congress enacted the Vision 100-Century of Aviation Reauthorization Act (Pub L., 108-176), which established a joint planning and development office in the FAA to manage the work related to the Next Generation Air Transportation System (NextGen). Today, NextGen is an ongoing FAA-led modernization of the nation's air transportation system to make flying safer, more efficient, and more predictable.

In support of NextGen, this proposal is part of an ongoing, large, and comprehensive T-route modernization project in the state of Alaska. The project mission statement states: "To modernize Alaska's Air Traffic Service route structure using satellite-based navigation development of new T-routes and optimization of existing T-routes will enhance safety, increase efficiency and access, and will provide en route continuity that is not subject to the restrictions associated with ground-based airway navigation."

As part of this initiative, the Hotham NDB is scheduled to be decommissioned. As a result, the portion of Alaskan V-506 that extends between the Kotzebue VOR/Distance Measuring Equipment (VOR/DME) and the Hotham NDB will become unusable. This airspace action proposes to amend the Alaskan V-506 by revoking the portion of the airway that extends between the Kotzebue VOR/DME and the Hotham NDB.

Additionally, the Kodiak VOR/DME is unusable on V-506 within 55 nautical miles of the navigational aid location. A notice to air missions was issued in 2019 upon a failed flight inspection, stating that V-506 from the Kodiak VOR/DME to the 55 nautical mile change over points on the airway are unusable. The disruption of the signal was first suspected to be caused by tree growth surrounding the VOR site within the VOR clear zone; however, efforts to restore the signal by clearing trees in this area have been unsuccessful. Due to the lack of usable signal and known cause of the signal loss, the FAA proposes to amend the Alaskan V-506 by revoking the portion of the airway that extends between the intersection of the Kodiak VOR/DME 107° radial and the Anchorage Oceanic Control Area/

Flight Information Region (CTA/FIR) boundary and the King Salmon VOR/Tactical Air Navigation (VORTAC).

### The Proposal

The FAA proposes to amend 14 CFR part 71 by amending Alaskan VOR Federal airway V–506. The proposed airspace actions are described below.

V–506: The Alaskan Federal airway V–506 extends between Barrow, AK, VOR/DME and the intersection of the Kodiak VOR/DME 107° radial and the Anchorage Oceanic CTA/FIR boundary. As amended, the Alaskan V–506 would extend between the Kotzebue VOR/DME and the King Salmon VORTAC.

### Regulatory Notices and Analyses

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### Environmental Review

This proposal will be subject to an environmental analysis in accordance with FAA Order 1050.1F, “Environmental Impacts: Policies and Procedures” prior to any FAA final regulatory action.

### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

### The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

### PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ V. The authority citation for 14 CFR part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

### § 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order JO 7400.11H, Airspace Designations and Reporting Points, dated August 11, 2023, and effective September 15, 2023, is amended as follows:

*Paragraph 6010(b) Alaskan VOR Federal Airways.*

\* \* \* \* \*

### V–508 [Amended]

From Kotzebue, AK; 53 miles 12 AGL, 71 miles 55 MSL, 35 miles 12 AGL; Nome, AK; Bethel, AK; 63 miles 12 AGL, 84 miles 70 MSL, 51 miles 12 AGL; to King Salmon, AK.

\* \* \* \* \*

Issued in Washington, DC, on October 13, 2023.

**Karen L. Chiodini,**

*Acting Manager, Rules and Regulations Group.*

[FR Doc. 2023–22952 Filed 10–17–23; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA–2023–1984; Airspace Docket No. 23–ASW–17]

**RIN 2120–AA66**

### Establishment of Class E Airspace; Liberty, TX

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to establish Class E airspace at Liberty, TX. The FAA is proposing this action to support new instrument procedures at this airport.

**DATES:** Comments must be received on or before December 4, 2023.

**ADDRESSES:** Send comments identified by FAA Docket No. FAA–2023–1984 and Airspace Docket No. 23–ASW–17 using any of the following methods:

\* *Federal eRulemaking Portal:* Go to [www.regulations.gov](http://www.regulations.gov) and follow the online instruction for sending your comments electronically.

\* *Mail:* Send comments to Docket Operations, M–30; U.S. Department of Transportation, 1200 New Jersey Avenue SE, Room W12–140, West Building Ground Floor, Washington, DC 20590–0001.

\* *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12–140 of the West Building

Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

\* *Fax:* Fax comments to Docket Operations at (202) 493–2251.

*Docket:* Background documents or comments received may be read at [www.regulations.gov](http://www.regulations.gov) at any time. Follow the online instructions for accessing the docket or go to Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FAA Order JO 7400.11H, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

**FOR FURTHER INFORMATION CONTACT:** Raul Garza Jr., Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222–5874.

### SUPPLEMENTARY INFORMATION:

#### Authority for This Rulemaking

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would establish Class E airspace extending upward from 700 feet above the surface Class E surface airspace at Liberty Dayton Regional Medical Center, Liberty, TX, to support instrument flight rule (IFR) operations at this airport.

#### Comments Invited

The FAA invites interested persons to participate in this rulemaking by submitting written comments, data, or views. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. The most helpful comments