

attachment fitting, part number (P/N) A 102 021N, for damage and material hardness following the procedures in AEROTECHNIK CZ s.r.o. Mandatory Service Bulletin SEH 13-005a, dated November 18, 1999.

(ii) If you find the tail-fuselage attachment fitting is damaged or the material does not meet the hardness requirements specified in the service bulletin during the inspection required in paragraph (f)(1)(i) of this AD, before further flight, you must contact the manufacturer to obtain an FAA-approved replacement part for P/N A 102 021N and FAA-approved installation instructions and install the replacement part. Use the contact information found in paragraph (i)(4) to contact the manufacturer.

(iii) As of November 27, 2000 (the effective date retained from AD 2000-20-12), do not install, on any glider, a P/N A 102 021N attachment fitting that has not passed the inspection required in paragraph (f)(1)(i) of this AD.

(2) *Model L 13 SDM VIVAT gliders:*

(i) Within the next 60 days after July 14, 2016 (the effective date of this AD), inspect the tail-fuselage attachment fitting, P/N A 102 021N, for damage and material hardness following the procedures in AEROTECHNIK CZ s.r.o. Mandatory Service Bulletin SEH 13-005a, dated November 18, 1999.

(ii) If you find the tail-fuselage attachment fitting is damaged or the material does not meet the hardness requirements specified in the service bulletin during the inspection required in paragraph (f)(2)(i) of this AD, before further flight, you must contact the manufacturer to obtain an FAA-approved replacement part for P/N A 102 021N and FAA-approved installation instructions and install the replacement part. Use the contact information found in paragraph (i)(4) to contact the manufacturer.

(iii) As of July 14, 2016 (the effective date of this AD), do not install, on any glider, a P/N A 102 021N attachment fitting that has not passed the inspection required in paragraph (f)(2)(i) of this AD.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI Civil Aviation Authority AD CAA-AD-T-112/1999R1, dated November 23, 1999, for related information. The MCAI can be found in the AD docket on the Internet at: <https://www.regulations.gov/documentDetail;D=FAA-2016-4230-0003>.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on November 27, 2000 (65 FR 61262, October 17, 2000).

(i) AEROTECHNIK CZ s.r.o. Mandatory Service Bulletin SEH 13-005a, dated November 18, 1999.

(ii) Reserved.

(4) For service information identified in this AD, contact EVEKTOR, spol. s.r.o., Letecká 1008, 686 04 Kunovice, Czech Republic; phone: +420 572 537 428; email: evektor@evektor.cz; Internet: <http://www.evektor.cz/en/sales-and-support>.

(5) You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. In addition, you can access this service information on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-4230.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on May 20, 2016.

Pat Mullen,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-12601 Filed 6-8-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2016-0149; Airspace Docket No. 15-AWA-8]

RIN 2120-AA66

Amendment of Class C Airspace; Billings Logan International Airport, MT

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends geographic coordinates of Billings Logan International Airport, Billings, MT, under Class C airspace, due to recent surveys of the airport. This action does not change the boundaries or operating requirements of the airspace.

DATES: Effective date 0901 UTC, September 15, 2016. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.9Z, Airspace Designations and Reporting Points and subsequent amendments can be viewed online at <http://www.faa.gov/airtraffic/publications/>. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington DC, 20591; telephone: (202) 267-8783. The order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.9Z at NARA, call (202) 741-6030, or go to http://www.archives.gov/federal-register/code_of_federal-regulations/ibr_locations.html.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Airspace Policy Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it updates the geographic coordinates of Billings Logan International Airport, Billings, MT.

History

During a review of the airspace for Billings Logan International Airport, Billings, MT, the FAA identified that the airport's geographic coordinates were incorrect. This action updates the geographic coordinates to coincide with the FAA's aeronautical database for the respective Class C airspace area.

Class C airspace designations are published in paragraph 4000 of FAA Order 7400.9Z dated August 6, 2015, and effective September 15, 2015, which is incorporated by reference in 14 CFR part 71.1. The Class C airspace designations listed in this document will be published subsequently in the Order.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, and effective September 15, 2015. FAA Order 7400.9Z is publicly available as listed in the ADDRESSES section of this document. FAA Order 7400.9Z lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 amends Class C airspace at Billings Logan International Airport, Billings, MT, by adjusting the geographic coordinates to reflect recent survey data.

This is an administrative change and does not affect the boundaries, altitudes, or operating requirements of the airspace, therefore, notice and public procedure under 5 U.S.C. 553(b) is unnecessary.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial

number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5–6.5a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71 —DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

- 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

- 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, effective September 15, 2015, is amended as follows:

Paragraph 4000 Class C Airspace.

* * * * *

ANM MT C Billings, MT [Amended]

Billings Logan International Airport, MT (Lat. 45°48'28" N., long. 108°32'34" W.)

That airspace extending upward from the surface to and including 7,700 feet MSL within a 5-mile radius of the Billings Logan International Airport; and that airspace extending upward from 4,900 feet MSL to and including 7,700 feet MSL within a 10-mile radius of the airport.

Issued in Washington, DC, on, June 1, 2016.

Leslie M. Swann,

Acting Manager, Airspace Policy Group.

[FR Doc. 2016–13553 Filed 6–8–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2015–4452; Airspace Docket No. 15–AWA–7]

RIN 2120–AA66

Amendment of Class C Airspace; Capital Region International Airport, MI

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action modifies the Lansing, MI, Class C airspace at the Capital Region International Airport, formerly the Lansing Capital City Airport, by removing a cutout from the surface area that was put in place to accommodate operations at an airport that is now permanently closed. This action also updates the Capital Region International Airport name and geographic coordinates to reflect the current information in the FAA's aeronautical database. The FAA is taking this action to ensure the safe and efficient operations at Capital Region International Airport.

DATES: Effective date 0901 UTC, September 15, 2016. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.9Z, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.9Z at NARA, call (202) 741–6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT:

Colby Abbott, Airspace Policy Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267–8783.