### (b) Affected ADs

None.

# (c) Applicability

This AD applies to all Airbus SAS Model A321–111, –112, –131, –211, –212, –213, –231, and –232 airplanes, certificated in any category.

### (d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

### (e) Unsafe Condition

This AD was prompted by stress analysis results indicating that cracks may appear in the center wing box at frame 42 and slanted junction areas. The FAA is issuing this AD to detect potential cracks in the center wing box at frame 42 and slanted junction areas. The unsafe condition, if not addressed, could affect the structural integrity of the fuselage.

## (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

## (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2023–0074, dated April 5, 2023 (EASA AD 2023–0074).

## (h) Exceptions to EASA AD 2023-0074

- (1) Where EASA AD 2023–0074 refers to its effective date, this AD requires using the effective date of this AD.
- (2) Where EASA AD 2023–0074 specifies to comply with "the instructions of the AOT," this AD requires compliance with the procedures marked as required for compliance (RC) in the Alert Operators Transmission (AOT).
- (3) This AD does not adopt the "Remarks" section of EASA AD 2023–0074.
- (4) Where paragraph (3) of EASA AD 2023–0074 specifies to "contact Airbus for approved repair instructions and, within the compliance time specified therein, accomplish those instructions accordingly," for this AD, if any cracking is detected, the cracking must be repaired before further flight using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.
- (5) Paragraph (4) of EASA AD 2023–0074 specifies to report inspection results to Airbus within a certain compliance time. For this AD, report inspection results at the applicable time specified in paragraph (h)(5)(i) or (ii) of this AD.
- (i) If the inspection was done on or after the effective date of this AD: Submit the report within 90 days after the inspection.
- (ii) If the inspection was done before the effective date of this AD: Submit the report within 90 days after the effective date of this AD.
- (6) Where paragraph (2) of EASA AD 2023– 0074 refers to a ferry flight, a special flight permit may be issued in accordance with 14

CFR 21.197 and 21.199 provided the operators comply with the provisions specified in paragraph (2) of EASA AD 2023–0074.

# (j) Additional AD Provisions

The following provisions also apply to this AD:

- (1) Alternative Methods of Compliance (AMOCs): The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.
- (2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.
- (3) Required for Compliance (RC): Except as required by paragraphs (h)(2) and (j)(2) of this AD, if any service information referenced in EASA AD 2023-0074 contains paragraphs that are labeled as RC, the instructions in RC paragraphs, including subparagraphs under an RC paragraph, must be done to comply with this AD; any paragraphs, including subparagraphs under those paragraphs, that are not identified as RC are recommended. The instructions in paragraphs, including subparagraphs under those paragraphs, not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the instructions identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to instructions identified as RC require approval of an AMOC.

## (k) Additional Information

For more information about this AD, contact Tim Dowling, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone 206–231–3667; email: timothy.p.dowling@faa.gov.

## (l) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.
- (i) European Union Aviation Safety Agency (EASA) AD 2023–0074, dated April 5, 2023.
- (ii) [Reserved]

- (3) For EASA AD 2023–0074, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@easa.europa.eu*; website *easa.europa.eu*. You may find this EASA AD on the EASA website at *ad.easa.europa.eu*.
- (4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.
- (5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibrlocations.html.

Issued on August 30, 2023.

### Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–19075 Filed 9–5–23; 8:45 am] BILLING CODE 4910–13–P

#### SILLING CODE 4910-13-P

### **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

### 14 CFR Part 71

[Docket No. FAA-2023-1780; Airspace Docket No. 23-ASO-35]

# RIN 2120-AA66

# Revocation of Class D and Class E Airspace; Milton, FL

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to remove Class D airspace, Class E surface airspace, and Class E airspace extending upward from 700 feet above the surface for Choctaw NOLF, Milton, FL.

**DATES:** Comments must be received on or before October 23, 2023.

**ADDRESSES:** Send comments identified by FAA Docket No. FAA–2023–1780 and Airspace Docket No. 23–ASO–35 using any of the following methods:

- \* Federal eRulemaking Portal: Go to www.regulations.gov and follow the online instructions for sending your comments electronically.
- \* Mail: Send comments to Docket Operations, M–30; U.S. Department of Transportation, 1200 New Jersey Avenue SE, Room W12–140, West Building Ground Floor, Washington, DC 20590–0001.
- \* Hand Delivery or Courier: Take comments to Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey

Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except for Federal holidays.

\* *Fax:* Fax comments to Docket Operations at (202) 493–2251.

Docket: Background documents or comments received may be read at www.regulations.gov anytime. Follow the online instructions for accessing the docket or go to the Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except for Federal holidays.

FAA Order JO 7400.11G Airspace Designations and Reporting Points and subsequent amendments can be viewed online at www.faa.gov/air\_traffic/publications/. You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Avenue, College Park, GA 30337; Telephone: (404) 305–6364.

### SUPPLEMENTARY INFORMATION:

### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority, as it would remove Class D and Class E airspace in Milton, FL. The closing of the air traffic control tower and cancellation of all instrument approaches determined that this update is necessary to support operations in the area.

## **Comments Invited**

The FAA invites interested persons to participate in this rulemaking by submitting written comments, data, or views. Comments are specifically invited on the proposal's overall regulatory, aeronautical, economic, environmental, and energy-related aspects. The most helpful comments reference a specific portion of the

proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should submit only one time if comments are filed electronically, or commenters should send only one copy of written comments if comments are filed in writing.

The FAA will file in the docket all comments it receives and a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, the FAA will consider all comments it receives on or before the closing date for comments. The FAA will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. The FAA may change this proposal in light of the comments it receives.

Privacy: In accordance with 5 U.S.C. 553(c), DOT solicits comments from the public to better inform its rulemaking process. DOT posts these comments, without edit, including any personal information the commenter provides, to www.regulations.gov, as described in the system of records notice (DOT/ALL–14 FDMS), which can be reviewed at www.dot.gov/privacy.

## **Availability of Rulemaking Documents**

An electronic copy of this document may be downloaded through the internet at www.regulations.gov.

Recently published rulemaking documents can also be accessed through the FAA's web page at www.faa.gov/air\_traffic/publications/airspace\_amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Operations office (see ADDRESSES section for address, phone number, and hours of operations). An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation Administration, Room 210, 1701 Columbia Ave., College Park, GA 30337.

# **Incorporation by Reference**

Class D and Class E airspace designations are published in Paragraphs 5000, 6002, and 6005 of FAA Order JO 7400.11, Airspace Designations and Reporting Points, which is incorporated by reference in 14 CFR 71.1 annually. This document proposes to amend the current version of that order, FAA Order JO 7400.11G, Airspace Designations and Reporting Points, dated August 19, 2022, and

effective September 15, 2022. These updates would be published subsequently in the next update to FAA Order JO 7400.11. FAA Order JO 7400.11G is publicly available as listed in the ADDRESSES section of this document. FAA Order JO 7400.11G lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

## The Proposal

The FAA proposes an amendment to 14 CFR part 71 to remove Class D airspace, Class E surface airspace, and Class E airspace extending upward from 700 feet above the surface for Choctaw NOLF, Milton, FL, as the air traffic control tower has closed, and all instrument approaches canceled.

## **Regulatory Notices and Analyses**

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

# **Environmental Review**

This proposal will be subject to an environmental analysis per FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," before any FAA final regulatory action.

## **Lists of Subjects in 14 CFR Part 71**

Airspace, Incorporation by reference, Navigation (air).

# The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

# PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

# §71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order JO 7400.11G, Airspace Designations and Reporting Points, dated August 19, 2022, and effective September 15, 2022, is amended as follows:

Paragraph 5000 Class D Airspace.

\* \* \* \* \*

ASO FL D Milton, FL [Removed]

\* \* \* \* \*

 ${\it Paragraph~6002~Class~E~Surface~Airspace}.$ 

\* \* \* \* \*

ASO FL E2 Milton, FL [Removed]

\* \* \* \* \*

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.

\* \* \* \* \* \*

ASO FL E5 Choctaw Outlying Field, FL [Removed]

\* \* \* \* \* \*

Issued in College Park, Georgia, on August 29, 2023.

# Lisa E. Burrows,

Manager, Airspace & Procedures Team North, Eastern Service Center, Air Traffic Organization.

[FR Doc. 2023–19045 Filed 9–5–23; 8:45 am]

BILLING CODE 4910-13-P