

from specified requirements of 14 CFR. The purpose of this notice is to improve the public's awareness of, and participation in, this aspect of FAA's regulatory activities. Neither publication of this notice nor the inclusion or omission of information in the summary is intended to affect the legal status of the petition or its final disposition.

DATES: Comments on this petition must identify the petition docket number involved and must be received on or before September 11, 2008.

ADDRESSES: You may send comments identified by Docket Number FAA-2008-0826 using any of the following methods:

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Send comments to the Docket Management Facility; U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590.

- Fax: Fax comments to the Docket Management Facility at 202-493-2251.

- Hand Delivery: Bring comments to the Docket Management Facility in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Privacy: We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. Using the search function of our docket web site, anyone can find and read the comments received into any of our dockets, including the name of the individual sending the comment (or signing the comment for an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78).

Docket: To read background documents or comments received, go to <http://www.regulations.gov> at any time or to the Docket Management Facility in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Kenna Sinclair (425) 227-1556, Transport Airplane Directorate, ANM-113, Federal Aviation Administration, 1601 Lind Avenue SE, Renton, WA 98055-4056; or Fran Shaver (202) 267-9681, Office of Rulemaking, Federal Aviation Administration, 800

Independence Avenue, SW., Washington, DC 20591. This notice is published pursuant to 14 CFR 11.85.

Issued in Washington, DC, on August 18, 2008.

Pamela Hamilton-Powell,
Director, Office of Rulemaking.

Petition for Exemption

Docket No.: FAA-2008-0826.

Petitioner: The Boeing Company.

Sections of 14 CFR Affected:

§§ 25.841(a)(2) and 25.841(a)(3).

Description of Relief Sought: The petitioner is requesting an exemption from certain pressurized cabin requirements in regard to uncontained engine failure for Boeing Model 747-8/8F series airplanes.

[FR Doc. E8-19461 Filed 8-21-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

[Summary Notice No. PE-2008-38]

Petition for Exemption; Summary of Petition Received

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of petition for exemption received.

SUMMARY: This notice contains a summary of a petition seeking relief from specified requirements of 14 CFR. The purpose of this notice is to improve the public's awareness of, and participation in, this aspect of FAA's regulatory activities. Neither publication of this notice nor the inclusion or omission of information in the summary is intended to affect the legal status of the petition or its final disposition.

DATE: Comments on this petition must identify the petition docket number involved and must be received on or before September 2, 2008.

ADDRESSES: You may send comments identified by Docket Number FAA-2008-0905 using any of the following methods:

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Send comments to the Docket Management Facility; U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590.

- Fax: Fax comments to the Docket Management Facility at 202-493-2251.

- Hand Delivery: Bring comments to the Docket Management Facility in

Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Privacy: We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. Using the search function of our docket Web site, anyone can find and read the comments received into any of our dockets, including the name of the individual sending the comment (or signing the comment for an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78).

Docket: To read background documents or comments received, go to <http://www.regulations.gov> at any time or to the Docket Management Facility in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Jan Thor (425) 227-2127, ANM-113, Federal Aviation Administration, 1601 Lind Avenue SW., Renton, WA 98057-3356, or Frances Shaver (202) 267-9681, Office of Rulemaking, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591.

This notice is published pursuant to 14 CFR 11.85.

Issued in Washington, DC, on August 19, 2008.

Pamela Hamilton-Powell,
Director, Office of Rulemaking.

Petition for Exemption

Docket No.: FAA-2008-0905.

Petitioner: Aviation Partners Boeing.

Section of 14 CFR Affected:

§ 25.981(a)(3).

Description of Relief Sought: Aviation Partners Boeing requests exemption from the lightning protection requirements for wing fasteners on the installation of blended winglets on their Boeing Model 767-300/300F airplanes.

[FR Doc. E8-19477 Filed 8-21-08; 8:45 am]

BILLING CODE 4910-13-P