Director no later than September 3, 2002. Written material for distribution at the meeting should reach the Coast Guard no later than September 3, 2002. If you would like a copy of your material distributed to each member of the committee in advance of the meeting, please submit 10 copies to Margie Hegy at the address in the ADDRESSES section no later than August 30, 2002.

## Information on Services for Individuals With Disabilities

For information on facilities or services for individuals with disabilities or to request special assistance at the meeting, contact the Executive Director as soon as possible.

Dated: August 14, 2002.

## Joseph J. Angelo,

Acting Assistant Commandant Marine Safety, Security and Environmental Protection. [FR Doc. 02–21131 Filed 8–19–02; 8:45 am]

BILLING CODE 4910-15-P

## **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

## Proposed Advisory Circular; Engine Instructions for Continued Airworthiness

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of availability of proposed advisory circular and request for comments.

**SUMMARY:** This notice announces the availability of proposed Advisory Circular (AC) No. 20.XX, Turbojet, Turboprop & Turbofan Engine Induction System Icing.

**DATES:** Comments must be received on or before October 21, 2002.

ADDRESSES: Send all comments on the proposed AC to the Federal Aviation Administration, Attn: John Fisher, Engine and Propeller Standards Staff, ANE–110, 12 New England Executive Park, Burlington, MA 01803–5299.

FOR FURTHER INFORMATION CONTACT: John Fisher, Engine and Propeller Standards Staff, ANE–110, at the above address, telephone (781) 238–7149, fax (781) 238–7199, or e-mail to john.fisher@faa.gov.

## SUPPLEMENTARY INFORMATION:

## **Comments Invited**

A copy of the subject AC may be obtained by contacting the person named under FOR FURTHER INFORMATION CONTACT or by downloading the proposed AC from the following

Internet Web site:

http:\\www2.airweb.FAA.gov/
Regulatory\_and\_Guidance\_Library/
RgDAC.nsf/mainframe?openframeset
The FAA invites interested parties to
comment on the proposed AC.
Comments should identify the subject of
the AC and be submitted to the
individual identified under FOR FURTHER
INFORMATION CONTACT. The FAA will
consider all communications received
by the closing date before issuing the
final AC.

## **Background**

This AC is on the subject of continued airworthiness of aircraft engines certificated under Title 14 of the Code of Federal Regulation (CFR) parts 33 and 25. The information and guidance presented in this AC would provide a method that can be used to demonstrate compliance with the requirements of §§ 25.1093, 33.68, 33.77, and 33.89.

On January 24, 2000, a Notice was published in the **Federal Register** (65 FR 3752), requesting public comments by February 23, 2000. Since then, those public comments, as well as other significant changes were made to the proposed AC. Therefore, this Notice announces an additional request for public comments on the revised AC proposal.

This advisory circular, published under the authority granted to the Administrator by 49 U.S.C. 106(g), 40113, 44701–44702, 44704, provides guidance for these proposed requirements.

Issued in Burlington, Massachusetts, on August 8, 2002.

## Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 02–21186 Filed 8–19–02; 8:45 am] BILLING CODE 4910–13–M

## DEPARTMENT OF TRANSPORTATION

## **Federal Aviation Administration**

# Proposed Advisory Circular 45–2B, Identification and Registration Marking

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of availability.

**SUMMARY:** This notice announces the availability of Advisory Circular (AC) 45–2B, Identification and Registration Marking for review and comments. The proposed AC provides guidance and information to comply with the requirements for identifying aircraft and related products with identification plates, and identifying aircraft with

nationality and registration marks. This AC provides a means, but not the only means, of demonstrating compliance with the requirements of Title 14, Code of Federal Regulations (14 CFR), part 45, Identification and Registration Marking.

**DATES:** Comments submitted must identify the proposed AC 45–2B and be received no later than 30 days after the date of this publication.

ADDRESSES: Copies of the proposed AC can be obtained from and comments may be returned to the following: Federal Aviation Administration, Airworthiness Certification Branch, AIR–220, Production and Airworthiness Division, Aircraft Certification Service, 800 Independence Avenue, SW., Washington, DC 20591.

## FOR FURTHER INFORMATION CONTACT:

David Broughton, Airworthiness Certification Branch, AIR–220, Production and Airworthiness Division, Aircraft Certification Service, 800 Independence Avenue, SW., Washington, DC 20591, (202) 267–9575.

#### SUPPLEMENTARY INFORMATION:

## **Background**

Proposed AC 45–2B is written in the Plain Language format to provide information and guidance on the requirements of identifying aircraft and related products with identification plates, and identifying aircraft with nationality and registration marks.

### Comments invited

Interested persons are invited to comment on proposed AC 45–2B listed on this notice by submitting such written data, views, or arguments, as they desire, to the aforementioned specified address. The Aircraft Certification Service will consider all communications received on or before the closing date before issuing the final AC.

Comments received on the proposed AC may be examined before and after the comment closing date in Room 815, FAA headquarters building, (FOB–10A), 800 Independence Avenue, SW., Washington, DC 20591, between 8:30 a.m. and 4:30 p.m.

Issued in Washington, DC, on August 15, 2002.

## Frank P. Paskiewicz,

Manager, Production and Airworthiness Division.

[FR Doc. 02–21184 Filed 8–19–02; 8:45 am] BILLING CODE 4910–13–M