

# Rules and Regulations

Federal Register

Vol. 72, No. 18

Monday, January 29, 2007

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

## FARM CREDIT ADMINISTRATION

### 12 CFR Parts 603, 605, 608, and 611

RIN 3052-AC34

#### Privacy Act Regulations; Information; Collection of Claims Owed the United States; Organization; Privacy and Security Information; Effective Date

**AGENCY:** Farm Credit Administration.

**ACTION:** Notice of effective date.

**SUMMARY:** The Farm Credit Administration (FCA) published a final rule under parts 603, 605, 608, and 611 on September 20, 2006 (71 FR 54899). This final rule updates and amends the regulations regarding privacy and security information and other matters. This action was taken to correct certain citations in the regulations and to conform the regulations to Executive order 13292. In accordance with 12 U.S.C. 2252, the effective date of the final rule is 30 days from the date of publication in the **Federal Register** during which either or both Houses of Congress are in session. Based on the records of the sessions of Congress, the effective date of the regulations is January 23, 2007.

**EFFECTIVE DATE:** The regulation amending 12 CFR parts 603, 605, 608, and 611, published on September 20, 2006 (71 FR 54899) is effective January 23, 2007.

**FOR FURTHER INFORMATION CONTACT:** Mike Wilson, Policy Analyst, Office of Policy and Analysis, Farm Credit Administration, McLean, VA 22102-5090, (703) 883-4498, TTY (703) 883-4434; or Bob Taylor, Attorney, Office of General Counsel, Farm Credit Administration, McLean, VA 22102-5090, (703) 883-4020, TTY (703) 883-4020.

(12 U.S.C. 2252(a)(9) and (10))

Dated: January 23, 2007.

**Roland E. Smith,**

*Secretary, Farm Credit Administration Board.*

[FR Doc. E7-1328 Filed 1-26-07; 8:45 am]

**BILLING CODE 6705-01-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2006-26047; Directorate Identifier 2006-NM-146-AD; Amendment 39-14906; AD 2007-02-19]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Model A300 B4-605R Airplanes and Model A310-308, -324, and -325 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Airbus Model A300 B4-605R airplanes and Model A310-308, -324, and -325 airplanes. This AD requires modifying the Bruce floor plan electrical emergency path marking system (FPEEPMS) and, for certain airplanes, modifying the automatic switching of the emergency lighting system. This AD results from a report that in the case of vertical separation of the fuselage forward of door 1, the FPEEPMS and the exit signs do not turn on. We are issuing this AD to prevent inadequate lighting and marking of the escape path, which could delay or impede the flightcrew and passengers when exiting the airplane during an emergency landing.

**DATES:** This AD becomes effective March 5, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of March 5, 2007.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information identified in this AD.

**FOR FURTHER INFORMATION CONTACT:** Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

##### Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Airbus Model A300 B4-605R airplanes and Model A310-308, -324, and -325 airplanes. That NPRM was published in the **Federal Register** on October 12, 2006 (71 FR 60089). That NPRM proposed to require modifying the Bruce floor plan electrical emergency path marking system (FPEEPMS) and, for certain airplanes, modifying the automatic switching of the emergency lighting system.

##### Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

#### Request To Change Incorporation of Certain Information

The Modification and Replacement Parts Association (MARPA) states that, typically, airworthiness directives are based on service information originating with the type certificate holder or its suppliers. MARPA adds that manufacturer service documents are privately authored instruments generally having copyright protection against duplication and distribution. MARPA notes that when a service document is incorporated by reference into a public document, such as an airworthiness directive, it loses its private, protected status and becomes a public document. MARPA adds that if a service document is used as a