

(g) Repetitive Inspections of the Aft Pressure Bulkhead Web at the “Y”-Chord Upper Bulkhead

At the applicable time specified in tables 9 and 10 of paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737–53A1214, Revision 5, dated January 30, 2015: Do detailed and low frequency eddy current (LFEC) inspections from the aft side of the aft pressure bulkhead web, or do detailed and high frequency eddy current (HFEC) inspections from the forward side of the aft pressure bulkhead web, for any cracking, incorrectly drilled fastener hole, and elongated fastener hole, and do all applicable related investigative and corrective actions, in accordance with Part I of the Accomplishment Instructions of Boeing Alert Service Bulletin 737–53A1214, Revision 5, dated January 30, 2015, except as required by paragraph (i) of this AD. Do all related investigative and corrective actions before further flight. If any cracking, incorrectly drilled fastener hole, or elongated fastener hole is found, before further flight, repair the web using a method approved in accordance with the procedures specified in paragraph (l) of this AD. Thereafter, repeat the inspections at the applicable times specified in tables 9 and 10 of paragraph 1.E., “Compliance” of Boeing Alert Service Bulletin 737–53A1214, Revision 5, dated January 30, 2015.

(h) Repetitive Inspections of the Aft Pressure Bulkhead Web at the “Y”-Chord Below S–15

At the applicable time specified in table 11 of 1.E., “Compliance” of Boeing Alert Service Bulletin 737–53A1214, Revision 5, dated January 30, 2015: Do detailed and eddy current inspections of the web from the forward or aft side of the bulkhead for any cracking, incorrectly drilled fastener hole, and elongated fastener hole, and do all applicable corrective actions, in accordance with Part III of the Accomplishment Instructions of Boeing Alert Service Bulletin 737–53A1214, Revision 5, dated January 30, 2015, except as required by paragraph (i) of this AD. Do all corrective actions before further flight. If any cracking, incorrectly drilled fastener hole, or elongated fastener hole is found, before further flight, repair the web using a method approved in accordance with the procedures specified in paragraph (l) of this AD. Thereafter, repeat the inspections at the applicable times specified in table 11 of paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737–53A1214, Revision 5, dated January 30, 2015.

(i) Exception to the Service Information

Where Boeing Alert Service Bulletin 737–53A1214, Revision 5, dated January 30, 2015, specifies to contact Boeing for repair instructions: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

(j) Terminating Action for Other Rulemaking

Accomplishing the actions required by paragraphs (g) and (h) of this AD terminates the inspections required by paragraphs (k) and (l) of AD 2012–18–13 R1, Amendment 39–17429 (78 FR 27020, May 9, 2013).

(k) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraphs (g) and (h) of this AD, if the actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 737–53A1214, Revision 4, dated December 16, 2011, which is not incorporated by reference in this AD.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (m)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of airplane, and the approval must specifically refer to this AD.

(m) Related Information

(1) For more information about this AD, contact Alan Pohl, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone: 425–917–6450; fax: 425–917–6590; email: Alan.Pohl@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on November 20, 2015.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015–30217 Filed 11–27–15; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2015–4006; Airspace Docket No. 15–ANE–3]

Proposed Amendment of Class E Airspace; West Dover, VT

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E Airspace at West Dover, VT as the Mt. Snow Non-Directional Beacon (NDB) has been decommissioned, requiring airspace redesign at Deerfield Valley Regional Airport. This action would enhance the safety and management of Instrument Flight Rules (IFR) operations at the airport. This action also would recognize the airport’s name change.

DATES: Comments must be received on or before January 14, 2016.

ADDRESSES: Send comments on this rule to: U. S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE, West Bldg Ground Floor Rm W12–140, Washington, DC 20590–0001; Telephone: 1–800–647–5527; Fax: 202–493–2251. You must identify the Docket Number FAA–2015–4006; Airspace Docket No. 15–ANE–3, at the beginning of your comments. You may also submit and review received comments through the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1–800–647–5527), is on the ground floor of the building at the above address.

FAA Order 7400.9Z, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC, 20591; telephone: 202–267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.9Z at NARA, call 202–741–6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-6364.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This proposed rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This proposed regulation is within the scope of that authority as it would amend Class E airspace at Deerfield Valley Regional Airport, West Dover, VT.

Comments Invited

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2015-4006; Airspace Docket No. 15-ANE-3) and be submitted in triplicate to the Docket Management System (see **ADDRESSES** section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Persons wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2015-4006; Airspace Docket No. 15-ANE-3." The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments

will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded from and comments submitted through <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal Holidays. An informal docket may also be examined between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal Holidays at the office of the Eastern Service Center, Federal Aviation Administration, room 350, 1701 Columbia Avenue, College Park, Georgia 30337.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory circular No. 11-2A, Notice of Proposed Rulemaking distribution System, which describes the application procedure.

Availability and Summary of Documents for Incorporation by Reference

This document proposes to amend FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, and effective September 15, 2015. FAA Order 7400.9Z is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.9Z lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Proposal

The FAA is considering an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to amend Class E airspace extending upward from 700 feet above the surface at Deerfield Valley Regional Airport, West Dover, VT. Airspace reconfiguration to within an 11-mile radius of the airport is necessary due to the decommissioning of the Mt. Snow NDB, and cancelation

of the NDB approach, and for continued safety and management of IFR operations at the airport. This action would also recognize the airport's name change from Mt. Snow Airport to Deerfield Valley Regional Airport.

Class E airspace designations are published in Paragraph 6005 of FAA Order 7400.9Z, dated August 6, 2015, and effective September 15, 2015, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

Regulatory Notices and Analyses

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

This proposal would be subject to an environmental analysis in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures" prior to any FAA final regulatory action.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, effective September 15, 2015, is amended as follows:

Paragraph 6005 Class E Airspace Areas Extending Upward from 700 feet or More Above the Surface of the Earth.

* * * * *

ANE VT E5 West Dover, VT [Amended]

Deerfield Valley Regional Airport, VT
(Lat. 42°55'58"N., long. 71°26'09"W.)

That airspace extending upward from 700 feet above the surface with an 11-mile radius of Deerfield Valley regional Airport.

Issued in College Park, Georgia, on November 17, 2015.

Ryan W. Almay,

*Acting Manager, Operations Support Group,
Eastern Service Center, Air Traffic
Organization.*

[FR Doc. 2015–30184 Filed 11–27–15; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA–2015–3967; Airspace
Docket No. 15–ASW–12]

Proposed Establishment of Class E Airspace; Clinton, AR

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to establish Class E airspace at Clinton, AR. Controlled airspace is necessary to accommodate new Standard Instrument Approach Procedures developed at Clinton Municipal Airport, for the safety and management of Instrument Flight Rules (IFR) operations at the airport.

DATES: Comments must be received on or before January 14, 2016.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590–0001, telephone (202) 366–9826. You must identify the docket number FAA–2015–3967; Airspace Docket No. 15–ASW–12, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in

person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1–800–647–5527), is on the ground floor of the building at the above address.

FAA Order 7400.9Z, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC, 20591; telephone: 202–267–8783. The order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to http://www.archives.gov/federal_register/code_offederal-regulations/ibr_locations.html.

FAA order 7400.9, Airspace Designations and Reporting Points is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT:

Rebecca Shelby, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone: 817–222–5857.

SUPPLEMENTARY INFORMATION:**Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would establish Class E airspace at Clinton Municipal Airport, Clinton, AR.

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments

are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA–2015–3967/Airspace Docket No. 15–ASW–12." The postcard will be date/time stamped and returned to the commenter.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177.

Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking (202) 267–9677, to request a copy of Advisory Circular No. 11–2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

Availability and Summary of Documents Proposed for Incorporation by Reference

This document proposes to amend FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, and effective September 15, 2015. FAA Order 7400.9Z is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.9Z lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Proposal

This action proposes to amend Title 14, Code of Federal Regulations (14 CFR), Part 71 by establishing Class E airspace extending upward from 700