

Rules and Regulations

Federal Register

Vol. 75, No. 105

Wednesday, June 2, 2010

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

FARM CREDIT ADMINISTRATION

12 CFR Parts 611, 613, 615, 619 and 620

RIN 3052-AC43

Organization; Eligibility and Scope of Financing; Funding and Fiscal Affairs, Loan Policies and Operations, and Funding Operations; Definitions; and Disclosure to Shareholders; Director Elections; Effective Date

AGENCY: Farm Credit Administration.

ACTION: Notice of effective date.

SUMMARY: The Farm Credit Administration (FCA or Agency), through the FCA Board (Board), issued a final rule under parts 611, 613, 615, 619 and 620 on April 12, 2010 (75 FR 18726) amending FCA's regulations to clarify director election processes and update FCA regulations to incorporate interpretations made through booklets to Farm Credit System institutions. In accordance with 12 U.S.C. 2252, the effective date of the final rule is 30 days from the date of publication in the **Federal Register** during which either or both Houses of Congress are in session. Based on the records of the sessions of Congress, the effective date of the regulations is May 24, 2010.

DATES: *Effective Date:* Under the authority of 12 U.S.C. 2252, the regulation amending 12 CFR parts 611, 613, 615, 619 and 620 published on April 12, 2010 (75 FR 18726) is effective May 24, 2010.

FOR FURTHER INFORMATION CONTACT:

Elna Luopa, Senior Corporate Analyst, Office of Regulatory Policy, Farm Credit Administration, McLean, Virginia 22102-5090, (703) 883-4498, TTY (703) 883-4434, or
Laura D. McFarland, Senior Counsel, Office of General Counsel, Farm Credit Administration, McLean,

Virginia 22102-5090, (703) 883-4020, TTY (703) 883-4020.

(12 U.S.C. 2252(a)(9) and (10))

Dated: May 26, 2010.

Roland E. Smith,

Secretary, Farm Credit Administration Board.

[FR Doc. 2010-13110 Filed 6-1-10; 8:45 am]

BILLING CODE 6705-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-27009; Directorate Identifier 2007-NE-02-AD; Amendment 39-16322; AD 2007-19-09R1]

RIN 2120-AA64

Airworthiness Directives; Turbomeca Arriel 2B1 Turboshift Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are revising an existing airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Since the issuance of AD 2007-0126 Turbomeca has released modification TU157 which consists in modifying the pressure relief valve of the HMU by introducing a damping device into the valve. Introduction of this device has demonstrated to decrease the pressure fluctuations in the system, therefore reducing significantly the risk of wear of the delta-P diaphragm fabric. This will delete the need for a periodical replacement of the delta-P diaphragm before overhaul of the HMU. The modification TU157 is therefore considered as the terminating action for this AD.

We are issuing this AD to prevent the loss of automatic control mode coupled with the deteriorated performance of the backup mode, which can lead to the inability to continue safe flight, forced autorotation landing, or an accident.

DATES: This AD becomes effective July 7, 2010.

ADDRESSES: The Docket Operations office is located at Docket Management

Facility, U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.

FOR FURTHER INFORMATION CONTACT:

Kevin Dickert, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: kevin.dickert@faa.gov; telephone (781) 238-7117; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on March 22, 2010 (75 FR 13451). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states that:

Since the issuance of AD 2007-0126 Turbomeca has released modification TU157 which consists in modifying the pressure relief valve of the HMU by introducing a damping device into the valve. Introduction of this device has demonstrated to decrease the pressure fluctuations in the system, therefore reducing significantly the risk of wear of the delta-P diaphragm fabric. This will delete the need for a periodical replacement of the delta-P diaphragm before overhaul of the HMU. The modification TU157 is therefore considered as the terminating action for this AD.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Mandatory Service Bulletin Reference Added

Since we issued the proposed AD, Turbomeca issued Mandatory Service Bulletin (MSB) No. 292 73 2818, Version C, dated January 29, 2009. We added that reference to paragraph (e)(2)(iii) of the AD.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD with the change described previously.