

whichever occurs later, and thereafter at intervals not exceeding 1,000 hours TIS:

(i) X-Ray inspect each MRB between station (STA) 30 and 289 for a crack, a wood split, a void, and delamination.

(ii) Using a 10× or higher power magnifying glass, inspect each spar plank between STA 33 and STA 78 for a wood split or a crack, and inspect each spar plank to plank glue-line for a void or delamination.

(2) If there is a crack, wood split, void, or delamination within maximum repair damage limits in an MRB, before further flight, repair the MRB. If there is a crack, wood split, void, or delamination exceeding maximum repair damage limits in an MRB, before further flight, replace the MRB with an airworthy MRB.

(3) Each inspection and repair procedure required for compliance with Paragraphs (e)(1) and (e)(2) of this AD must be accomplished by a method approved by the Manager, Boston Aircraft Certification Office (ACO). For a repair method to be approved by the Manager, Boston ACO, as required by this AD, the Manager's approval letter must specifically refer to this AD.

#### (f) Alternative Methods of Compliance (AMOC)

(1) The Manager, Boston ACO, FAA, may approve AMOCs for this AD. Send your proposal to: Nicholas Faust, Aviation Safety Engineer, Boston Aircraft Certification Office, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, Massachusetts 01803; telephone (781) 238-7763; email [nicholas.faust@faa.gov](mailto:nicholas.faust@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

#### (g) Additional Information

Kaman Aerospace Corporation Maintenance Manual 04-00-00, Continued Airworthiness, Revision 31, dated August 1, 2013, and Kaman Aerospace Corporation Maintenance Manual 05-20-06, 1,000 Hour Rotor Blade Spar Inspection, Revision 31, dated August 1, 2013, which are not incorporated by reference, contain additional information about the subject of this AD. You may review a copy of this information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth Texas 76137. For information on the availability of this material at the FAA, call (817) 222-5110.

#### (h) Subject

Joint Aircraft Service Component (JASC)  
Code: 6210: Main Rotor MRB.

Issued in Fort Worth, Texas, on September 17, 2014.

**Kim Smith,**

Directorate Manager, Rotorcraft Directorate,  
Aircraft Certification Service.

[FR Doc. 2014-23588 Filed 10-2-14; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF HEALTH AND HUMAN SERVICES

### Food and Drug Administration

#### 21 CFR Part 179

[Docket No. FDA-2014-F-1370]

#### Casa de Mesquite LLC; Filing of Food Additive Petition

**AGENCY:** Food and Drug Administration, HHS.

**ACTION:** Notice of petition.

**SUMMARY:** The Food and Drug Administration (FDA or we) is announcing that we have filed a petition, submitted by Casa de Mesquite LLC, proposing that the food additive regulations be amended to provide for the safe use of ionizing radiation to treat mesquite bean flour.

**DATES:** The food additive petition was filed on August 11, 2014.

#### FOR FURTHER INFORMATION CONTACT:

Teresa A. Croce, Center for Food Safety and Applied Nutrition (HFS-265), Food and Drug Administration, 5100 Paint Branch Pkwy., College Park, MD 20740-3835, 240-402-1281.

**SUPPLEMENTARY INFORMATION:** Under the Federal Food, Drug, and Cosmetic Act (section 409(b)(5) (21 U.S.C. 348(b)(5))), we are giving notice that we have filed a food additive petition (FAP 4M4807), submitted by Casa de Mesquite LLC, 10021 Pacheco Pass Hwy., Hollister, CA 95023. The petition proposes to amend the food additive regulations in § 179.26 (21 CFR 179.26), *Ionizing radiation for the treatment of food*, to provide for the safe use of ionizing radiation to reduce the levels of food-borne pathogens in mesquite bean flour.

We have determined under 21 CFR 25.32(j) that this action is of a type that does not individually or cumulatively have a significant effect on the human environment. Therefore, neither an environmental assessment nor an environmental impact statement is required.

Dated: September 29, 2014.

**Dennis M. Keefe,**

Director, Office of Food Additive Safety,  
Center for Food Safety and Applied Nutrition.

[FR Doc. 2014-23597 Filed 10-2-14; 8:45 am]

**BILLING CODE 4164-01-P**

## DEPARTMENT OF THE TREASURY

### 31 CFR Part 1

RIN 1505-AC43

#### Privacy Act, Implementation

**AGENCY:** Departmental Offices, Treasury.

**ACTION:** Proposed rule.

**SUMMARY:** In accordance with the requirements of the Privacy Act of 1974, as amended, 5 U.S.C. 552a, the Department of the Treasury gives notice of a proposed amendment to update its Privacy Act regulations, and to add an exemption from certain provisions of the Privacy Act for a system of records related to the Office of Intelligence and Analysis.

**DATES:** Comments must be received no later than November 3, 2014.

**ADDRESSES:** Written comments should be sent to the Director Intelligence Information Systems, Office of Intelligence and Analysis, Department of the Treasury, 1500 Pennsylvania Ave. NW., Washington, DC 20220. The Department will make such comments available for public inspection and copying in the Department's Library, Room 1020, Annex Building, 1500 Pennsylvania Ave. NW., Washington, DC 20220, on official business days between the hours of 10 a.m. and 5 p.m. Eastern Standard Time. You must make an appointment to inspect comments by telephoning (202) 622-0990 (not a toll free number). You may also submit comments through the Federal rulemaking portal at <http://www.regulations.gov> (follow the instructions for submitting comments). All comments, including attachments and other supporting materials, received are part of the public record and subject to public disclosure. You should submit only information that you wish to make available publicly.

#### FOR FURTHER INFORMATION CONTACT:

Director Intelligence Information Systems, Office of Intelligence and Analysis, Department of the Treasury, at (202) 622-1826, facsimile (202) 622-1829, or email [OIAExec@treasury.gov](mailto:OIAExec@treasury.gov).

**SUPPLEMENTARY INFORMATION:** The Department is establishing "Treasury/DO. 411—Intelligence Enterprise Files," maintained by the Office of Intelligence and Analysis.

Under 5 U.S.C. 552a(k)(1), the head of an agency may promulgate rules to exempt a system of records from certain provisions of 5 U.S.C. 552a if the system of records is subject to the provisions of 5 U.S.C. 552(b)(1), which regards matters specifically authorized under criteria established by an Executive